

**U.S. Nuclear Regulatory Commission  
Human Factors Information System (HFIS)  
IR/LER Category Analysis by Docket Report**

Total Number of Hits: 3662

National Average: 35

2x National Average: 70

National Median: 21

Average for Selected Dockets: 35

---

**Facility Name: Arkansas Nuclear 2 Docket (050- 00368)**

Details	Department	Work Type	Docket/Report
<b>Oversight / IR</b>			
130 - Inadequate supervision / command and control	M - Mechanical	M - Maintenance / Repair	050-00368/2008-002
130 - Inadequate supervision / command and control	O - Operations	O - Control Room Ops	050-00368/2008-002
131 - Management expectations or directions LTA	M - Mechanical	M - Maintenance / Repair	050-00368/2008-002
131 - Management expectations or directions LTA	O - Operations	O - Control Room Ops	050-00368/2008-002
<b>Number of Items for this Docket: 4</b>			
<b>Percent of Total for this Docket: 9</b>			

---

**Procedures & Reference Document / IR**

111 - Procedure / reference document technical content	E - Electrical	M - Maintenance / Repair	050-00368/2007-009
111 - Procedure / reference document technical content	M - Mechanical	M - Maintenance / Repair	050-00368/2007-005
111 - Procedure / reference document technical content	M - Mechanical	M - Maintenance / Repair	050-00368/2007-009
111 - Procedure / reference document technical content	M - Mechanical	M - Maintenance / Repair	050-00368/2007-009
111 - Procedure / reference document technical content	M - Mechanical	T - Testing	050-00368/2008-002
<b>Number of Items for this Docket: 5</b>			
<b>Percent of Total for this Docket: 11</b>			

---

**Problem Identification & Resolution / IR**

140 - Problem not completely or accurately identified	M - Mechanical	M - Maintenance / Repair	050-00368/2007-009
140 - Problem not completely or accurately identified	O - Operations	B - Bal of Plant Ops	050-00368/2008-002
142 - Operating experience (OE) review LTA	D - Emergency Planning	Q - Fire Protection	050-00368/2007-005
142 - Operating experience (OE) review LTA	E - Electrical	M - Maintenance / Repair	050-00368/2007-009
142 - Operating experience (OE) review LTA	S - Specialized task force	W - Assessment	050-00368/2007-009
145 - Causal development LTA	D - Emergency Planning	Q - Fire Protection	050-00368/2007-005
146 - Evaluation LTA	D - Emergency Planning	Q - Fire Protection	050-00368/2007-005
146 - Evaluation LTA	G - Engineering	G - Design	050-00368/2007-009
146 - Evaluation LTA	M - Mechanical	M - Maintenance / Repair	050-00368/2007-009
146 - Evaluation LTA	S - Specialized task force	W - Assessment	050-00368/2007-009
147 - Individual corrective action LTA	E - Electrical	M - Maintenance / Repair	050-00368/2007-009
147 - Individual corrective action LTA	E - Electrical	M - Maintenance / Repair	050-00368/2007-009
148 - Action not yet started or untimely	M - Mechanical	M - Maintenance / Repair	050-00368/2007-009
150 - Programmatic deficiency	M - Mechanical	M - Maintenance / Repair	050-00368/2007-009
<b>Number of Items for this Docket: 14</b>			
<b>Percent of Total for this Docket: 30</b>			

---

**U.S. Nuclear Regulatory Commission  
Human Factors Information System (HFIS)  
IR/LER Category Analysis by Docket Report**

Total Number of Hits: 3662

National Average: 35

2x National Average: 70

National Median: 21

Average for Selected Dockets: 35

---

**Facility Name: Arkansas Nuclear 2 Docket (050- 00368)**

Details	Department	Work Type	Docket/Report
<b>Work Planning &amp; Practices / IR</b>			
185 - Procedural adherence LTA	E - Electrical	M - Maintenance / Repair	050-00368/2007-009
185 - Procedural adherence LTA	M - Mechanical	M - Maintenance / Repair	050-00368/2008-002
185 - Procedural adherence LTA	O - Operations	O - Control Room Ops	050-00368/2007-005
186 - Failure to take action / meet requirements	D - Emergency Planning	Q - Fire Protection	050-00368/2007-005
186 - Failure to take action / meet requirements	E - Electrical	M - Maintenance / Repair	050-00368/2007-009
186 - Failure to take action / meet requirements	G - Engineering	G - Design	050-00368/2007-005
186 - Failure to take action / meet requirements	M - Mechanical	T - Testing	050-00368/2008-002
187 - Action implementation LTA	G - Engineering	G - Design	050-00368/2007-005
187 - Action implementation LTA	G - Engineering	G - Design	050-00368/2007-005
187 - Action implementation LTA	G - Engineering	G - Design	050-00368/2007-009
187 - Action implementation LTA	G - Engineering	G - Design	050-00368/2007-009
187 - Action implementation LTA	G - Engineering	G - Design	050-00368/2008-002
189 - Recognition of adverse condition / questioning attitude LTA	E - Electrical	M - Maintenance / Repair	050-00368/2007-009
189 - Recognition of adverse condition / questioning attitude LTA	M - Mechanical	M - Maintenance / Repair	050-00368/2008-002
189 - Recognition of adverse condition / questioning attitude LTA	O - Operations	B - Bal of Plant Ops	050-00368/2008-002
190 - Failure to stop work / non-conservative decision making	M - Mechanical	M - Maintenance / Repair	050-00368/2007-009
190 - Failure to stop work / non-conservative decision making	O - Operations	O - Control Room Ops	050-00368/2007-005
194 - Housekeeping LTA	E - Electrical	M - Maintenance / Repair	050-00368/2007-009
194 - Housekeeping LTA	M - Mechanical	M - Maintenance / Repair	050-00368/2007-009
<b>Number of Items for this Docket:</b> 19			
<b>Percent of Total for this Docket:</b> 40			
<b>Communication / LER</b>			
161 - Communication LTA	G - Engineering	A - Administrative	050-00368/2008-002-00
161 - Communication LTA	O - Operations	O - Control Room Ops	050-00368/2008-002-00
<b>Number of Items for this Docket:</b> 2			
<b>Percent of Total for this Docket:</b> 4			
<b>Work Planning &amp; Practices / LER</b>			
189 - Recognition of adverse condition / questioning attitude LTA	O - Operations	M - Maintenance / Repair	050-00368/2008-001-00
189 - Recognition of adverse condition / questioning attitude LTA	O - Operations	O - Control Room Ops	050-00368/2008-002-00

**U.S. Nuclear Regulatory Commission  
Human Factors Information System (HFIS)  
IR/LER Category Analysis by Docket Report**

Total Number of Hits: 3662  
National Average: 35  
2x National Average: 70  
National Median: 21  
Average for Selected Dockets: 35

---

**Facility Name: Arkansas Nuclear 2 Docket (050- 00368)**

Details	Department	Work Type	Docket/Report
<b>Work Planning &amp; Practices / LER</b>			
189 - Recognition of adverse condition / questioning attitude LTA	Z - Other / Unknown	M - Maintenance / Repair	050-00368/2008-001-00
<b>Number of Items for this Docket:</b> 3			
<b>Percent of Total for this Docket:</b> 6			

---

**Total Items for this Docket:** 47

---