

U.S. Nuclear Regulatory Commission
Human Factors Information System (HFIS)
IR/LER Category Analysis by Docket Report

Total Number of Hits: 3662
National Average: 35
2x National Average: 70
National Median: 21
Average for Selected Dockets: 35

Facility Name: Peach Bottom 3 Docket (050- 00278)

Details	Department	Work Type	Docket/Report
Procedures & Reference Document / IR			
111 - Procedure / reference document technical content	D - Emergency Planning	Q - Fire Protection	050-00278/2008-002
111 - Procedure / reference document technical content	H - Health Physics	H - Health Physics	050-00278/2008-502
111 - Procedure / reference document technical content	M - Mechanical	M - Maintenance / Repair	050-00278/2007-005
113 - Procedure / reference document development and maintenance L	D - Emergency Planning	Q - Fire Protection	050-00278/2008-002
Number of Items for this Docket: 4			
Percent of Total for this Docket: 19			

Problem Identification & Resolution / IR			
140 - Problem not completely or accurately identified	G - Engineering	G - Design	050-00278/2007-005
142 - Operating experience (OE) review LTA	M - Mechanical	M - Maintenance / Repair	050-00278/2007-005
146 - Evaluation LTA	G - Engineering	G - Design	050-00278/2007-005
147 - Individual corrective action LTA	E - Electrical	S - Surveillance	050-00278/2008-007
147 - Individual corrective action LTA	G - Engineering	G - Design	050-00278/2007-005
148 - Action not yet started or untimely	E - Electrical	S - Surveillance	050-00278/2008-007
Number of Items for this Docket: 6			
Percent of Total for this Docket: 29			

Work Planning & Practices / IR			
185 - Procedural adherence LTA	D - Emergency Planning	Q - Fire Protection	050-00278/2008-002
185 - Procedural adherence LTA	M - Mechanical	M - Maintenance / Repair	050-00278/2007-005
186 - Failure to take action / meet requirements	E - Electrical	S - Surveillance	050-00278/2008-007
186 - Failure to take action / meet requirements	H - Health Physics	H - Health Physics	050-00278/2008-502
186 - Failure to take action / meet requirements	M - Mechanical	M - Maintenance / Repair	050-00278/2007-005
187 - Action implementation LTA	E - Electrical	G - Design	050-00278/2008-007
187 - Action implementation LTA	G - Engineering	G - Design	050-00278/2008-007
187 - Action implementation LTA	H - Health Physics	H - Health Physics	050-00278/2008-502
189 - Recognition of adverse condition / questioning attitude LTA	D - Emergency Planning	Q - Fire Protection	050-00278/2008-002
189 - Recognition of adverse condition / questioning attitude LTA	M - Mechanical	M - Maintenance / Repair	050-00278/2007-005
190 - Failure to stop work / non-conservative decision making	D - Emergency Planning	Q - Fire Protection	050-00278/2008-002
Number of Items for this Docket: 11			
Percent of Total for this Docket: 52			

Total Items for this Docket: 21
