

NRC NEWS

U.S. NUCLEAR REGULATORY COMMISSION

Office of Public Affairs, Region II 245 Peachtree Center Ave., NE, Suite 1200 Atlanta, GA 30303-1257 Site: www.nrc.gov

Blog: http://public-blog.nrc-gateway.gov

E-mail: OPA2.Resource@nrc.gov

No: II-11-045 August 16, 2011

CONTACT: Roger Hannah (404) 997-4417 Joey Ledford (404) 997-4416

NRC BEGINS SPECIAL INSPECTION AT TURKEY POINT NUCLEAR POWER PLANT

The Nuclear Regulatory Commission staff began a special inspection at FPL's Turkey Point nuclear power plant today to assess the circumstances surrounding the brief loss of the intake cooling water function at one of the plant's two nuclear units.

On Aug. 11, Turkey Point Unit 3 lost the function of the intake cooling water system for about 20 minutes when an open valve closed and then failed in that closed position. The intake cooling water system provides cooling to important plant equipment. The NRC staff determined that because the failure resulted in the loss of a safety system and because there is also a potential generic concern, a special inspection was appropriate.

The NRC special inspection team is composed of two inspectors from the NRC's region office in Atlanta as well as an acting resident inspector already at the Turkey Point plant. The team will develop a timeline and review FPL's response to the event, assess the plant's ability to meet its design functions, review maintenance and testing performed for the valve, and assess the company's problem investigation activities.

The on-site portion of the inspection will be completed this week, and a report documenting the results should be issued within 45 days of the completion of the inspection.

###

News releases are available through a free <u>listserv</u> subscription or by clicking on the <u>EMAIL UPDATES</u> link on the NRC homepage (<u>www.nrc.gov</u>). E-mail notifications are sent to subscribers when news releases are posted to NRC's website.