

"Hinton's"

***TYPE A ANNUAL INSPECTION SUMMARY
LESS FAMILY HOUSING
MARINE CORPS BASE
CAMP LEJEUNE, NORTH CAROLINA
FISCAL YEAR 1968***

ANNUAL INSPECTION SUMMARY - TRANSMITTAL SHEET

2720 (REV. 1-66)
04-804-801

Instructions for completing form are contained in NAVDOCKS P-322

FROM MCO, CLIC All facilities inspected are in satisfactory condition except those listed on Form NAVDOCKS 2730 having essential deficiencies which cannot be accomplished during the current fiscal year due to lack of resources. <i>John F. Mentzer</i> 26 Dec 1967 BY DIRECTION	2. B.F.D. CODE	3. ACTIVITY CODE	4. ACTIVITY Marine Corps Base Camp Lejeune, North Carolina 28542	1. <input checked="" type="checkbox"/> LESS HOUSING A 2. <input type="checkbox"/> HOUSING
	5. TO Commandant of the Marine Corps (Code COM)		6. FOR PERIOD ENDING	7. COPIES TO
6. VIA		9. INSPECTED BY <input type="checkbox"/> ACTIVITY <input checked="" type="checkbox"/> CONTINUOUS <input type="checkbox"/> BFD <input type="checkbox"/> ONE-TIME COMPREHENSIVE <input type="checkbox"/> OTHER		
10. FACILITIES NOT INSPECTED None	11. REASON		12. DATE OF PREVIOUS INSPECTION	13. APPROXIMATE DATE OF NEXT INSPECTION

ENDORSEMENT

FOR: **Base Maintenance Officer**

DATE **26 Dec 1967**

The undersigned confirms that the items of deficiencies reported in attached form NAVDOCKS 2730 are essential in accordance with the criteria contained in MCO P11000.4A, and that the deficiencies cannot be accomplished during the current fiscal year.

Attention is invited to enclosures (1) and (2). Enclosure (1) depicts the condition of exterior paint on barracks and other buildings. Enclosure (2) shows, by photographs, a sampling of the condition of the Bituminous Surfaced Roads throughout Marine Corps Base.

JAMES M. HAYES
BY DIRECTION





UNFUNDED FACILITIES DEFICIENCIES

Instructions for completing form are contained in NAVDOCKS P-322

1. PART NO. 1	3. ACTIVITY CODE 67001	5. OPERATIONAL STATUS OF ACTIVITY <input checked="" type="checkbox"/> ACTIVE <input type="checkbox"/> PARTIAL MAINTENANCE <input type="checkbox"/> INACTIVE <input type="checkbox"/> MAINTENANCE	6. F. E. O. CODE	FOR BUREAU USE ONLY A B C	8. ACTIVITY Marine Corps Base Camp Lejeune, North Carolina Leas Family Housing
2. SHEET 2 of 26E	4. ACCT'G. NO. 67001	<input type="checkbox"/> DEVELOPMENT <input type="checkbox"/> CONTRACTOR OPERATED FOR RESEARCH & DEVELOPMENT <input type="checkbox"/> DISESTABLISHED	7. MANAGEMENT BUREAU CODE		9. FOR PERIOD ENDING 30 June 1968 FISCAL YEAR 1968

10. THIS PART CONSISTS OF	DEFICIENCY CODE	ITEMS INCIDENTAL TO MAINTENANCE AND REPAIR	DEFICIENCY CODE
ITEMS OF MAINTENANCE AND REPAIR	XX		XX
	XXXXXXXXXXXXXXXXXXXX		XX
	XXXXXXXXXXXXXXXXXXXX		XX

DEFICIENCY CODES IN ACCORDANCE WITH MCO P11000.4A, Change 4

11 CATEGORY CODE	12 PROJECT NUMBER	13 DEFICIENCY	14 DEFICIENCY CODE	15 ESTIMATED \$ COST		16 PROBABLE FUNDING SOURCE CODE	17 DATE OF FEO VALIDATION OR FEO ON-SITE REVIEW
				WORK INCURRED Line Item #	TOTAL REMAINING		
229		1 PRODUCTION -- MAINTENANCE REPAIR, AND OPERATION OF INSTALLATIONS Struct. Repair, Exterior Painting, Mech., Elec., and Replace Part of Roof - 909	1	6	\$21,100 15,800 repair Painting 6000 gal.	Project 15	27 Feb 67 Revalidated 14 March 1968 gAU.
442		2 STORAGE -- COVERED - INSTALLATION AND ORGANIZATIONAL Interior Painting, Exterior Painting, Elec. Struct. repair & Replace Roof (1 Roof) (This includes 1 burned building) - 1108, 1301, 1606 and 1709 Roof out. Barred	1	7	44,000 74,300?	Project 15	14 March 1968 gAU (Val. Bldg 1) 27 Feb 67 \$10,000 Funding action pending on Bldg 1. Work on Bldg 2 is construction gAU.
610		2 ADMINISTRATIVE BUILDINGS Repair Elec. Systems 1 & 2 (3)	1	8	26,000	Project 15	
610		1 ADMINISTRATIVE BUILDING Renovation of Heads & Showers - 59	1	9	85,000 88,800	Project 15	Validated 14 March 1968 gAU. Building to revert to original use, barracks, upon completion of Force Troop Complex

John L. Downer
Civil Eng.



UNFUNDED FACILITIES DEFICIENCIES

Instructions for completing form are contained in NAVDOCKS P-322

1. PART NO. 1	3. ACTIVITY CODE 67001	5. OPERATIONAL STATUS OF ACTIVITY <input checked="" type="checkbox"/> ACTIVE <input type="checkbox"/> PARTIAL MAINTENANCE <input type="checkbox"/> DEVELOPMENT <input type="checkbox"/> INACTIVE <input type="checkbox"/> CONTRACTOR OPERATED FOR RESEARCH & DEVELOPMENT <input type="checkbox"/> MAINTENANCE <input type="checkbox"/> DISESTABLISHED	6. F. E. O. CODE	FOR BUREAU USE ONLY A B C			8. ACTIVITY Marine Corps Base Camp Lejeune, North Carolina Less Family Housing
2. SHEET 3 of 26	4. ACCT'G. NO. 67001		7. MANAGEMENT BUREAU CODE			9. FOR PERIOD ENDING 30 June 1968	FISCAL YEAR 1968

10. THIS PART CONSISTS OF	DEFICIENCY CODE	DEFICIENCY CODE
ITEMS OF MAINTENANCE AND REPAIR	XX	XX
ITEMS INCIDENTAL TO MAINTENANCE AND REPAIR	XX	XX

DEFICIENCY CODES IN ACCORDANCE WITH MCO P11000.4A, Change 4

11 CATEGORY CODE	12 PROJECT NUMBER	13 DEFICIENCY	14 DEFICIENCY CODE	15 ESTIMATED \$ COST		16 PROBABLE FUNDING SOURCE CODE	17 DATE OF FEO VALIDATION OR FEO ON-SITE REVIEW
				15 TOTAL REMAINING	15 TOTAL REMAINING		
722	15th 16th	20 TROOP HOUSING - EM BARRACKS W/O MESS Renovation of Heads & Showers - 8, 10, 51, 53, 55, 57, 63, 105, 309, 313, 412, 502, 503, 510, 514, 517, 1109, 1110, 1313 & 1314	1	10	\$854,000 898,260	Project 15	Val 25 March 1966 19 March 1968 gbl
722		18 TROOP HOUSING - EM BARRACKS W/O MESS Interior Painting, Exterior Painting, Mech., Elec., & Struct repairs - 308, 312, 404, 406, 407, 410, 415, 417, BB 13 & BA-105 (This includes 1 burned building) (See enclosure 1) Funding Action pending BA105 68,000	1	11	180,619 67,000	Project 15	All bldgs withdrawn except BA-105 for which funding action is pending gbl
723	(5)	9 TROOP HOUSING - DETACHED FACILITIES Interior Painting, Exterior Painting, Elec., Mech., & Struct repairs - 9, 54, 107, 206, 307, 411, BB-7, RR-3 & TC-920 (Enclosure 1)	1	12	258,850 Painting incidental to repair	Project 15	14 March 1968 gbl
723		8 TROOP HOUSING - DETACHED FACILITIES Tile Dining Room Decks Minor Construction	1	13	302,000	Project 15	Construction Project gbl

John H. Brown
Civil Eng



TYPE A ANNUAL INSPECTION SUMMARY
NAVDOCKS 2730 (6-64)

REPORT SUBDOCES 11010-1

UNFUNDED FACILITIES DEFICIENCIES

Instructions for completing form are contained in NAVDOCKS P-322

1. PART NO. 1	3. ACTIVITY CODE 67001	5. OPERATIONAL STATUS OF ACTIVITY <input checked="" type="checkbox"/> ACTIVE <input type="checkbox"/> PARTIAL MAINTENANCE <input type="checkbox"/> INACTIVE <input type="checkbox"/> MAINTENANCE	6. F. E. O. CODE	FOR BUREAU USE ONLY A B C			8. ACTIVITY Marine Corps Base Camp Lejeune, North Carolina Less Family Housing
2. SHEET 4 OF 26E	4. ACCT G. NO. 67001	<input type="checkbox"/> CONTRACTOR OPERATED FOR RESEARCH & DEVELOPMENT <input type="checkbox"/> DISESTABLISHED	7. MANAGEMENT BUREAU CODE				9. FOR PERIOD ENDING 30 June 1968 FISCAL YEAR 1968

10. THIS PART CONSISTS OF	DEFICIENCY CODE	ITEMS INCIDENTAL TO MAINTENANCE AND REPAIR	DEFICIENCY CODE
ITEMS OF MAINTENANCE AND REPAIR	XX		XX
	XXXXXXXXXXXXXXXXXXXX		XXXXXXXXXXXXXXXXXXXX
	XXXXXXXXXXXXXXXXXXXX		XXXXXXXXXXXXXXXXXXXX

DEFICIENCY CODES IN ACCORDANCE WITH MCO P11000.4A, Change 4

11 CATEGORY CODE	12 PROJECT NUMBER	13 DEFICIENCY	14 DEFICIENCY CODE	15 ESTIMATED \$ COST		16 PROBABLE FUNDING SOURCE CODE	17 DATE OF FEO VALIDATION OR FEO ON-SITE REVIEW
				XXXX Line Item #	TOTAL REMAINING		
730		1 COMMUNITY FACILITIES - PERSONNEL SUPPORT AND SERVICE Interior Painting, Exterior Painting, Struct. & Renovate Machine Room & Water Softeners - 1500	1	14	\$25,700 13,600	Project 15	14 March 1968 gbl
740		2 COMMUNITY FACILITIES - MORALE, WELFARE AND RECREATIONAL INTERIOR Interior Painting, Exterior Painting, Elec., Mech., - TC-200 & 19 out out		15	21,550 less than 10pc per facility.	Project 15	14 March 1968 gbl
750		1 COMMUNITY MORALE, WELFARE AND RECREATIONAL, EXTERIOR Repair Book S-715	1	16	13,000	Project 15 NAF	Not Validated gbl
812	7	ELECTRICITY - DISTRIBUTION AND TRANSMISSION LINES Replace Street Lights (Hadnot Point Area) Replace Underground Conduit & Service Wire 400 Housing Units Replace Poles, Crossarms, Insulators, Hardware & Switches	1	17	670,000	Project 15	14 March 1968 gbl

John H. Thomas
Civ Eng



UNFUNDED FACILITIES DEFICIENCIES

Instructions for completing form are contained in NAVDOCKS P-322

1. PART NO.	3. ACTIVITY CODE	5. OPERATIONAL STATUS OF ACTIVITY	6. F. E. O.	FOR BUREAU USE ONLY	8. ACTIVITY
1	67001	<input checked="" type="checkbox"/> ACTIVE <input type="checkbox"/> PARTIAL MAINTENANCE <input type="checkbox"/> DEVELOPMENT <input type="checkbox"/> INACTIVE <input type="checkbox"/> CONTRACTOR OPERATED FOR RESEARCH & DEVELOPMENT <input type="checkbox"/> MAINTENANCE <input type="checkbox"/> DISESTABLISHED		A B C	Marine Corps Base Camp Lejeune, North Carolina Less Family Housing
2. SHEET	4. ACCT'G. NO.		7. MANAGEMENT BUREAU		9. FOR PERIOD ENDING
5 of 26E	67001				30 June 1968
					FISCAL YEAR 1968

10. THIS PART CONSISTS OF:		DEFICIENCY CODE	ITEMS INCIDENTAL TO MAINTENANCE AND REPAIR	DEFICIENCY CODE
ITEMS OF MAINTENANCE AND REPAIR		XK	XXXXXXXXXXXXXXXXXXXX	XK
XXXXXXXXXXXXXXXXXXXX		XXXXXXXXXXXXXXXXXXXX	XXXXXXXXXXXXXXXXXXXX	XX
XXXXXXXXXXXXXXXXXXXX		XXXXXXXXXXXXXXXXXXXX	XXXXXXXXXXXXXXXXXXXX	

DEFICIENCY CODES IN ACCORDANCE WITH MCO P11000.4A, Change 4.

11. CATEGORY CODE	12. PROJECT NUMBER	13. DEFICIENCY	14. DEFICIENCY CODE	15. ESTIMATED \$ COST		16. PROBABLE FUNDING SOURCE CODE	17. DATE OF FED VALIDATION OR FED ON-SITE REVIEW
				NKDE XXXXXXXXXXXX Line Item #	TOTAL REMAINING		
821		HEAT, STEAM - SOURCE <i>Replace Boiler</i> Interior Painting, Exterior Painting Structure, Replace 1 Boiler (PT-3) Part of 1 Roof - 1700, PT-3 & TC 9410 <i>out</i>	1	18	\$66,150 23,400	Project 15	14 March 1968 JAR
841	2	6 WATER - SUPPLY, TREATMENT AND STORAGE Replace 6 Wells - 4, 30, 24, 28, 31 & 29	1	19	120,000	Project 15	14 March 1968 Although all 6 wells require repair. This work is limited to 4 wells in accordance with CMC ltr COM/MMA 27 Dec 67 until changed by higher authority. Selection of wells to be repaired is the prerogative of the Maint. Officer. JAR
841		1 WATER - SUPPLY, TREATMENT AND STORAGE Interior Painting, Exterior Painting, Mech., & Struct. - 20 <i>out</i>	1	20	13,075	Project 15	14 March 1968 Validated March 66 \$100,000 in process of funding. Revalidated 14 March 1968 JAR
851	8027 (6)	ROADS Resurface and repair roads throughout Base (See enclosure (2)).	1	21	315,700	Project 15	14 March 1968 JAR
851		ROADS Repair & Paint Onslow Beach Bridge - SBA-129 <i>NO PLANS?</i>	1	22	? 27,500 Repair portion exceeds \$10,000. Paint incidental to repair.	Project 15	14 March 1968 JAR

John R. Alexander
Civil Eng.



TYPE A ANNUAL INSPECTION SUMMARY
NAVDOKCS 2730 (6-64)

UNFUNDED FACILITIES DEFICIENCIES

Instructions for completing form are contained in NAVDOCKS P-322

1. PART NO. 1	3. ACTIVITY CODE 67001	5. OPERATIONAL STATUS OF ACTIVITY		6. F. E. O. CODE	FOR BUREAU USE ONLY			8. ACTIVITY Marine Corps Base Camp Lejeune, North Carolina Less Family Housing
		<input checked="" type="checkbox"/> ACTIVE	<input type="checkbox"/> PARTIAL MAINTENANCE		A	B	C	
2. SHEET 6 OF 268	4. ACCT'G. NO. 67001	<input type="checkbox"/> INACTIVE	<input type="checkbox"/> DEVELOPMENT	7. MANAGEMENT BUREAU CODE				9. FOR PERIOD ENDING 30 June 1968
		<input type="checkbox"/> MAINTENANCE	<input type="checkbox"/> CONTRACTOR OPERATED FOR RESEARCH & DEVELOPMENT					FISCAL YEAR 1968
		<input type="checkbox"/> DIS-ESTABLISHED	<input type="checkbox"/> CONTRACTOR OPERATED FOR RESEARCH & DEVELOPMENT					

10. THIS PART CONSISTS OF:	DEFICIENCY CODE	ITEMS INCIDENTAL TO MAINTENANCE AND REPAIR	DEFICIENCY CODE
ITEMS OF MAINTENANCE AND REPAIR	XX		XX
			XX

DEFICIENCY CODES IN ACCORDANCE WITH MCO P11000.4A, Change 4

11 CATEGORY CODE	12 PROJECT NUMBER	13 DEFICIENCY	14 DEFIC- IENCY CODE	15 ESTIMATED \$ COST		16 PROBABLE FUNDING SOURCE CODE	17 DATE OF FEO VALIDATION OR FEO ON-SITE REVIEW
				XXXX Line #	TOTAL REMAINING		
852	10 80210	SIDEWALK AND OTHER PAVEMENT Resurface and repair Parking Areas (Hadnot Point)	1	23	\$22,300	Project 15	Val 1 March 1966 14 March 1968 GAC
	9 8029	Replace Broken Sidewalks (Throughout Base)	1	24	45,000		
Subtotal Deficiency Code 1					\$3,491,424		
135		COMMUNICATION LINES - COMMUNICATION AND CONTROL Replace Main Battery at Montford Point Telephone Exchange, Building M-167 - Replace 3,700 L.F. Direct Burial Telephone Cable from Building 19 to 24 - Trunking Cable #4 & #1 - Replace manual Telephone System for Data Processing Building 1101 - Replace manual Switchboard for Credit Union Building 58 and Replace manual switchboard for Range Facilities Building 11	2	25	2817,650 18,000		

John H. Brown
CIV Eng



J

X

X





UNFUNDED FACILITIES DEFICIENCIES

Instructions for completing form are contained in NAVDOCKS P-322

1. PART NO. 1	3. ACTIVITY CODE 67001	5. OPERATIONAL STATUS OF ACTIVITY <input checked="" type="checkbox"/> ACTIVE <input type="checkbox"/> PARTIAL MAINTENANCE <input type="checkbox"/> INACTIVE <input type="checkbox"/> MAINTENANCE	6. F. E. O. CODE	FOR BUREAU USE ONLY A B C	8. ACTIVITY Marine Corps Base Camp Lejeune, North Carolina Less Family Housing
2. SHEET 8 of 26E	4. ACCT'G. NO. 67001	<input type="checkbox"/> DEVELOPMENT <input type="checkbox"/> CONTRACTOR OPERATED FOR RESEARCH & DEVELOPMENT <input type="checkbox"/> DISESTABLISHED	7. MANAGEMENT BUREAU CODE		9. FOR PERIOD ENDING 30 June 1968 FISCAL YEAR 1968

10. THIS PART CONSISTS OF	DEFICIENCY CODE	ITEMS INCIDENTAL TO MAINTENANCE AND REPAIR	DEFICIENCY CODE
ITEMS OF MAINTENANCE AND REPAIR	XX		XX
	XXXXXX		XX

DEFICIENCY CODES IN ACCORDANCE WITH MCO P11000.4A, Change 4.

11 CATEGORY CODE	12 PROJECT NUMBER	13 DEFICIENCY	14 DEFICIENCY CODE	15 ESTIMATED \$ COST		16 PROBABLE FUNDING SOURCE CODE	17 DATE OF FED VALIDATION OR FED ON-SITE REVIEW
				Line #	Item #		
179 <i>NO3</i>		79 TRAINING FACILITIES OTHER Interior Painting, Exterior Painting, Struct, & Replace Roofs (6 Roofs) + S-850, S-755, S-760, S-761, S-771, S-772, S-773, S-774, SBB-181, STC-1200, STC-1201, STC-1202, STC-1203, STC-1204, STC-1205, STC-1206, S-151, S-152, S-153, S-246, S-349, S-453, S-454, SM-261, SM-427, SM-524, S-156, S-157, S-247, S-249, S-350, S-351, S-556, S-557, S-873, S-876, S-877, SF-18A, S-851, SK-5A, SK-6A, SK-7A, SK-11A, SK-25A, SM-6A, SM-262, ST-1, ST-2, ST-3, ST-5, ST-6, ST-10, ST-11, ST-12, ST-13, ST-14, ST-15, ST-18, SBB-146, SBB-161, SBB-178, SES-136, SFC-700, SOC-1C, SOC-6C, SOC-15C, SOC-26C, SRR-64, SSH-10, STC-1219, SVL-112, SVL-113, SVL-115, SVL-130, SVL-131, SVL-142, SVL-143, SVL-165 & K-325	2	27	\$34,685		

March 1968

John H. Adams









UNFUNDED FACILITIES DEFICIENCIES

Instructions for completing form are contained in NAVDOCS P-322

1. PART NO. 1	3. ACTIVITY CODE 67001	5. OPERATIONAL STATUS OF ACTIVITY <input checked="" type="checkbox"/> ACTIVE <input type="checkbox"/> PARTIAL MAINTENANCE <input type="checkbox"/> DEVELOPMENT <input type="checkbox"/> INACTIVE <input type="checkbox"/> CONTRACTOR OPERATED FOR RESEARCH & DEVELOPMENT <input type="checkbox"/> MAINTENANCE <input type="checkbox"/> DISESTABLISHED	6. F. E. O. CODE A B C	8. ACTIVITY Marine Corps Base Camp Lejeune, North Carolina Leas Family Housing
2. SHEET 12 of 26E	4. ACCT'G. NO. 67001	7. MANAGEMENT BUREAU CODE 	9. FOR PERIOD ENDING 30 June 1968	FISCAL YEAR 1968

10. THIS PART CONSISTS OF:

ITEMS OF MAINTENANCE AND REPAIR

DEFICIENCY CODE

ITEMS INCIDENTAL TO MAINTENANCE AND REPAIR

DEFICIENCY CODE

~~XXXXXXXXXXXXXXXXXXXXXXXXXXXX~~
~~XXXXXXXXXXXXXXXXXXXX~~

XX

~~XXXXXXXXXXXXXXXXXXXXXXXXXXXX~~

XX

~~XXXXXXXXXXXXXXXXXXXXXXXXXXXX~~
~~XXXXXXXXXXXXXXXXXXXX~~

~~XXXXXXXXXXXXXXXXXXXX~~
~~XXXXXXXXXXXXXXXXXXXX~~

~~XXXXXXXXXXXXXXXXXXXXXXXXXXXX~~

XX

DEFICIENCY CODES IN ACCORDANCE WITH MCO P11000.4A, Change 4.

11 CATEGORY CODE	12 PROJECT NUMBER	13 DEFICIENCY	14 DEFICIENCY CODE	15 ESTIMATED \$ COST		16 PROBABLE FUNDING SOURCE CODE	17 DATE OF FEO VACIDATION OR FEO ON-SITE REVIEW
				DEBK XXXXXXXXXX Line Item #	TOTAL REMAINING		
610 N103		TC-342, TC-460, TC-462, TC-470, TC-471, TC-473, TC-474, TC-560, TC-562, TC-569, TC-572, TC-608, TC-611, TC-760, TC-761, TC-762, TC-774, TC-775, TC-861, TC-863, TC-1021, TC-1023, TC-1025, TC-1030, TC-1031, TC-1032, TC-1033, TC-1035, TP-449, TP-452, TT-49, TT-58, VL-164, VL-166, SBB-140, SBB-170, SES-300, STT-50, & STT-51, 1103, 1606, 100 ADMINISTRATIVE BUILDINGS Interior Painting, Exterior Painting, Elec., Mech., Struct., & Replace Roofs (11 Roofs) - 1, 2, 3B, 13, 33, 37, 114, 121, 123, 127, 214, 216, 219, 223, 303, 304, 306, 311, 315, 317, 320, 333, 336, 337, 339, 340, 342, 400, 416, 419, 423, 428, 438, 439, 501, 516, 522, 526, 530, 531, 535, 536, 746, 756, 800, 827, 857, 900, 926, 927, 928, 1115, 1403, 1405, 1407, 1811, 1812, M-105, M-200, M-201, M-416, M-521, M-621, BB-5, BB-15, BB-28, BB-37,	2	32	\$171,598 177,798	1391	

19 March 1968
J.H.D.
John R. Deanna
Civ Eng.



UNFUNDED FACILITIES DEFICIENCIES

Instructions for completing form are contained in NAVDOCS P-322

1. PART NO. 1	3. ACTIVITY CODE 67001	6. OPERATIONAL STATUS OF ACTIVITY		8. F. E. O. CODE	FOR BUREAU USE ONLY			9. ACTIVITY Marine Corps Base Camp Lejeune, North Carolina Less Family Housing
		<input checked="" type="checkbox"/> ACTIVE	<input type="checkbox"/> PARTIAL MAINTENANCE			A	B	
2. SHEET 13 of 26	4. ACCT'G. NO. 67001	<input type="checkbox"/> INACTIVE	<input type="checkbox"/> DEVELOPMENT	7. MANAGEMENT BUREAU CODE				10. FOR PERIOD ENDING 30 June 1968
		<input type="checkbox"/> MAINTENANCE	<input type="checkbox"/> CONTRACTOR OPERATED FOR RESEARCH & DEVELOPMENT					FISCAL YEAR 1968
		<input type="checkbox"/> DISESTABLISHED						

10. THIS PART CONSISTS OF:	DEFICIENCY CODE	ITEMS INCIDENTAL TO MAINTENANCE AND REPAIR	DEFICIENCY CODE
ITEMS OF MAINTENANCE AND REPAIR	XX		XX
	XX		XX

DEFICIENCY CODES IN ACCORDANCE WITH MCO P11000.4A, Change 4

11 CATEGORY CODE	12 PROJECT NUMBER	13 DEFICIENCY	14 DEFIC- IENCY CODE	15 ESTIMATED \$ COST		16 PROBABLE FUNDING SOURCE CODE	17 DATE OF FEO VALIDATION OR FEO ON-SITE REVIEW
				XX X Line Item #	TOTAL REMAINING		
722	174	BB-38, BB-86, BB-101, BB-102, BB-103, ES-131, GP-5, RR-11, RR-17, RR-20, RR-22, RR-24, RR-249, SH-7, TC-1038, TC-1056, TC-1063, TC-1120, TT-43, VL-100, VL-105, 117, 203, 922, 1005, 1020, 1021, 1100, M-144, M-418, M-620, & TT-42 174 665 TROOP HOUSING - EM BARRACKS W/O MESS Interior Painting, Exterior Painting, Elec., Mech., Struct., Termite Treatment & Replace Roofs (49 Roofs) - 6, 8, 10, 12, 51, 53, 55, 57, 58, 67, 101, 102, 104, 105, 108, 109, 111, 112, 118, 120, 124, 128, 202, 204, 205, 208, 209, 212, 213, 217, 220, 224, 227, 228, 301, 305, 309, 313, 316, 318, 321, 323, 326, 327, 409, 412, 420, 422, 426, 427, 502, 503, 506, 507, 510, 511, 514, 515, 517, 519, 523, 527, 1109, 1110, H-30, 1313, 1314, M-128, M-211, M-212, H-32, M-215, M-216, M-217, M-218, M-219, M-220, M-221, M-222, M-223, M-224,	2	33	\$772,194 785,594 842,213	1391	14 March 1968 9 & 21 Buildings encircled have been combined with item 10 page 3 (cat Code) 14 March 1968 JLL

John E. Brown
C. W. Eng.



UNFUNDED FACILITIES DEFICIENCIES

Instructions for completing form are contained in NAVDOCKS P-322

1. PART NO. I	3. ACTIVITY CODE 67001	5. OPERATIONAL STATUS OF ACTIVITY		6. F. E. O.			FOR BUREAU USE ONLY	8. ACTIVITY Marine Corps Base Camp Lejeune, North Carolina Leas Family Housing
		<input checked="" type="checkbox"/> ACTIVE	<input type="checkbox"/> PARTIAL MAINTENANCE	<input type="checkbox"/> DEVELOPMENT	<input type="checkbox"/> INACTIVE	<input type="checkbox"/> CONTRACTOR OPERATED FOR RESEARCH & DEVELOPMENT	<input type="checkbox"/> MAINTENANCE	
2. SHEET 14 OF 26E	4. ACCT'G. NO. 67001			7. MANAGEMENT BUREAU			9. FOR PERIOD ENDING	
							30 June 1968	
							FISCAL YEAR 1968	

10. THIS PART CONSISTS OF:

ITEMS OF MAINTENANCE AND REPAIR	DEFICIENCY CODE	ITEMS INCIDENTAL TO MAINTENANCE AND REPAIR	DEFICIENCY CODE
XXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX	XX	XXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX	XX
XXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX	XXXXXXXXXXXXXXXXXXXX 3 (Less than \$2,000)	XXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX	XX

DEFICIENCY CODES IN ACCORDANCE WITH MCO P11000.4A, Change 4.

11 CATEGORY CODE	12 PROJECT NUMBER	13 DEFICIENCY	14 DEFICIENCY CODE	15 ESTIMATED \$ COST		16 PROBABLE FUNDING SOURCE CODE	17 DATE OF FEO VALIDATION OR FEO ON-SITE REVIEW
				XXXXX LINE #	TOTAL REMAINING		
		M-225, M-226, M-227, M-228, M-229, M-234, M-235, M-305, M-309, M-311, M-313, M-316, M-318, M-503, M-504, M-507, M-509, M-511, M-518, M-604, M-607, M-609, M-611, M-614, M-622, BA-102, BA-104, BB-11, BB-12, BB-14, RR-1, RR-2, RR-4, RR-5, RR-201, RR-202, RR-203, RR-204, RR-206, RR-207, RR-208, RR-209, RR-210, RR-218, RR-219, RR-220, RR-221, RR-223, RR-224, TC-1003, TC-1004, TC-1005, TC-1006, TC-1007, TC-1008, TC-1009, TC-1017, TC-1018, TC-1019, TC-1026, TC-1027, TC-1028, TC-1029, TC-1036, TC-1037, TC-1046, TC-1047, TC-1048, TC-1049, TC-1055, TC-1057, TC-1058, TC-1060, TC-1061, TC-1062, TC-1064, TC-1065, TC-1110, TC-1119, TC-1131, TC-1132, TC-1142, 60 & 43. 308, 312, 404, 406, 407, 412, 415, 417 & 1113 (See enclosure (1)).					

14 March 1968
John H. Down
Civ Eng






11




















|









UNFUNDED FACILITIES DEFICIENCIES

Instructions for completing form are contained in NAVDOCS P-322

1. PART NO. 1	3. ACTIVITY CODE 67001	5. OPERATIONAL STATUS OF ACTIVITY <input checked="" type="checkbox"/> ACTIVE <input type="checkbox"/> PARTIAL MAINTENANCE <input type="checkbox"/> INACTIVE <input type="checkbox"/> DEVELOPMENT <input type="checkbox"/> CONTRACTOR OPERATED FOR RESEARCH & DEVELOPMENT <input type="checkbox"/> MAINTENANCE <input type="checkbox"/> DISESTABLISHED	6. F. E. O. CODE	FOR BUREAU USE ONLY A B C			D. ACTIVITY Marine Corps Base Camp Lejeune, North Carolina Less Family Housing	
2. SHEET 26A OF 26E	4. ACCT'G. NO. 67001		7. MANAGEMENT BUREAU CODE				E. FOR PERIOD ENDING 30 June 1968	FISCAL YEAR 1968

10. THIS PART CONSISTS OF:	DEFICIENCY CODE	DEFICIENCY CODE
ITEMS OF MAINTENANCE AND REPAIR	XX	XX
ITEMS INCIDENTAL TO MAINTENANCE AND REPAIR	XX	XX

DEFICIENCY CODES IN ACCORDANCE WITH MCO P11000.4A, Change 4.

11 CATEGORY CODE	12 DEFICIENCY NUMBER of Bldgs	13 DEFICIENCY	14 DEFICIENCY CODE	15 ESTIMATED \$ COST		16 PROBABLE FUNDING SOURCE CODE	17 DATE OF FEO VALIDATION OR FEO ON-SITE REVIEW
				THIS INCREMENT	TOTAL REMAINING		
123	6	Sheets 26A through 26E are submitted to emphasize the requirement for exterior paint and structural repairs prior to painting. The dollars shown on these sheets are also included in the appropriate Category Code in the Summary and not considered to be an additional requirement (See Photos enclosure (1)).			\$ 1,935		
124	2				645		
125	1				300		
126	2				940		
131	4				735		







TYPE A ANNUAL INSPECTION SUMMARY
NAVDOCKS 2790 (6-64)

UNFUNDED FACILITIES DEFICIENCIES

Instructions for completing form are contained in NAVDOCKS P-322

1. PART NO. I	3. ACTIVITY CODE 67001	5. OPERATIONAL STATUS OF ACTIVITY <input checked="" type="checkbox"/> ACTIVE <input type="checkbox"/> PARTIAL MAINTENANCE <input type="checkbox"/> DEVELOPMENT <input type="checkbox"/> INACTIVE <input type="checkbox"/> CONTRACTOR OPERATED FOR RESEARCH & DEVELOPMENT <input type="checkbox"/> MAINTENANCE <input type="checkbox"/> DISESTABLISHED	6. F. E. O. CODE	FOR BUREAU USE ONLY A B C	8. ACTIVITY Marine Corps Base Camp Lejeune, North Carolina Less Family Housing
2. SHEET 26D of 26E	4. ACTIVITY NO. 67001		7. MANAGEMENT BUREAU CODE		9. FOR PERIOD ENDING 30 June 1968
10. THIS PART CONSISTS OF ITEMS OF MAINTENANCE AND REPAIR			DEFICIENCY CODE XX	ITEMS INCIDENTAL TO MAINTENANCE AND REPAIR XXXXXXXXXXXXXXXXXXXXXXXXXXXX	
XXXXXXXXXXXXXXXXXXXXXXXXXXXX XXXXXXXXXXXXXXXXXXXX			XX	XXXXXXXXXXXXXXXXXXXXXXXXXXXX	
XXXXXXXXXXXXXXXXXXXXXXXXXXXX XXXXXXXXXXXXXXXXXXXX			XXXXXXXXXXXXXXXXXXXX XXXXXXXXXXXXXXXXXXXX	XXXXXXXXXXXXXXXXXXXXXXXXXXXX	

DEFICIENCY CODES IN ACCORDANCE WITH MCO P11000.4A, Change 4.

14 DEFICIENCY CODE	15 ESTIMATED \$ COST		16 PROBABLE FUNDING SOURCE CODE	17 DATE OF FEO VALIDATION OR FEO ON-SITE REVIEW
	THIS INCREMENT	TOTAL REMAINING		
XXXXXXXXXX of Bldgs		97,273		
740	82	20,448		
750	31	4,000		
812	2	5,105		
821	10	2,650		
831	12	990		
832	11	2,110		
833	4	26,520		
841	59	275		
842	5	27,500		
851	1	1,125		
880	2			





REVISED

TYPE A ANNUAL INSPECTION SUMMARY - TRANSMITTAL SHEET

REPORT BUDOCKS 11014-1

NAVDOCKS 2729 (REV. 1-66)

S/N. 0104-804-8671

Instructions for completing form are contained in NAVDOCKS P-322

1. FROM MCB, CLNC All facilities inspected are in satisfactory condition except those listed on Form NAVDOCKS 2370, having essential deficiencies which cannot be accomplished during the current fiscal year due to lack of resources. <i>H Col Olson</i>	2. B.F.D.	3. ACTIVITY CODE	4. ACTIVITY Marine Corps Base Camp Lejeune, North Carolina 28542	<input type="checkbox"/> 1 LESS HOUSING <input checked="" type="checkbox"/> A HOUSING
	CODE		8. FOR PERIOD ENDING <input checked="" type="checkbox"/>	<input type="checkbox"/> 2 HOUSING FISCAL YEAR <input checked="" type="checkbox"/>
5. TO Commandant of the Marine Corps (Code COM)		7. COPIES TO		9. INSPECTED BY <input type="checkbox"/> ACTIVITY <input type="checkbox"/> BFD <input checked="" type="checkbox"/> CONTINUOUS <input type="checkbox"/> OTHER
6. VIA				<input type="checkbox"/> ONE-TIME COMPREHENSIVE
DATE 18 July 1968 BY DIRECTION <i>RME</i>				

10	11	12	13
FACILITIES NOT INSPECTED	REASON	DATE OF PREVIOUS INSPECTION	APPROXIMATE DATE OF NEXT INSPECTION
None			

14. FIRST ENDORSEMENT

FROM: **Base Maintenance Officer**

DATE **17 July 1968**

Comments **Revised Summary in accordance with CMC Message R051624Z, Jul 68**

The undersigned confirms that the items of deficiencies reported in attached form NAVDOCKS 2730 are essential in accordance with the criteria contained in MCO P11000.4A, and that the deficiencies cannot be accomplished during the current fiscal year.

JAMES M. HAYES
BY DIRECTION

1. NAME OF COMPANY 2. ADDRESS 3. CITY 4. STATE 5. ZIP CODE	6. TYPE OF SERVICE 7. DATE OF INSPECTION 8. NAME OF INSPECTOR	9. NAME OF MANAGER 10. NAME OF SUPERVISOR	11. NAME OF INSPECTOR 12. TITLE
13. TYPE OF SERVICE 14. DATE OF INSPECTION 15. NAME OF INSPECTOR	16. TYPE OF SERVICE 17. DATE OF INSPECTION 18. NAME OF INSPECTOR	19. TYPE OF SERVICE 20. DATE OF INSPECTION 21. NAME OF INSPECTOR	22. TYPE OF SERVICE 23. DATE OF INSPECTION 24. NAME OF INSPECTOR
25. TYPE OF SERVICE 26. DATE OF INSPECTION 27. NAME OF INSPECTOR	28. TYPE OF SERVICE 29. DATE OF INSPECTION 30. NAME OF INSPECTOR	31. TYPE OF SERVICE 32. DATE OF INSPECTION 33. NAME OF INSPECTOR	34. TYPE OF SERVICE 35. DATE OF INSPECTION 36. NAME OF INSPECTOR

DATE 17 July 1968

FROM: Base Maintenance Station
SUBJECT: Annual Inspection in accordance with OIG Message 781212A, Jul 58

The maintenance condition of the items of equipment reported in attached form NAVROINS 1730 are satisfactory. The equipment with the exception of MCM 71000 and the electrical control is satisfactory. The electrical control is satisfactory.

JAMES H. WATTS
10/5501 (10)

REVISIONS TO TYPE A ANNUAL INSPECTION SUMMARY
 FY-68
 DEFICIENCY CODE 1

Category Code	Comments	Sheet No.	Line Item No.	Increase	Decrease
135	Funded FY-68 - dropped from summary	1 of 26E	1		14,800.
152	Excluded by CMC ltr dtd 23May68	"	2		175,000.
214	Funded FY-68 - dropped from summary	"	4		64,000.
218	This item no longer considered essential. Dropped as per Second Endorsement to BMO ltr 21B/HAP/jf over 11100 dtd 3May68	"	5		21,500.
610	Bldg. #1 - Funded FY-68 - dropped from summary Bldg. #2 - This is construction - dropped from summary	2 of 26E	8		26,000.
722	Bldg. #8, 10, 105, 309, 313, 412, 502, 510, 514, & 517 funded FY-68, 15th & 16th Increments, Head & Shower Facilities - dropped from summary	3 of 26E	10		440,000.
722	Bldg. #308, 312, 404, 406, 407, 410, 415, 417, BB-13, - Funded exterior paint & structure repairs FY-68. Bldg. BA-105 funded FY-68 - dropped from summary. The exterior repairs and painting on these buildings was funded and dropped from the summary. However, there are other deficiencies in these buildings, therefore the building number cannot be marked out. Similar cases will be found throughout the revision.	3 of 26E	11		120,992.
723	Estimate revised to \$404,000. Bldg. #206, 307, 411, BB-7, & RR-3 exterior structure & paint funded FY-68 - dropped from summary. Bldg. M-424 substituted for 54.	3 of 26E	12	145,150.	19,000.
723	Not validated as Maintenance & Repair project - (Construction) - dropped from summary.	3 of 26E	13		302,000.

Category Code	Comments	Sheet No.	Line Item No.	Increase	Decrease
730	Bldg. #1500, Exterior repairs & paint accomplished - dropped from summary	4 of 26E	14		4,900.
	Revised estimate on Machine Room & Water softener repairs	4 of 26E	14	10,700.	
740	Bldg. TC-200 - Repairs not considered essential - dropped from summary	4 of 26E	15		10,100.
750	Not validated - dropped from summary	4 of 26E	16		13,000.
812	CMC ltr dtd 23May68 advised that the project for Replacement of street lights (Hadnot Point Area) was considered more associated with rehabilitation, or is of such low priority they were excluded from the summary. Only \$36,000 of the total \$670,000 is for street lights. The remainder is for replacing underground conduit and service wire to 400 housing units; replace poles, crossarms, insulators, hardware, switches & etc. Recommend that this be reconsidered for inclusion in the summary.	4 of 26E	17		36,000.
821	Bldg. #TC-941 - Replacement planned; Bldg. PT-3, No longer considered essential, reference Second Endorsement to BMO ltr 21B/HAP/jf over 11100 dtd 3 May 1968 - dropped from summary	5 of 26E	18		35,550.
841	Bldg. #20 - Ext. Struc repairs & paint funded FY-68 - dropped from summary	5 of 26E	20		2,200.
851	Funded \$100,000 FY-68, dropped from summary	5 of 26E	21		100,000.
852	Parking Areas funded FY-68 - dropped.	6 of 26E	23		22,300.
	Sidewalks funded \$36,000 FY-68 - dropped from summary	6 of 26E	23		36,000.
TOTAL (Increase & Decrease)				\$155,850.	\$1,443,342.
NET DECREASE					\$1,287,492.

WILLIAMS

WILLIAMS (1930-1935)

1930-1935

1935	WILLIAMS (1930-1935)	100.00	100.00
1934	WILLIAMS (1930-1935)	100.00	100.00
1933	WILLIAMS (1930-1935)	100.00	100.00
1932	WILLIAMS (1930-1935)	100.00	100.00
1931	WILLIAMS (1930-1935)	100.00	100.00
1930	WILLIAMS (1930-1935)	100.00	100.00

DEFICIENCY CODE 2

Category Code	Comments	Sheet No.	Line Item No.	Increase	Decrease
171	Bldg. #338, 443, 537 - Ext. Struc & paint funded FY-68 - dropped from summary	7 of 26E	26		2,525.
442	Bldg. #100, 103, 116, 131, 133, 310, 329, 330, 332, 334, 402, 405, 413, 414, 418, 429, 431, 432, 433, 434, 504, 505, 512, 513, 525, 528, 529, 532, 533, 534, 26, 56, 61, 64, BB-6, BB-16, 343, 435, 436, 437, 440, 441, 442, 444, 445, 125-A, 322-A, 322-B, 425-A, and 42, Exterior struc & paint funded FY-68 - dropped from summary	10 of 26E	31		30,585.
610	Bldg. #303, 306, 311, 333, 438, 610, 531, BB-15, 336, 337, 339, 340, 342, 439, 535, 536, 117, 203, BB-5, 114, 121, 317, 400, 416, 419, 501, 516, 423, 320, 123, 13, Exterior struc & paint funded FY-68 - dropped from summary	12 of 26E	32		26,440.
722	Bldg. #102, 104, 105, 108, 112, 118, 120, 124, 128, 202, 204, 208, 212, 220, 224, 227, 228, 301, 305, 309, 313, 316, 318, 321, 323, 326, 327, 409, 412, 420, 422, 426, 427, 502, 503, 506, 507, 510, 511, 514, 515, 517, 519, 523, 527, 6, 8, 10, 12, 51, 53, 55, 57, 60, BB-11, BB-12, BB-14, 43, 58, and 67 Exterior struc & paint funded FY-68 - dropped from summary; Bldg. #105, 128, 213, 224, 227, 503, 507, 514, 515, Interior paint & preparation reduced prior to 30 Jun 1968 by Self-Help and Maintenance effort - dropped from summary	12 of 26E	33		276,098.
723	Bldg. #226, 408 & 509 - Exterior struc & paint funded FY-68 - dropped from summary	15 of 26E	34		11,400.

Category Code	Comments	Sheet No.	Line Item No.	Increase	Decrease
730	Bldg. #BB-8 - Exterior struc & paint funded FY-68 - dropped from summary	16 of 26E	36		665.
740	Bldg. #319, 331, 334, 52, 335, 302, 403, 4, RR-10, BB-3, 117-A, 203-A, 4-A, BB-3A, 403-A, 125, 322, 425, 300, 401, 500, Exterior struc & paint funded FY-68 - dropped from summary	16 of 26E	37		23,670.
841	Bldg #762 - Exterior struc & paint funded FY-68 - dropped from summary	19 of 26E	39		401.
NET DECREASE, CODE 2					\$371,784.

DEFICIENCY CODE 3

Category Code	Comments	Sheet No.	Line Item No.	Increase	Decrease
141	Bldg. 27 - Exterior structure & paint funded FY-68 - dropped from summary	21 of 26E	47		665.
151	Structure SRR-82 - Not validated - dropped from summary	"	48		3,000.
159	Structure MH-2 - Not validated - dropped from summary	"	49		125.
217	Bldg. #207 - Exterior Struc & paint funded FY-68 - dropped from summary	22 of 26E	52		715.
540	Bldg. #36 - Exterior struc & paint funded FY-68 - dropped from summary	23 of 26E	56		375.
550	Bldg. #119 - Exterior struc & paint funded FY-68 - dropped from summary	23 of 26E	57		275.
821	Bldg. #PT-3 - No longer considered essential - dropped from summary	24 of 26E	61		4,180.
NET DECREASES, DEFICIENCY CODE 3					\$9,335.

Sheets 26A through 26E have been revised to show the remaining requirement after funded items and items which are no longer considered essential have been deducted.

THE UNIVERSITY OF CHICAGO
DEPARTMENT OF CHEMISTRY
530 SOUTH EAST ASIAN AVENUE
CHICAGO, ILLINOIS 60607

MEMORANDUM FOR THE RECORD

10/1/68

101. [Illegible text]

102. [Illegible text]

103. [Illegible text]

104. [Illegible text]

105. [Illegible text]

106. [Illegible text]

107. [Illegible text]

APPROVED: [Illegible Signature]

DATE: [Illegible Date]

UNFUNDED FACILITIES DEFICIENCIES

Instructions for completing form are contained in NAVDOCS P-322

1. PART NO. 1	3. ACTIVITY CODE 67001	5. OPERATIONAL STATUS OF ACTIVITY <input checked="" type="checkbox"/> ACTIVE <input type="checkbox"/> PARTIAL MAINTENANCE <input type="checkbox"/> INACTIVE <input type="checkbox"/> MAINTENANCE	6. F. E. O. CODE	FOR BUREAU USE ONLY A B C			8. ACTIVITY Marine Corps Base Camp Lejeune, North Carolina Less Family Housing
2. SHEET 1 of 268	4. ACCT'G. NO. 67001	<input type="checkbox"/> DEVELOPMENT <input type="checkbox"/> CONTRACTOR OPERATED FOR RESEARCH & DEVELOPMENT <input type="checkbox"/> DISESTABLISHED	7. MANAGEMENT BUREAU CODE			9. FOR PERIOD ENDING 30 June 1968	FISCAL YEAR 1968

10. THIS PART CONSISTS OF:	DEFICIENCY CODE	ITEMS INCIDENTAL TO MAINTENANCE AND REPAIR	DEFICIENCY CODE
ITEMS OF MAINTENANCE AND REPAIR	XX		XX
	XX		XX

DEFICIENCY CODES IN ACCORDANCE WITH MCO P11000.4A, Change 4

11 CATEGORY CODE	12 PROJECT NUMBER	13 DEFICIENCY	14 DEFIC. IENCY CODE	15 ESTIMATED \$ COST		16 PROBABLE FUNDING SOURCE CODE	17 DATE OF FEO VALIDATION OR FEO ON-SITE REVIEW
				Line	TOTAL REMAINING		
135	8021A	COMMUNICATION LINES - COMMUNICATION AND CONTROL Replace 1400 L.F. of submarine Tel. Cable across New River at Sneeds Ferry Bridge	1	1	\$14,800	Project 15	Funded F.Y. 68
152		WHARVES Sandblasting Preservating Coating to Metal Mile Hammock Bay	1	2	\$175,000	Project 15	Dropped by CMC Letter
179		1 TRAINING FACILITY OTHER THAN BUILDINGS Replace gasoline motor, Repair third rail, Repair switches, Repair track and track bed - G-5 Range	1	3	14,200	Project 15	
214	8026 80213	2 MAINTENANCE - TANK, AUTOMOTIVE FACILITIES Replace Roofs (2 Roofs) - 1502 & 1601	1	4	64,000	Project 15	Funded F.Y. 68
210		1 MAINTENANCE - FACILITIES FOR MISCELLANEOUS PROCURED ITEMS AND EQUIPMENT Struct. Repair and Exterior Painting - PT-1	1	5	21,500	Project 15	Dropped as per 2nd endorsement to BMO Letter 210/HAP/UF over 1100 of 21104

1968































UNFUNDED FACILITIES DEFICIENCIES

Instructions for completing form are contained in NAVDOCS P 322

1. PART NO. 1	3. ACTIVITY CODE 67001	5. OPERATIONAL STATUS OF ACTIVITY <input checked="" type="checkbox"/> ACTIVE <input type="checkbox"/> PARTIAL MAINTENANCE <input type="checkbox"/> DEVELOPMENT <input type="checkbox"/> INACTIVE <input type="checkbox"/> CONTRACTOR OPERATED FOR RESEARCH & DEVELOPMENT <input type="checkbox"/> MAINTENANCE <input type="checkbox"/> DISESTABLISHED	6. F. E. O. CODE	FOR BUREAU USE ONLY A B C			8. ACTIVITY Marine Corps Base Camp Lejeune, North Carolina Less Family Housing
2. SHEET 16 OF 26E	4. ACCT'G. NO. 67001	7. MANAGEMENT BUREAU CODE				9. FOR PERIOD ENDING 30 June 1968	FISCAL YEAR 1968

10. THIS PART CONSISTS OF:	DEFICIENCY CODE	ITEMS INCIDENTAL TO MAINTENANCE AND REPAIR	DEFICIENCY CODE
ITEMS OF MAINTENANCE AND REPAIR	XX		XX
	XX		XX

DEFICIENCY CODES IN ACCORDANCE WITH MCO P11000.4A, Change 4.

11 CATEGORY CODE	12 PROJECT NUMBER	13 DEFICIENCY	14 DEFIC. TENCY CODE	15 ESTIMATED \$ COST		16 PROBABLE FUNDING SOURCE CODE	17 DATE OF FEO VALIDATION OR FEO ON-SITE REVIEW
				XXXX Line #	TOTAL REMAINING		
730		2617, M-130, M-231, M-233, BB-45, RR-9, TC-1066, TC-1067, TC-1068, TC-1069, TC-1160, TC-1161 & TC-1162 ³⁰ 31 COMMUNITY FACILITIES - PERSONNEL SUPPORT AND SERVICE Interior Painting, Exterior Painting, Elec., Mech., Struct., & Replace Roofs (2 Roofs) - 18, 1400, 2600, BB-8 , RR-6, TC-701, LCH-4022, 3, A-15, A-20, D-41, D-42, M-169, M-325, ES-132, RR-78, SH-8A, TC-307, TC-1300, 25, TT-2477, 2624, M-132, 1968, 1969, 1918, D-33, D-36, M-303, BB-136, & BB-137	2	36	\$24,809 24,144		Ext. Paint & Struc. Funded FY-68 665
740		⁸⁹ 102 COMMUNITY FACILITIES - MORALE, WELFARE & RECREATIONAL INTERIOR Interior Painting, Exterior Painting, Elec., Mech., Struct., & Replace Roofs (11 Roofs) - M-116, M-100, TC-601, 4, 52, 84, 302 , 403, 1207, 1728, M-320, M-602, BB-3 , RR-10,	2	37	195,461 171,791		Ext. Paint & Struc. Funded FY-68 23670









UNFUNDED FACILITIES DEFICIENCIES

Instructions for completing form are contained in NAVDOCKS F-322

1. PART NO. 1	3. ACTIVITY CODE 67001	5. OPERATIONAL STATUS OF ACTIVITY <input checked="" type="checkbox"/> ACTIVE <input type="checkbox"/> PARTIAL MAINTENANCE <input type="checkbox"/> DEVELOPMENT <input type="checkbox"/> INACTIVE <input type="checkbox"/> CONTRACTOR OPERATED FOR RESEARCH & DEVELOPMENT <input type="checkbox"/> MAINTENANCE <input type="checkbox"/> DISESTABLISHED	6. F. E. O. CODE XX	FOR BUREAU USE ONLY A B C	8. ACTIVITY Marine Corps Base Camp Lejeune, North Carolina Less Family Housing
2. SHEET 20 OF 26E	4. ACCT'G. NO. 67001		7. MANAGEMENT BUREAU CODE XX		9. FOR PERIOD ENDING 30 June 1968 FISCAL YEAR 1968

10. THIS PART CONSISTS OF:	DEFICIENCY CODE	ITEMS INCIDENTAL TO MAINTENANCE AND REPAIR	DEFICIENCY CODE
ITEMS OF MAINTENANCE AND REPAIR	XX	XX	XX
	XX	XX	XX

DEFICIENCY CODES IN ACCORDANCE WITH MCO P11000.4A, Change 4.

11 CATEGORY CODE	12 PROJECT NUMBER	13 DEFICIENCY	14 DEFICIENCY CODE	15 ESTIMATED \$ COST		16 PROBABLE FUNDING SOURCE CODE	17 DATE OF FEO VALIDATION OR FEO ON-SITE REVIEW
				XX Line Item #	TOTAL REMAINING		
880		FIRE AND OTHER ALARM SYSTEMS Replace 3000 L.F. burial Fire Alarm Cable Hadnot Point - Replace Fire Alarm Control Circuits, Pull Boxes Hadnot Point, Interior Painting, Exterior Painting & Struct. Repair - ST-7, ST-8 & ST-9	2	41	\$ 14,650		
		Subtotal Deficiency Code 2			\$1,956,602 1,584,818		
123		6 LAND VEHICLE DISPENSING Exterior Painting & Struct Repair - 1002, S-1813, S-1840, S-1843, TC-362 & TC-364	3	42	2,010		
124		2 OPERATING FUEL STORAGE Exterior Painting & Struct Repairs - S-781 and SLCH-4024	3	43	645		
125		1 POL PIPELINE Exterior Painting & Struct Repair (Pumping Station) - 1004	3	44	300		































TYPE A ANNUAL INSPECTION SUMMARY - TRANSMITTAL SHEET

REPORT BUDDOCKS 11014-1

NAVDOCKS 2729 (REV. 1-66)

S/N-0104-804-8671

Instructions for completing form are contained in NAVDOCKS P-322

1. FROM MCB, CLNC All facilities inspected are in satisfactory condition except those listed on Form NAVDOCKS 2370, having essential deficiencies which cannot be accomplished during the current fiscal year due to lack of resources.	2. B.F.O.	3. ACTIVITY CODE	4. ACTIVITY Marine Corps Base Camp Lajeune, North Carolina 28542	<input type="checkbox"/> 1 LESS HOUSING <input checked="" type="checkbox"/> A HOUSING <input type="checkbox"/> 2 HOUSING
	CODE	8. FOR PERIOD ENDING		FISCAL YEAR
	5. TO Commandant of the Marine Corps (Code COM)	7. COPIES TO		9. INSPECTED BY <input type="checkbox"/> ACTIVITY <input type="checkbox"/> BFD <input checked="" type="checkbox"/> CONTINUOUS <input type="checkbox"/> ONE-TIME COMPREHENSIVE <input type="checkbox"/> OTHER
6. VIA		DATE <i>28 Dec 1967</i> BY DIRECTION		

10	11	12	13
FACILITIES NOT INSPECTED	REASON	DATE OF PREVIOUS INSPECTION	APPROXIMATE DATE OF NEXT INSPECTION
None			

14. FIRST ENDORSEMENT

FROM: **Base Maintenance Officer**


DATE **26 Dec 1967**


Comments


The undersigned confirms that the items of deficiencies reported in attached form NAVDOCKS 2730 are essential in accordance with the criteria contained in MCO F11000.4A, and that the deficiencies cannot be accomplished during the current fiscal year.


Attention is invited to enclosures (1) and (2). Enclosure (1) depicts the condition of exterior paint on barracks and other buildings. Enclosure (2) shows, by photographs, a sampling of the condition of the Bituminous Surfaced Roads throughout Marine Corps Base.


JAMES M. HAYES
BY DIRECTION






























































































MESSHALL 521

Paint weathered and fascia board rotten.



BARRACKS 205

Paint weathered and fascia board rotten.

Enclosure (1)

