

JOB ORDER NO	DATE COMPLETED	COST	DESCRIPTION
3418	3-9-90	2260	Procure Service Contract to Remove double door
3013	3-9-90	1320	Repl existing glass/steel door.
3043	4-13-90	13 772	Install wiring system for power and lights.
1018	6-22-90	5012	Fabricate (13) Drain pans.
1001	10-17-90	257	Install (3) Elec. outlets
3771	10-25-91	2504	DISCONNECT / RECONNECT OFFICE MODULES
3637	5-29-91	1749	Repl Comp For A/C UNIT
4331	2-26-93	1621	Repl ace Vinyl Floor tiles
3085	3-3-89	9734	Rm/Repl main service + panel board
2043	5-13-88	3479	Install (6 window) fans + shutters on skylight monitors
3605	5-28-96	5161	Repl Breaker purged 8/23/00 by
4514	10-30-98	2675	1st And Construct room around HVAC system & 9/10/02 PAF
4514	10-30-98	14210	Remove (2EA) A/C Units / install new (Carriers) Purged PAF
3061	050799	5206	Remove 15 48" fluorescent lights in warehouse C/S out LTR 08-99 PAF
3067	050799	395.	Amendment to Delete Hrs NOT Needed on job for Shop 4/1 Etc.

BLDG NO

INT. PAINT SQ FT

EXT. PAINT SQ FT

ROOF SQ FT

CONDEN. LINES LIN FT

FACILITY HISTORY RECORD

MCBCL 11011/3

JOB ORDER NO	DATE COMPLETED	COST	DESCRIPTION
3225	1/14/81	353	ISS MAT for SELF HELP PAINT
4636	6.30.83	666	RPL door
1211	3.25.83	548	INSTALL 20A BRANCH CIRCUIT
1549	9.30.83	729	INSTALL WINDOW
4006	3.15.83	1242	RPL Ceiling Tile
1187	2.25.83	2850	Inst Hot Water Radiators
1191	3.3.83	534	INSTALL LIGHTS RECP.
1087	3.3.83	3993	FAB / ERRECT PART
1058	6-15-84	4775	CONSTRUCT CONFERENCE ROOM
2079	3-29-85	869	INSTALL CIRCUIT TO TELER EQUIP
✓ 2089	5-11-84	2113	ASSEMBLE & PUT INTO OPN ON DISASSEMBLED
2151	3-1-85	405	RELOCATE TELEPHONE CABLES
3202	2-12-86	1925	REPLACE 2 SETS OF DOUBLE DOORS
3548	CP	151	DEWINTERIZE CENTRAL A/C
3573	1-18-85	1271	RPL CONDENSATE PUMP
3981	2-8-85	98	REPAIRS TO DOORS
✓ 4137	8-3-84	457	INSTALL 200 AMP 120/208/3 SERVICE
4167	8-9-85	860	RPL LIGHTING ABOVE WALKWAYS
4408	Compl	1,385	REMOVE 4000 SQ FT OF ADDITIONAL OLD CEILING TILE
4408	Compl	2526	RPL SUSPENDED CEILING
4408	Compl	2408	RPL SUSPENDED CEILING IN CO. OFF.
4725		15,504	GROUP RELAMP, REPAIR LIGHTING
4057	Comp	3,316	CONSTRUCT CONFERENCE ROOM - SELF HELP -
4408	12-10-85	2526	REPLACE SUSPENDED CEILING
4723	5-30-85	15504	RELAMP, REPAIR LIGHTING IN WAREHOUSE & O/S LIGHTS
3202	10-24-85	1925	REPLACE (2) SETS OF DOUBLE DOORS

JOB ORDER NO	DATE COMPLETED	COST	DESCRIPTION
2933	12-15-79	—	PM material handling conveyor belt system
3234	12-1-78	704	Rpl ceiling tile lower right office / paint rpl filler boards ceiling right aid office area
9135	Comp	1189	Install Key telephone system
2612	9-29-78	625	4 th Qtr PM material handling conveyor conveyor belt system
1228	7-14-78	1436	Install 2 safety zone emergency shower & eyewash units
2900	12-8-78	625	1 st Qtr PM material handling conveyor belt system
5341	12-15-78	289	Replace missing door between S-1 and XO's office
2505	8-31-79	220	Install (2) new floor recept w/ plants system bracket
4227	5-25-79	353	Install add outlets w/ quality assurance & household goods area
2005	11-30-79	263	Relocate water cooler
3897	3-23-79	244	Issue material for self help
2536	Complete	1661	Install outlets of computer equip. (19 bldgs)
3185	Comp.	648	Check out heating system
5700	4-2-80	1011	Cleanup auming
3243	3-21-80	193	Rpl. broken window glass doors
1069	1980	354	Knock training, construct windbreaker + Reconstruct SNAK Bar
3237	1980	863	Assist Fire Dept. to test + flush sprinkler systems
3150	1980	11,992	Relamp all 48" fixtures + Repair low pressure sodium fixtures outside
4138	3-20-81	10,913	Rpl. roof over loading ramp
1208	9-24-82	3605	Install Heating in Rec. offices
1202	8-13-82	3665	Fab. + erect partition, heat + A/C units rooms, Paint
1346	5-28-82	436	Install Elec. Circ & window A/C unit
1145	3-16-82	1325	Expans. of office
4115	1-15-82	1154	Repair floor tile + ceiling tile. interior repairs

JOB ORDER NO	DATE COMPLETED signed	COST	DESCRIPTION
07260	5/4/62		Inst 4 fluorescent lights (C 5/11/62)
023-03615-82	7/13/62		Minor repairs and remodeling
023-02717-82043	9/27/62		Paint exterior
023-02784-82	10/28/62		Renovate
023-03041-82	2/11/63		Install grounding
ND4-06534220510	6/11/64	234.39	Inst 3 receptacles for A/Cond (C 6/17/64)
45105	1-3-69	312	Relocate 4 lites, install 3 toggle switches
30807	10-7-68	1063	Rpr exterior walls + doors
N62470-70-C-0489	1/28/71		Mechanical Repairs
OND-186	6-13-68	294	Replace 200 amp circuit breaker
OND-142	9-6-67	1037	Remove old + rpl with new floor tile
ODG-109	9-26-67	458	Relocate floor outlets
OC2-106	5-23-67	186	Rpl 2 flr lite fixtures
577-174	1-20-67	619	Rpl steam coil
530-152	5-3-67	518	Install 50' feedrail
653-144	3-20-67	5515	Build a continuous protective weather shelter
611-125	1-6-67	185	Dig up straighten + rpr hydrant
4424	4-13-70	489	Paint 5 ceilings
2653	10-15-70	632	Install security gates
2651	10-15-70	1281	Rpr foot locker
3317	7-30-69	4444	Ext rps + paint
1095	10-26-71	311	Install receptacles
2489	7-24-72	403	Install A/C
2519	8-3-72	97	" "
2638	11-7-72	2225	Inst a KTS 515
4015	9-24-73		Correct wiring in machine rooms + specilla m.

JOB ORDER NO	DATE COMPLETED	COST	DESCRIPTION
2463	10-15-73	200	INSTALL RECEPTACLES
2606	9-9-74	325	RPL SIGNS
9133	11-8-74	1557	Inst a key telephone system
4036	9-19-74	5771	Rpr + paint interior
0221		481	Improve Lending machine
0252		122	Sprinkler system in Lending machine
3919	10-10-75	310	Repair & Paint side entrance shed
3646	8-29-75	242	Repair to brick wall
0147	11-7-75	358	Extend air ducts & insulate
1129	12-2-75	191	Install (4) new downy type flood lights
2862		794	Sign for Bldg
2602	4-14-78	625	PM material handling conveyor 3rd & 4th 78
3679	12/15/76	5322	Rpl water tower
2862	9/19/74	794	Signs for bldg
2494	10/22/74	285	Relocate 3 (AC)
1115	12/8/76	529	install new light panel
1011	12/8/76	150	install door (1st maj office)
1112	12/11/76	298	modify conveyor
1038	10/20/76	171	install (4) additional duplex recept
1028	10/21/76	483	install lightning on Bn file rm
1005	10/22/76	328	install (2) sets of door locks
3888	3-11-78	205	Repair cords on trolley feedrail
9138		1569	Upgrade telephone service to bldg
4879	5-12-78	981	Replace A/C compressor
1016	2-3-78	344	Extend A/C duct line into another rm.
3472	12-2-77	626	Correct drainage of roof