

BLDG NO

INT. PAINT SQ FT

EXT. PAINT SQ FT

ROOF SQ FT

CONDEN. LINES LIN FT

FACILITY HISTORY RECORD

TC-754

MCBCL 11011/3

JOB ORDER NO	DATE COMPLETED signed	COST	DESCRIPTION
529-62	2/23/62	610.35	Rehabilitate and int and ext paint (C 2/23/62)
897-62	6/18/62	1,016.	Replace obsolete lighting (C 6/22/62)
1038	3-18-74	4574	Install Head facilities & cover floors
3377	8-17-73	2006	Repair & paint ext
4767	6-29-73	288	Int repairs to window & doors
2764	6-22-73	215	Change (5) 115V recept
1128	3-30-73	7037	Remount Bldg sign
1127	3-30-73	553	Furnish & install metal partition
4331	3-19-71	493	Repair & paint int
2485	2-13-70	181	Install 2 type recept
4059	12-5-69	174	Replace Heating Coil
4650	1-16-75	6900	Remove old storm & condenser lines from attic
5137	4/14/76	3108	Reps to today
Contract # 79-2615	Fy 79	2000	Ext- & Int Paint
1242	4-28-78	1464	Install new elec service - new outlets and 4 winter A/C units
3401	7-6-79	3268	Make int ext reps to old and paint
3263	Comp	552	Replace Steam heating coil.
3881	Comp	6479	Replace window & door screens.
4382	12-11-81	228	Repairs before contract painting
3924	9-23-83	1027	Replace broken sewer line
1243	9-18-86	352	Construct new head m A/C line field OFF.
3458	9-21-84	1051	Repairs to Int and Ext -
8832	1-15-86	11396	Perform Recurring Cyclic Maint
3779	3-19-86	3111	Repl Masonite wall, Repl door locks, Raise Front Stoop, Paint Int. of TMO Offices
4407	3-18-85	1893	Repl Missing & Damaged Screens

