

BLDG NO

INT. PAINT SQ FT

EXT. PAINT SQ FT

ROOF SQ FT

CONDEN. LINES LIN FT

FACILITY HISTORY RECORD

MCBCL 11011/3

5 BA-142

JOB ORDER NO	DATE COMPLETED	COST	DESCRIPTION
NB4-04977-22	1/16/64		Replace built up roof
HQ7-087-627-126	5/19/67	592	Dismantle 6 sets Bleachers & assemble at Bldg 751
HQ7-170-600-116	4/21/67	1,828	Remove 6 sets Bleachers & replace w/6 sets from 5-1715
HQ8-CM-09C-100	3/22/68	1,441	Misc carp, elect, plumb & paint repairs
HQ8-CM-09C-104	1/5/68	120	Repair insulation & replace defective elect heat tapes beneath Bldg
HQ8-CM-09C-105	5/17/68	405	Replace deteriorated conduit, wire, etc.
HQ8-CM-09C-107	5/10/68	1,085	Repairs & paint ext trim
HQ8-CM-09C-113	4/19/68	598	Repair pier
AA9-23-XV-31704	4/11/69	1,344	Repairs & paint ext
AA1-23-437503X-T	5/16/71	2,190	Repair & paint interior & exterior
AA2-23-469223X-	11/14/72	241	Repair & partial paint ext.
AA6-23-388623X	10/8/69	261	Repair & paint
60025	3-13-86	295	REPLACE FLUSH TYPE WATER @ CLOSETS w/ TANK TYPE
3427	7-1-91	5820	Repl existing rusty steel window/door security.
3547	6-11-91	3600	Repl water lines at Pier.
3682	Complete	3592	REMOVE FIBERGLASS ROOFING
4876	3-24-94	579	RELOC SECONDARY ELECTRODE CONDUCTOR
3837	3	3146	
3837	3-1-96	871	RPR Broken Sewer Line in PUNGLU 33

JOB ORDER NO	DATE COMPLETED	COST	DESCRIPTION
4662	4-25-75	717	Repair to window screens, doors, deck boards
4661	5-2-75	1265	Int Paint & Repairs
4765	4-30-76	3740	Repairs + Paint Exterior
4721	4-30-76	151	Interior Repairs
5313	5/24/76	6520	make necessary repairs to pier
3719	12/21/74	70	Rpr to screen door, reconnect tile
3804	5-20-77	2239	Rpr + paint 2 apts. int + ext
4033	3-10-78	117	Rpl fiberglass panels on roof wind damage damage
4339	4-21-78	3592	Make necessary repairs and paint
3346	11-30-78	943	EXT + INT Repairs + paint new wood
3239	4-3-81	1,015	Rpr to Rec. Ledge, & rpl. bad wood on pier
3286	3-12-82	1680	Replace sewer line beneath pier
3221	1-14-82	2301	Repairs int & ext, paint int of 2 apts complete
(Amend) 3239	4-16-81	213	Repairs to Rec Ledge, & Replace bad wood on pier
4416	12-18-81	501	Repairs to pier ramp, using salted treated lumber
4727	2-4-83	2187	Repair Benches, Vents, Fiber Glass Roofing
3189	2-2-83	920	Repair handrail, paint Soft Maj. Cabana
3784	2-23-83	5640	De-winterize Beach Bldg
4604	4-25-83	2311	Rep. Paint
1135	1-10-83	943	RPI glass panel doors
3784	3-4-83	535	
1002		1009	Insulate All Exposed water lines on & under Fishing Pier
4604	4-25-85	2311	Rpr + Paint
3491	12-18-85	4009	Rock Parking Area
1002	9-19-86	1009	INSULATE ALL OF EXPOSED W/TIC LINES FISHING Pier
1249	5-23-86	2179	ONSLOW BEACH
1249	5-23-86	2179	EXPAND PARKING AREA AT SBA-142
3576	1-24-86	110	REFIT DOORS