

BLDG NO
BB-31

INT. PAINT SQ FT

EXT. PAINT SQ FT

ROOF SQ FT

CONDEN. LINES LIN FT

FACILITY HISTORY RECORD
MCBCL 11011/3

JOB ORDER NO	DATE COMPLETED signed	COST	DESCRIPTION
022-06688-620	1/23/62	E 1457.21	Repairs and paint (C 5/15/62)
023-03165-82	8/25/63	E 285	Renovation
H98-CM-OND-114	10/6/67	1,172	Replace condensate lines, traps & fittings, condensate pump unit. ^{Repair insulation on steam lines}
H98-CM-OND-123	2/23/68	416	Repair & paint interior of maint shop complete
H58-CM-05N-225	5/31/68	520	Install (5) 96" fluo. lights in classroom
AA9-23-XX-3200	7/16/70	129	Self-Help paint - 2 offices
3137	6-21-74	2804	Repairs & paint exterior
3139	1-25-74	2157	Repair & paint interior
1076	10-3-71	96	Installation of ext door, west end
1044	12-30-71	467	Construct security cage
1022	12-2-71	4607	Install (8) steam space heaters
4216	4-2-71	540	Replace main service
1025	10/21/76	786	install 8 fluo. light fixtures.
3249	11-4-80	468	Remove incandescent light fix., replace with flouresc.
1006	11-7-78		
4638	8-12-77	1402	Repair leaking steam pit
1198	3-7-79	2997	Issue material to build int partition, panel and insulate wall stg. CR 5
1006	11-7-78	400	Install flourescent light furnish material self-help
3340	11-26-79	1258	Replc MO Gas pumps
3613	5-4-79	4318	Ext Reps to bldg
4316	5-23-79	144	Indmitfy & connect telephone syst
4058	8-15-80	1322	Repair metal doors
3491	7-24-81	467	Install (4) new 115V Recept and one 120V A/c outlet.
4116	COMP	3700	Rework the Heating System.

JOB ORDER NO	DATE COMPLETED	COST	DESCRIPTION
2069	Comp	2500	Procure contract for leasing
3628	4-16-82	2226	Replace condensate pumps
2028	Comp	3839	maintain intrusion alarm system
2003	Comp	3831	maintain intrusion alarm system
3084	10-285	997	Route service to gas pump
3671	2-1784	593	Pump out WATER from fuel tanks

REC'D
 FILED
 FEB 11 1984
 RECORDED