

1980
HADNOT POINT

JULY			AUGUST			SEPTEMBER			OCTOBER			NOVEMBER			DECEMBER			REMARKS		
WELL #	STAT.	PUMP LEV.	DRAW DOWN	STAT.	PUMP LEV.	DRAW DOWN	STAT.	PUMP LEV.	DRAW DOWN	STAT.	PUMP LEV.	DRAW DOWN	STAT.	PUMP LEV.	DRAW DOWN	STAT.	PUMP LEV.		DRAW DOWN	
601		Down																		
602				34'	60'	26'	35'	60'	25'							37'	60'	23'		
603		60'		38'	60'	22'	35'	58'	23'							37'	57'	20'		
606										52'	15'	37'				15'	52'	37'		
608	41'	57'	16'	41'	59'	18'	40'	54'	14'	40'	50'	10'								
609										40'	10'	30'				10'	40'	30'		
610				21'	45'	24'	22'	47'	23'									43'		
611																				
612	35'																			
			Down 29 July																	
			PUMPING SAND.																	
613																				
614																				
615	28'	19'	9'	30'	43'	13'				28'	11'									

CLW
0000003644

STAT. = STATIC PUMP LEV. = PUMPING LEVEL

JULY				AUGUST			SEPTEMBER			OCTOBER			NOVEMBER			DECEMBER			REMARKS
WELL #	STAT.	PUMP LEV.	DRAW DOWN	STAT.	PUMP LEV.	DRAW DOWN	STAT.	PUMP LEV.	DRAW DOWN	STAT.	PUMP LEV.	DRAW DOWN	STAT.	PUMP LEV.	DRAW DOWN	STAT.	PUMP LEV.	DRAW DOWN	
1980 HADNOT POINT																			
616	35'	10'					35'	10'	25'							35'	10'	25'	
620																			
621																			
626																			
627																			
632																			
633	38'	25'	8'																
634	20'	50'	30'																
635	50'	38'	12'																
636	30'	58'	28'																
637	72'	77'	5'	70'	77'	7'	69'	75'	6'										
638																			

STAT. = STATED

PUMP LEV. = PUMPING LEVEL

450000003645

