

If any of these fasteners are located, contact your QPA representative or supervisor for instructions or J. G. Bolm or J. E. Duda.




HELP STAMP OUT SUSPECTS/COUNTERFEITS

Examples of stainless steel fasteners that have been upgraded from 18-8 to ASTM A320 or ASTM A193 Grade B8 after hand stamping. The last three examples show samples of fasteners to indicate conformation to two noncompatible standards, ASTM A193 and ASTM F 593C.

Any bolt on this list should be treated as defective without further testing and process in accordance with PRC-PRO-QA-301. Note: This list was originally published by DOE/EH-0196, Issue No. 97-6.

If any of these fasteners are located, contact your facility S/CI Point of Contact (POC) for instructions. The POC list is on the Hanford Intranet at: <u>http://prc.rl.gov/rapidweb/QA/i</u> <u>ndex.cfm?PageNum=58</u>.







CH2MHILL Plateau Remediation Company