


CHAPTER 2—ORGANIZATION OF SPECIFICATIONS

Specifications are divided into various Divisions and Sections (see PDDM Subchapter 9.6.9.8).

Each section uses the hierarchy shown below to distinguish varying levels of information. Use only as many sublevels as necessary to clearly organize and convey specification requirements. Add content-specific headings where possible.



* Main Subsection Headers follow the five part AASHTO format: Description, Material, Construction Requirements, Measurement, and Payment.

Figure 2-1. Hierarchical Organization of FLH Specifications

