

Combined IR/ER/LER Report
Docket: 50-423 MILLSTONE 3

Total Number of Hits in Date Range: 2
From 01/01/2003 to 01/01/2004
2x National Average: 85

Details	Department	Work Type	Docket/Report
Communications IR			
Number of items: 0			
Percent of total: 0			
Communications ER			
Number of items: 0			
Percent of total: 0			
Communications LER			
Number of items: 0			
Percent of total: 0			
Human-System Interface and Environm IR			
Number of items: 0			
Percent of total: 0			
Human-System Interface and Environm ER			
Number of items: 0			
Percent of total: 0			
Human-System Interface and Environm LER			
Number of items: 0			
Percent of total: 0			
Management and Supervision IR			
Number of items: 2			
Percent of total: 100.			
40-Individual Corre G-Engineering	M-Maint / Repair		50-423/2003004
47-Root Cause LTA G-Engineering	M-Maint / Repair		50-423/2003004
Management and Supervision ER			
Number of items: 0			
Percent of total: 0			
Management and Supervision LER			
Number of items: 0			
Percent of total: 0			
Organizational Issues IR			
Number of items: 0			
Percent of total: 0			
Organizational Issues ER			
Number of items: 0			
Percent of total: 0			
Organizational Issues LER			
Number of items: 0			
Percent of total: 0			
Procedures and Reference Document IR			
Number of items: 0			
Percent of total: 0			
Procedures and Reference Document ER			
Number of items: 0			
Percent of total: 0			
Procedures and Reference Document LER			
Number of items: 0			
Percent of total: 0			
Training IR			
Number of items: 0			

Percent of total: 0

Training ER

Number of items: 0

Percent of total: 0

Training LER

Number of items: 0

Percent of total: 0

Work Factors IR

Number of items: 0

Percent of total: 0

Work Factors ER

Number of items: 0

Percent of total: 0

Work Factors LER

Number of items: 0

Percent of total: 0

Page: 1

Date:05/24/2004