Gallatin Fossil Plant (GAF) Fact Sheet



Issues Found

- Steep divider dike slopes at Bottom Ash Pond A.
- Steep slopes at north dike toe of Fly Ash Pond E.

Remediation Projects Completed

None.

Remediation Projects Partially Completed

None.

Future Remediation Projects

- Flattening and/or buttressing of divider dike slopes at Bottom Ash Pond A.
- Flattening and/or buttressing of dike toe at North side of Fly Ash Pond E.

