

<b>REPORT OF CHANNEL CONDITIONS</b> <b>100 TO 400 FEET WIDE</b> <i>(ER 1130-2-306)</i>	<b>PAGE</b> 1 <b>OF</b> 1
	<b>DATE</b> December 3, 2010

<b>TO:</b> The Record	<b>FROM:</b> U.S. Army Corps of Engineers 26 Federal Plaza, ATTN: CENAN-OP-ST New York, NY 10278-0090
-----------------------	-------------------------------------------------------------------------------------------------------------

<b>RIVER/HARBOR NAME AND STATE:</b> Port Jefferson Harbor, New York	<b>MINIMUM DEPTHS IN CHANNEL ENTERING FROM SEAWARD</b>
------------------------------------------------------------------------	--------------------------------------------------------

NAME OF CHANNEL	DATE OF SURVEY	AUTHORIZED PROJECT			LEFT OUTSIDE QUARTER (feet)	MIDDLE HALF (feet)	RIGHT OUTSIDE QUARTER (feet)
		WIDTH (feet)	LENGTH (n. miles)	DEPTH (feet)			
<b>Reach A:</b> A Channel from deep water in Long Island Sound to the Head of the Harbor	Map 9 Sheet 1-4 of 4; 3 Nov 2010	300*	2.0	26*	24.4	27.9	26.1

**REMARKS:**

- All depths in Mean Low Water (MLW)
- Channel Length is in nautical miles

**PORT JEFFERSON HARBOR**

- **Reach A:** A small shoaling area exists at approximately 1,800 feet seaward of RED NUN #4 on the toe of the left channel line.
- \* The channel was never completed to the authorized depth of 40 feet or authorized width of 350 feet. In 1957, the channel was dredged by private interests to a depth of 26.0 feet with a width of 300 feet.