


Navigation Channel Condition Status Report - 22 January 2015



Dredge Status
Dredge Potter
- Potter will be docked until further notice.

Channel Marker Status
Be aware that there may be other buoys off station/missing than the ones mentioned in this report. Mariners should use caution.
The MV PATHFINDER will be docked until further notice.

Additional Risks / Concerns
Winter Ice Conditions At Locks
LD 22 - 100% ice coverage, 3 in. thick breaking, 20 mi. upstream. Due to heavy ice conditions a 70-foot width restriction is in effect until further notice at Lock 22. Double tripping or use of an industry helper boat will be required.
LD 24 - 80% ice coverage, 3 in. thick sheet, 14 miles upstream.
LD 25 - 70% ice coverage, 3 in. thick sheet, 12 miles upstream.
Mel Price LD - 100% ice coverage, 3 in. thick sheet, 12 miles upstream.

Navigation Notices
Local Notice to Mariners

Current Weather
Highs in the upper 50's to upper 40's and lows in the upper 20's to upper 30's. Friday snow showers and p.m. rain.
[Hannibal, MO](#)
[St. Louis, MO](#)
[Cape Girardeau, MO](#)
[Cairo, IL](#)

Web Information
For additional info about New River Training Structures, see the link below:
<http://www.mvs.usace.army.mil/Missions/Navigation/Construction.aspx>
For the most recent channel patrol and predredge surveys, see the link below:
<http://www.mvs.usace.army.mil/Missions/Navigation/Surveys/Dredge.aspx>
The new electronic Navigation charts for the Upper Mississippi River are now available online for download or to order at the below link:
<http://www2.mvr.usace.army.mil/NIC2/mrcharts.cfm>

More Status Reports
Please click for older status reports

Key

◆	Anticipated Dredging Locations
★	Groundings
△	Dredge Potter
▽	Dredge Goetz
▽	Dredge America
Red	Very Likely to be Problematic Within 4 Weeks
Yellow	Could be Problematic Within 4 Weeks
Green	Problem Resolved

Probable "Hot" Spots Within 4 Weeks / Upcoming Dredging Locations

River Mile	Estimated Problematic Date	Dredge ETA	Dredge Complete	Dredge
	28+ Days			

Please click below to email comments or suggestions:
mvsnavstatus@usace.army.mil

Generation Time: 01-22-2015 11:23