


## Navigation Channel Condition Status Report - 04 May 2016



**Dredge Status:**  
Dredge Potter: Dockside until further notice.

**Channel Marker Status:**  
Be aware that there may be other buoys off station/missing than the ones mentioned in this report. Mariners should use caution.  
  
For ATON or Buoy issues please contact SUMRWaterways@uscg.mil or 319-520-8556.  
  
The Pathfinder will be dockside next week.

**Additional Risks / Concerns**

**Navigation Notices**

**Local Notice to Mariners**

**Weather**  
Highs in the lower 80's; Lows in the upper 40's, rain Wed. and Sun.

Hannibal, MO
St. Louis, MO
Cape Girardeau, MO
Cairo, IL

**Web Information**  
For additional River Training Structure information, see the link below:  
<http://www.mvs.usace.army.mil/Mission/Navigation/Construction/Current.aspx>  
  
For the most recent channel patrol and pre-dredge surveys, see the link below:  
<http://www.mvs.usace.army.mil/Mission/Navigation/Surveys/ChannelPatrol.aspx>

The new electronic Navigation charts for the Upper Mississippi River are now available online for download or to order at the below link:  
<http://www2.mvr.usace.army.mil/NIC2/mrcharts.cfm>

**More Status Reports**  
[Click for older status reports](#)

**Key:**

- ◆ Anticipated Dredging Locations
- ☆ Groundings
- △ Dredge Potter
- ▽ Dredge Goetz

	Very Likely to be Problematic at Low Water
	Could be Problematic at Low Water
	Problem Resolved

**Probable "Hot" Spots**

River Mile	Min Depth at Low Water	Problematic On:	Dredge ETA	Dredge Complete	Dredge