

104 First Choice Drive • Suite A • Madison, MS 39110 (601) 898-2434 • FAX (601) 898-3738

## Original Via Certified U.S. Mail - Return Receipt Requested and Copy Via E-Mail

February 11, 2014

Wayne T. Lemoi Director, Office of Pipeline Safety PHMSA Southern Region 233 Peachtree Street Ste. 600 Atlanta, GA 30303

Dear Mr. Lemoi:

CPF 2-2014-60002

On August 12-15, and August 27, 2013, representatives of the Pipeline and Hazardous Materials Safety Administration (PHMSA), Southern Region, Office of Pipeline Safety (OPS) inspected the Enmark Energy, Inc. (Enmark) Sandhill and Air Liquide Carbon Dioxide (C0<sub>2</sub>) pipelines in Madison, Mississippi, pursuant to chapter 601 of 49 United States Code.

As a result of the inspection, it appears that Enmark has committed probable violations of the Pipeline Safety Regulation, Title 49, Code of Federal Regulations and PHMSA proposes to issue a Compliance order to Enmark. Enmark has reviewed the *Proposed Compliance Order* and will take the required steps in the *Proposed Compliance Order* so that Enmark ensures its compliance with the pipeline safety regulations. Thank you for inspecting our pipelines and identifying items that needed to be improved in order to operate our pipelines in the safest manner possible.

Sincerely yours,

Connell Rader

President

Enmark Energy, Inc.

cc: Michael Schwarzkopf (via e-mail)