



U.S. Department
of Transportation

**Pipeline and
Hazardous Materials Safety
Administration**

233 Peachtree Street Ste. 600
Atlanta, GA 30303

November 26, 2010

Mr. Steve Pankhurst
President
BP Pipelines (North America), Inc.
28100 Torch Parkway
Warrenville, IL 60555

CPF 2-2008-5007

Dear Mr. Pankhurst:


On October 9-12, and October 22-24, 2007, a team of representatives from the Pipeline and Hazardous Materials Safety Administration (PHMSA), Office of Pipeline Safety conducted an inspection of the BP Pipelines (North America), Inc. (BPNA) gas integrity management program (IMP) in Warrenville, Illinois, pursuant to Chapter 601 of 49 United States Code.

As a result of the inspections, PHMSA issued a Final Order on October 6, 2010. The Final Order included a Compliance Order (CO), which required BPNA to take certain actions to protect the public and the environment.

The PHMSA Southern Region has reviewed your November 12, 2010, written response to the CO. We find that you have met the requirements specified in the CO. No further action is necessary with regards to the Final Order and this case is now closed.

Please be advised that nothing herein states or implies that the above described gas integrity management program meets the requirements of the federal pipeline safety regulations or that the program is approved. The pipeline system and IMP remain subject to inspection by PHMSA.

Sincerely,


Wayne T. Lemo
Director, Office of Pipeline Safety
PHMSA Southern Region