Appendix M Explanation of Schematic Symbols

The following symbols are used consistently on schematic representations of production sites.

Schematic feature	Symbol
Oil well	•
Gas well	÷.
Drilling well	0
Injection well	$\overset{\circ}{\mathbf{r}}$
Production equipment	\bigcirc
Gas plant	
Lease automatic custody transfer (LACT) turbine meter	P
Orifice meter	
Tank	
Allocation meter/injection point	

Schematic feature	Symbol
Directionally drilled well	✓ Surface location
	Bottom hole location
Plugged and abandoned (P&A)	-\$-
Temporarily abandoned (TA) oil	•
TA gas	÷