

# **Richland Operations Office Vision**

Continuing Our Legacy of Success: Cleanup and Protection for the Future

## 2016 - 2028





## **Mission**:

Protect the workers, public and environment by further risk reduction, provide necessary infrastructure for continued safe and effective cleanup operations, and restore Hanford lands for access and use.



### Infrastructure and Facility Base Operations

- Operate key waste management facilities
- Maintain safe operations for Hanford nuclear and nonnuclear facilities
- Provide occupational medicine, laundry and other essential site-wide services
- Provide safeguards and security
- Maintain infrastructure

#### Groundwater Base Operations

- Contain key contaminants and treat contaminated groundwater
- Maintain RCRA compliance
- Implement RCRA groundwater monitoring requirements

## K Basin Sludge Transfer

 Complete transfer of K West Basin sludge to the Central Plateau



### Complete Remaining River Corridor Cleanup

- Complete dewatering, demolition and removal of K West Basin
- Complete the remainder of K Area facility D4 and waste site remediation
- Complete K Area Reactors Interim Safe Storage
- Complete 618-10 and 316-4 remediation
- Complete 300-296 waste site remediation and 324 Building D4
- Conduct any additional soil remediation required by the final CERCLA RODs
- Complete 618-11 remediation

#### Complete Capsule Transfer from the WESF to Dry Storage

- Complete design and construction of a transfer and storage facility
- Transfer 1,936 cesium/strontium capsules (~100 million curies) to dry storage

## Complete Infrastructure Upgrades to Accomplish the Site Mission

- Upgrade critical site infrastructure
- Support startup of the Waste Treatment Plant and Tank Farm operations



## Expand Groundwater Cleanup

- Complete 300 Area uranium sequestration
- Conduct any additional groundwater remediation required by the final River Corridor CERCLA RODs
- Obtain 200 East CERCLA RODs
- Implement 200 East (BP-5/PO-1) remedies
- · Implement additional remedies required by the 200 West UP-1 CERCLA ROD
- Conduct well decommissioning





## Retrieve, Treat, and Enable Shipping of Transuranic Waste to WIPP

- Retrieve and treat "contact-handled" TRU waste
- Retrieve and treat "remote-handled" TRU waste
- Develop and implement new TRU waste disposition capabilities
- · Certify and ship TRU waste to WIPP
- Treat K Basin sludge



## Continue Cleanup of the Central Plateau

- Complete waste site characterization and treatability tests
- Complete RI/FS and obtain RODs
- Remediate waste sites
- Demolish facilities
- Conduct RCRA TSD closures



### Initiate Canyon Disposition

- Conduct demolition preparation and hazard reduction
- Complete canyon characterization (B Plant, PUREX, REDOX)
- Complete above grade demolition of U Plant canyon, remediate adjacent waste sites and install protective barrier



## Restore Hanford Land for Access and Use

- Manage and operate the Manhattan Project National Historical Park in partnership with the National Park Service
- · Increase controlled Tribal and public access and use
- Protect cultural resources and restore natural resources
- · Work closely with our partners to enable reuse of Hanford land consistent with the Comprehensive Land-Use Plan