

Agreed Order Signed August 7, 2012

Jose Felipe and Maricela Flores, Docket No. GUD 9805

Location of violation: Stafford Apartments, Unit ID No. 22163, System ID No. 161045, Dimmit, Castro County, Texas

Rule Violated:

Pipeline Safety Rule Title 16, 8.220(b): Leakage survey of master-metered distribution system not conducted.

Date Violation Began: April 21, 2008

Date of Compliance: September 22, 2008

Penalty Paid: \$3,750.00