

COGIS - Field Inspection Report



API Number: 05-061-06010	Name: FOSTER #1
Location: NENW 15 19S 45W	Lat: 38.40981 Long: -102.44794
Operator #:	Operator Name: WESTERN OPERATING COMPANY
Inspection Date: 8/15/2011	Inspector: GARY HELGELAND

Inspection was: **Unsatisfactory**

Insp. Type: **ES** Insp. Stat: **PR** Reclamation (Pass, Interim or Fail): P&A (Pass/Fail):
Brhd. Pressure: Inj. Pressure: T-C Ann. Pressure: UIC Violation Type:
Violation: **Y** NOAV Sent: **N** Date Corrective Action Due: Date Remedied:

Field Inspection Comments and Observations

Insp. Comment	Inspection/Violation Comments
ACTION	REPAIR AND MAINTAIN WELLHEAD. REMOVE AND PROPERLY DISPOSE OF CONTAMINATED SOIL.
SPILCOM	OBSERVED LARGE PILE OF OILY SOIL STOCKPILED ON LOCATION. LARGE AREA OF OILY SOIL FROM WELL LEAK AT STUFFING BOX. SOIL SAMPLED FOR ANALYSIS. REPAIR AND MAINTAIN WELLHEAD. REMOVE AND PROPERLY DISPOSE OF CONTAMINATED SOIL.