

Agreed Order Signed April 10, 2012

South Shore Pipeline, L.P., Docket No. GUD 10137

At 19289 South Shore/Reg 7 Unit, System ID 1580 of Company ID 6482, System ID 73065925, S. Coast, 4"-5"-8" and System ID 730180 Barney Davis, 8", Nueces County, Texas.

Rules Violated:

49 CFR 192.603(b): Records necessary to administer the operation and maintenance plans were not maintained or were inadequate.

49 CFR 192.807(b): The operator did not maintain records supporting an individual's current qualification while the individual was performing the current task.

Date Violation Began: February 14, 2011

Date of Compliance: January 18, 2012

Penalty Paid: \$3,750.00