

## Bibliography of Open-File Reports for Level II scour analyses for Vermont Bridges

**Contact:** Debra Foster, Outreach Coordinator for a copy of any of these Open-File Reports  
dhfoster@usgs.gov (603) 226-7837 FAX (603) 226-7894

---

- Ayotte, J.D., 1996a, Level II scour analysis for Bridge 2 (CRAFTH00590002) on Town Highway 59, crossing Black River, Craftsbury, Vermont: U.S. Geological Survey Open-File Report 96-156, 51 p.
- 1996b, Level II scour analysis for Bridge 10 (NORWTH00120010) Town Highway 012 Bloody Brook, Norwich, Vermont: U.S. Geological Survey Open-File Report 96-161, 59 p.
- 1996c, Level II scour analysis for Bridge 22 (CRAFTH00180022) on Town Highway 18, crossing Black River, Craftsbury, Vermont: U.S. Geological Survey Open-File Report 96-158, 50 p.
- 1996d, Level II scour analysis for Bridge 25 (CLARTH00100025) on Town Highway 10, crossing the Clarendon River, Clarendon, Vermont: U.S. Geological Survey Open-File Report 96-636, 50 p.
- 1996e, Level II scour analysis for Bridge 25 (HARDTH00420025) on Town Highway 42, crossing Lamoille River, Hardwick, Vermont: U.S. Geological Survey Open-File Report 96-231, 55 p.
- 1996f, Level II scour analysis for Bridge 26 (CRAFTH00250026) on Town Highway 25, crossing Black River, Craftsbury, Vermont: U.S. Geological Survey Open-File Report 96-155, 50 p.
- 1996g, Level II scour analysis for Bridge 34 (BRIDTH00050034) on Town Highway 005, crossing North Branch Ottauquechee River, Bridgewater, Vermont: U.S. Geological Survey Open-File Report 96-190, 52 p.
- 1996h, Level II scour analysis for Bridge 37 (BARTTH00080037) on Town Highway 8, crossing Willoughby River, Barton, Vermont: U.S. Geological Survey Open-File Report 96-405, 47 p.
- 1996i, Level II scour analysis for Bridge 45 (CHELTH00440045) on Town Highway 44, crossing first Branch White River, Chelsea, Vermont: U.S. Geological Survey Open-File Report 96-241, 50 p.
- 1997a, Level II scour analysis for Bridge 9 (BLOOVT01020009) on State Route 102, crossing the Nulhegan River, Bloomfield, Vermont: U.S. Geological Survey Open-File Report 97-389, 50 p.
- 1997b, Level II scour analysis for Bridge 32 (BRIDTH00050032) on Town Highway 005, crossing North Branch Ottauquechee River, Bridgewater, Vermont: U.S. Geological Survey Open-File Report 96-152, 48 p.
- Ayotte, J.D., and Hammond, R.E., 1996, Level II scour analysis for Bridge 37 (BARTUS00050166) on U.S. Route 5, crossing Barton River, Barton, Vermont: U.S. Geological Survey Open-File Report 96-746, 49 p.

- Ayotte, J.D., and Ivanoff, M.A., 1996, Level II scour analysis for Bridge 96 (BLOOVT01050096) on Vermont Route 105, crossing Nulhegan River, Bloomfield, Vermont: U.S. Geological Survey Open-File Report 96-566, 47 p.
- Ayotte, J.D., and Medalie, Laura, 1996, Level II scour analysis for Bridge 1 (BLOOTH00020001) on Town Highway 2, crossing Mill Brook, Bloomfield, Vermont: U.S. Geological Survey Open-File Report 96-408, 50 p.
- Ayotte, J.D., and Olson, S.A., 1996, Level II scour analysis for Bridge 57 (BRIDTH00650057) on Town Highway 65, crossing Broad Brook, Bridgewater, Vermont: U.S. Geological Survey Open-File Report 96-232, 50 p.
- Ayotte, J.D., and Robinson, K.W., 1997, National Water-Quality Assessment Program, New England Coastal Basins: U.S. Geological Survey Fact Sheet FS-060-97, 4 p.
- Ayotte, J.D., and Song, D.L., 1996, Level II scour analysis for Bridge 42 (BETHTH00860042) on Town Highway 86, crossing Gilead Brook, Bethel, Vermont: U.S. Geological Survey Open-File Report 96-310, 50 p.
- Boehmler, E.M., 1996a, Level II scour analysis for Bridge 1 (CANATH00010001) on Town Highway 1, crossing Halls Stream, Canaan, Vermont: U.S. Geological Survey Open-File Report 96-640, 54 p.
- 1996b, Level II scour analysis for Bridge 4 (CRAFTH00040004) on Town Highway 4, crossing Whitney Brook, Craftsbury, Vermont: U.S. Geological Survey Open-File Report 96-402, 48 p.
- 1996c, Level II scour analysis for Bridge 4 (MNTGTH00020004) on Town Highway 2, crossing Wade Brook, Montgomery, Vermont: U.S. Geological Survey Open-File Report 96-561, 49 p.
- 1996d, Level II scour analysis for Bridge 8 (BARTTH00020008) on Town Highway 2, crossing Roaring Brook, Barton, Vermont: U.S. Geological Survey Open-File Report 96-404, 49 p.
- 1996e, Level II scour analysis for Bridge 8 (HANCTH00020008) on Town Highway 2, crossing Hancock Branch White River, Hancock, Vermont: U.S. Geological Survey Open-File Report 96-235, 50 p.
- 1996f, Level II scour analysis for Bridge 13 (IRAVT013300133) on State Route 133, crossing an Ira Brook Tributary, Ira, Vermont: U.S. Geological Survey Open-File Report 96-749, 48 p.
- 1996g, Level II scour analysis for Bridge 25 (ALBATH00250030) on Town Highway 25, crossing the Black River, Albany, Vermont: U.S. Geological Survey Open-File Report 96-194, 49 p.
- 1996h, Level II scour analysis for Bridge 25 (CRAFTH00220025) on Town Highway 22, crossing the Wild Branch Lamoille River, Craftsbury, Vermont: U.S. Geological Survey Open-File Report 96-312, 51 p.
- 1996i, Level II scour analysis for Bridge 26 (BRIDTH00340026) on Town Highway 034, crossing Ottauquechee River, Bridgewater, Vermont: U.S. Geological Survey Open-File Report 96-157, 52 p.

- 1996j, Level II scour analysis for Bridge 28 (MNTGTH00190028) on Town Highway 19, crossing Wade Brook, Montgomery, Vermont: U.S. Geological Survey Open-File Report 96-562, 50 p.
- 1996k, Level II scour analysis for Bridge 29 (CRAFTH00550029) on Town Highway 55, crossing the Black River, Craftsbury, Vermont: U.S. Geological Survey Open-File Report 96-386, 48 p.
- 1996l, Level II scour analysis for Bridge 31 (ALBATH00380031) on Town Highway 38, crossing the Black River, Albany, Vermont: U.S. Geological Survey Open-File Report 96-196, 49 p.
- 1996m, Level II scour analysis for Bridge 31 (BRNATH00470031) on Town Highway 47, crossing Locust Creek, Barnard, Vermont: U.S. Geological Survey Open-File Report 96-384, 47 p.
- 1996n, Level II scour analysis for Bridge 32 (BRNATH00470032) on Town Highway 47, crossing Locust Creek, Barnard, Vermont: U.S. Geological Survey Open-File Report 96-409, 47 p.
- 1996o, Level II scour analysis for Bridge 40 (BETHTH00230040) on Town Highway 23, crossing Gilead Brook, Bethel, Vermont: U.S. Geological Survey Open-File Report 96-198, 51 p.
- 1996p, Level II scour analysis for Bridge 45b (BRIDTH00040045b) on Town Highway 4, crossing an unnamed Dailey Hollow Branch Tributary, Bridgewater, Vermont: U.S. Geological Survey Open-File Report 96-568, 47 p.
- 1997a, Level II scour analysis for Bridge 6 (MORRTH00030006) on Town Highway 3, crossing Ryder Brook, Morristown, Vermont: U.S. Geological Survey Open-File Report 97-105, 49 p.
- 1997b, Level II scour analysis for Bridge 11R (ROCKTH0001011R) on Town Highway 1 (VT 121 & FAS 125), crossing the Saxtons River, Rockingham, Vermont: U.S. Geological Survey Open-File Report 97-345, 49 p.
- 1997c, Level II scour analysis for Bridge 20 (BRISTH00270020) on Town Highway 27, crossing Little Notch Brook, Bristol, Vermont: U.S. Geological Survey Open-File Report 97-756, 49 p.
- 1997d, Level II scour analysis for Bridge 23 (CRAFTH00390023) on Town Highway 39, crossing the Black River, Craftsbury, Vermont: U.S. Geological Survey Open-File Report 97-217, 52 p.
- 1997e, Level II scour analysis for Bridge 27 (BRIGVT001140027) on State Route 114, crossing Pherrins River, Brighton, Vermont: U.S. Geological Survey Open-File Report 97-207, 49 p.

- 1997f, Level II scour analysis for Bridge 53 (WILMVT01000053) on State Route 100, crossing Cold Brook, Wilmington, Vermont: U.S Geological Survey Open-File Report 97-343, 49 p.
  - 1998a, Level II scour analysis for Bridge 2 (RTLCCYRIVR0002) on River Street, crossing Otter Creek, Rutland City, Vermont: U.S. Geological Survey Open-File Report 98-568, 56 p.
  - 1998b, Level II scour analysis for Bridge 8 (SALITH00010008) on Town Highway 1, crossing Otter Creek, Salisbury, Vermont: U.S. Geological Survey Open-File Report 98-536, 51 p.
  - 1998c, Level II scour analysis for Bridge 8 (TROYTH00120008) on Town Highway 12, crossing the Missisquoi River, Troy, Vermont: U.S. Geological Survey Open-File Report 98-016, 48 p.
  - 1998d, Level II scour analysis for Bridge 9 (LOWETH00020009) on Town Highway 2, crossing the East Branch Missisquoi River, Lowell, Vermont: U.S. Geological Survey Open-File Report 98-291, 50 p.
  - 1998e, Level II scour analysis for Bridge 11 (BAKETH00030011) on Town Highway 3, crossing "The Branch", Bakersfield, Vermont: U.S. Geological Survey Open-File Report 98-014, 47 p.
  - 1998f, Level II scour analysis for Bridge 15 (WRUTTH00060015) on Town Highway 6, crossing the Castleton River, West Rutland, Vermont: U.S. Geological Survey Open-File Report 98-154, 51 p.
  - 1998g, Level II scour analysis for Bridge 48 (ENOSTH00020048) on Town Highway 2, crossing the Tyler Branch Missisquoi River, Enosburg, Vermont: U.S. Geological Survey Open-File Report 98-377, 50 p., 8 figs.
- Boehmler, E.M., and Degnan, J.R., 1996a, Level II scour analysis for Bridge 41 (BAKEVT01080041) on State Route 108 crossing The Branch, Bakersfield, Vermont: U.S. Geological Survey Open-File Report 96-643, 48 p.
- 1996b, Level II scour analysis for Bridge 94 (FERDVT01050094) on State Route 105, crossing the Nulhegan River, Ferdinand, Vermont: U.S. Geological Survey Open-File Report 96-586, 48 p.
- Boehmler, E.M., and Burns, R.L., 1997a, Level II scour analysis for Bridge 6 (BRISVT01160006) on State Highway 116, crossing Little Notch Brook, Bristol, Vermont: U.S. Geological Survey Open-File Report 97-4, 53 p.
- 1997b, Level II scour analysis for Bridge 8 (ATHETH00090008) on Town Highway 9, crossing Bull Creek, Athens, Vermont: U.S. Geological Survey Open-File Report 97-818, 50 p.
  - 1997c, Level II scour analysis for Bridge 20 (GRAFTH00010020) on Town Highway 1, crossing the Saxtons River, Grafton Vermont: U.S. Geological Survey Open-File Report 97-375, 50 p.
  - 1997d, Level II scour analysis for Bridge 22 (REDSVT01000022) on State Route 100, crossing the West Branch Deerfield River, Readsboro, Vermont: U.S. Geological Survey Open-File Report 97-191, 49 p.

- 1997e, Level II scour analysis for Bridge 137 (FERRUS00070137) on U.S. Route 7, crossing Little Otter Creek, Ferrisburg, Vermont: U.S. Geological Survey Open-File Report 97-189, 49 p.
- Boehmler, E.M., and Degnan, J.R., 1997a, Level II scour analysis for Bridge 5 (MORRTH00060005) on Town Highway 6, crossing Bedell Brook, Morristown, Vermont: U.S. Geological Survey Open-File Report 97-793, 47 p.
- 1997b, Level II scour analysis for Bridge 12 (FFIETH00030012) on Town Highway 3, crossing the Fairfield River, Fairfield, Vermont: U.S. Geological Survey Open-File Report 97-108, 52 p.
- 1997c, Level II scour analysis for Bridge 21 (MIDBTH00230021) on Town Highway 23, crossing the Middlebury River, Middlebury, Vermont: U.S. Geological Survey Open-File Report 97-754, 49 p.
- 1997d, Level II scour analysis for Bridge 39 (LOWETH00080039) on Town Highway 8, crossing Potter Brook, Lowell, Vermont: U.S. Geological Survey Open-File Report 97-629, 50 p.
- 1997e, Level II scour analysis for Bridge 41 (ROCKTH00390041) on Town Highway 39, crossing the Saxtons River, Rockingham, Vermont: U.S. Geological Survey Open-File Report 97-377, 49 p.
- 1998a, Level II scour analysis for Bridge 11 (BELVTH00080011) on Town Highway 8, crossing the North Branch Lamoille River, Belvidere, Vermont: U.S. Geological Survey Open-File Report 98-278, 49 p.
- 1998b, Level II scour analysis for Bridge 35 (BURKTH00310035) on Town Highway 31, crossing the West Branch Passumpsic River, Burke, Vermont: U.S. Geological Survey Open-File Report 98-586, 51 p.
- 1998c, Level II scour analysis for Bridge 42 (BAKETH00060042) on Town Highway 6, crossing "The Branch", Bakersfield, Vermont: U.S. Geological Survey Open-File Report 98-585, 51 p.
- Boehmler, E.M., and Flynn, R.H., 1997, Level II scour analysis for Bridge 125 (MIDBUS00070125) on U.S. Route 7 crossing the Middlebury River, Middlebury, Vermont: U.S. Geological Survey Open-File Report 97-103, 49 p.
- 1998a, Level II scour analysis for Bridge 28 (WORCTH00200028) on Town Highway 20, crossing Minister Brook, Worcester, Vermont: U.S. Geological Survey Open-File Report 98-526, 51 p.
- 1998b, Level II scour analysis for Bridge 29 (FERRTH00260029) on Town Highway 26, crossing Little Otter Creek, Ferrisburgh, Vermont: U.S. Geological Survey Open-File Report 98-022, 49 p.

- Boehmler, E.M., and Hammond, R.E., 1997a, Level II scour analysis for Bridge 2 (STAMVT01000002) on State Route 100 crossing Roaring Brook, Stamford, Vermont: U.S. Geological Survey Open-File Report 97-211, 47 p.
- 1997b, Level II scour analysis for Bridge 7 (MORRTH00020007) on Town Highway 2 (FAS 239), crossing Ryder Brook, Morristown, Vermont: U.S. Geological Survey Open-File Report 97-190, 47 p.
- 1997c, Level II scour analysis for Bridge 17 (POMFTH00010017) on Town Highway 1 (FAS 166) crossing Mill Brook, Pomfret, Vermont: U.S. Geological Survey Open-File Report 97-2, 50 p.
- 1997d, Level II scour analysis for Bridge 19 (CHARTH00390019) on Town Highway 39, crossing Mad Brook, Charleston, Vermont: U.S. Geological Survey Open File Report 97-212, 48 p.
- 1998, Level II scour analysis for Bridge 10 (GRAFTH00020010) on Town Highway 2 (FAS 126 and State Route 121), crossing the Saxtons River, Grafton, Vermont: U.S. Geological Survey Open-File Report 98-538, 51 p.
- Boehmler, E.M., and Ivanoff, M.A., 1996a, Level II scour analysis for Bridge 7 (BERKTH00030007) on Town Highway 3, crossing the Pike River, Berkshire, Vermont: U.S. Geological Survey Open-File Report 96-645, 48 p.
- 1996b, Level II scour analysis for Bridge 36 (RICHVT01050036) on State Route 105, crossing Stanhope Brook, Richford, Vermont: U.S. Geological Survey Open-File Report 96-584, 48 p.
- 1996c, Level II scour analysis for Bridge 59 (NWPCVT01050059) on State Route 105 crossing an unnamed Mud Creek Tributary, Newport, Vermont: U.S. Geological Survey Open-File Report 96-748, 49 p.
- 1997a, Level II scour analysis for Bridge 29 (PUTNTH00210029) on Town Highway 21, crossing East Putney Brook, Putney, Vermont: U.S. Geological Survey Open-File Report 97-406, 50 p.
- 1997b, Level II scour analysis for Bridge 32 (NFIEVT012A0032) on State Route 12A, crossing the Dog River, Northfield, Vermont: U.S. Geological Survey Open-File Report 97-188, 51 p.
- 1998, Level II scour analysis for Bridge 33 (PFRDTH00230033) on Town Highway 23, crossing Otter Creek, Pittsford, Vermont: U.S. Geological Survey Open-File Report 98-557, 52 p.
- Boehmler, E.M., and Medalie, Laura, 1996, Level II scour analysis for Bridge 46 (ENOSVT01080046) on State Route 108, crossing an Unnamed "The Branch" Tributary, Enosburg, Vermont: U.S. Geological Survey Open-File Report 96-585, 48 p.
- 1997, Level II scour analysis for Bridge 21 (MONKTH00340021) on Town Highway 34, crossing Little Otter Creek, Monkton, Vermont: U.S. Geological Survey Open-File Report 97-672, 48 p.
- 1998a, Level II scour analysis for Bridge 7 (SALITH00080007) on Town Highway 8, crossing the Middlebury River, Salisbury, Vermont: U.S. Geological Survey Open-File Report 98-257, 51 p.

- 1998b, Level II scour analysis for Bridge 13 (JAY-TH00230013) on Town Highway 23, crossing the Jay Branch of the Missisquoi River, Jay, Vermont: U.S. Geological Survey Open-File Report 98-059, 46 p.
- 1998c, Level II scour analysis for Bridge 71 (STOWTH0CEM0071) on Cemetery Road, crossing the Little River, Stowe, Vermont: U.S. Geological Survey Open-File Report 98-569, 51 p.
- Boehmler, E.M., and Severance, Timothy, 1997, Level II scour analysis for Bridge 120 (LEICUS00070120) on U.S. Route 7, crossing the Leicester River, Leicester, Vermont: U.S. Geological Survey Open-File Report 97-3, 50 p.
- 1998a, Level II scour analysis for Bridge 15 (BURKTH00580015) on Town Highway 58, crossing the West Branch Passumpsic River, Burke, Vermont: U.S. Geological Survey Open-File Report 98-380, 50 p.
- 1998b, Level II scour analysis for Bridge 33 (CASTTH0050033) on Town Highway 5, crossing the Castleton River, Castleton, Vermont: U.S. Geological Survey Open-File Report 98-542, 50 p.
- Boehmler, E.M., and Striker, L.K., 1998, Level II scour analysis for Bridge 37 (ANDOVT00110037) on State Route 11, crossing the Middle Branch Williams River, Andover, Vermont: U.S. Geological Survey Open-File Report 98-417, 50 p.
- Boehmler, E.M., and Song, D.L., 1996, Level II scour analysis for Bridge 5 (IRASTH00010005) on Town Highway 1, crossing Lords Creek, Irasburg, Vermont: U.S. Geological Survey Open-File Report 96-571, 49 p.
- 1997, Level II scour analysis for Bridge 30 (BRNATH00470030) on Town Highway 47, crossing Locust Creek, Barnard, Vermont: U.S. Geological Survey Open-File Report 97-210, 49 p.
- Boehmler, E.M., and Weber, M.A., 1997, Level II scour analysis for Bridge 7 (CHARTH00010007) on Town Highway 1, crossing Mad Brook, Charleston, Vermont: U.S. Geological Survey Open File Report 97-213, 50 p.
- Boehmler, E.M., and Wild, E.C., 1997, Level II scour analysis for Bridge 144 (ROCHVT01000144) on State Route 100, crossing the White River, Rochester, Vermont: U.S. Geological Survey Open-File Report 97-7, 51 p.
- 1998, Level II scour analysis for Bridge 34 (WWINTH00370034) on Town Highway 37, crossing Mill Brook, West Windsor, Vermont: U.S. Geological Survey Open-File Report 98-570, 50 p.
- Burns, R.L., 1997a, Level II scour analysis for Bridge 7 (CHESTH00030007) on Town Highway 3, crossing the South Branch Williams River, Chester, Vermont: U.S. Geological Survey Open-File Report 97-362, 48 p.

- 1997b, Level II scour analysis for Bridge 12 (HUNTTH00010012) on Town Highway 001, crossing Brush Brook, Huntington, Vermont: U.S. Geological Survey Open-File Report 97-226, 47 p.
- 1997c, Level II scour analysis for Bridge 16 (RIPTTH00110016) on Town Highway 11, crossing the Middle Branch Middlebury River, Ripton, Vermont: U.S. Geological Survey Open-File Report 97-751, 47 p.
- 1997d, Level II scour analysis for Bridge 25 (JAMATH00010025) on Town Highway 1, crossing Ball Mountain Brook, Jamaica, Vermont: U.S. Geological Survey Open-File Report 97-376, 47 p.
- 1997e, Level II scour analysis for Bridge 26 (JAMATH00010026) on Town Highway 1, crossing Ball Mountain Brook, Jamaica, Vermont: U.S. Geological Survey Open-File Report 97-395, 50 p.
- 1997f, Level II scour analysis for Bridge 27 (ANDOTH00290027) on Town Highway 29, crossing Middle Branch Williams River, Andover, Vermont: U.S. Geological Survey Open-File Report 97-225, 49 p.
- 1997g, Level II scour analysis for Bridge 30, (HUNTTH00220030), on Town Highway 22, crossing Brush Brook, Huntington, Vermont: U.S. Geological Survey Open-File Report 97-816, 47 p.
- 1997h, Level II scour analysis for Bridge 32 (HUNTTH00220032) on Town Highway 22, crossing Brush Brook, Huntington, Vermont: U.S. Geological Survey Open-File Report 97-651, 47 p.
- 1997i, Level II scour analysis for Bridge 33 (CONCTH00580033) on Town Highway 58, crossing Miles Stream, Concord, Vermont: U.S. Geological Survey Open-File Report 97-650, 50 p.
- 1997j, Level II scour analysis for Bridge 39 (ANDOVT00110039) on State Route 11, crossing the Middle Branch Williams River, Andover, Vermont: U.S. Geological Survey Open-File Report 97-373, 50 p.
- 1997k, Level II scour analysis for Bridge 68 (NFIETH00960068) on Town Highway 96, crossing the Dog River, Northfield, Vermont: U.S. Geological Survey Open-File Report 97-590, 50 p.
- 1998a, Level II scour analysis for Bridge 12 (NEWBTH00020012) on Town Highway 2, crossing Scott Brook, Newbury, Vermont: U.S. Geological Survey Open-File Report 98-011, 50 p.
- 1998b, Level II scour analysis for Bridge 18 (BRATTH00480018) on Town Highway 48, crossing Whetstone Brook, Brattleboro, Vermont: U.S. Geological Survey Open-File Report 98-053, p.50
- 1998c, Level II scour analysis for Bridge 2 I (SOMMTH00010002) on Town Highway 1, crossing the Rake Branch Deerfield River, Somerset, Vermont: U.S. Geological Survey Open-File Report 98-535, 50 p.
- 1998d, Level II scour analysis for Bridge 23 (WNDSTH0070023) on Town Highway 7, crossing Mill Brook, Windsor, Vermont: U.S. Geological Survey Open-File Report 98-079, 47 p.
- 1998e, Level II scour analysis for Bridge 57 (NEWFTH00690057) on Town Highway 69, crossing Hunter Brook, Newfane, Vermont: U.S. Geological Survey Open-File Report 98-193, 49 p.



- Burns, R.L., and Boehmler, E.M., 1997a, Level II scour analysis for Bridge 3 (EASTTH00010003) on Town Highway 1, crossing the East Branch Passumpsic River, East Haven, Vermont: U.S. Geological Survey Open-File Report 97-759, 47 p.
- 1997b, Level II scour analysis for Bridge 17 (BURKTH00070017) on Town Highway 7, crossing Dish Mill Brook, Burke, Vermont: U.S. Geological Survey Open-File Report 97-757, 50 p.
- 1997c, Level II scour analysis for Bridge 50 (STARTH00250050) on Town Highway 25, crossing Lewis Creek, Starksboro, Vermont: U.S. Geological Survey Open-File Report 97-798, 50 p.
- 1998a, Level II scour analysis for Bridge 7 (BRATTH00120007) on Town Highway 12, crossing Halladay Brook, Brattleboro, Vermont: U.S. Geological Survey Open-File Report 98-074, 50 p.
- 1998b, Level II scour analysis for Bridge 14 (WRUTTH00170014) on Town Highway 17, crossing the Clarendon River, West Rutland, Vermont: U.S. Geological Survey Open-File Report 98-420, 51 p.
- 1998c, Level II scour analysis for Bridge 28 (NEWBTH00840028) on Town Highway 84, crossing Halls Brook Newbury, Vermont: U.S. Geological Survey Open-File Report 98-551, 54 p.
- 1998d, Level II scour analysis for Bridge 32 (SHRETH00060032) on Town Highway 6, crossing Saragent Brook, Shrewsbury, Vermont: U.S. Geological Survey Open-File Report 98-299, 47 p.
- Burns, R.L., and Degnan, J.R., 1997a, Level II scour analysis for Bridge 16, (NEWBTH00500016) on Town Highway 50, crossing Halls Brook, Newbury, Vermont: U.S. Geological Survey Open-File Report 97-814, 50 p.
- 1997b, Level II scour analysis for Bridge 33 (HUNTTH00220033) on Town Highway 22, crossing Brush Brook, Huntington, Vermont: U.S. Geological Survey Open-File Report 97-664, 50 p.
- 1997c, Level II scour analysis for Bridge 39 (PEACTH00620039) on Town Highway 62, crossing South Peacham Brook, Peacham, Vermont: U.S. Geological Survey Open-File Report 97-775, 50 p.
- 1998a, Level II scour analysis for Bridge 2 (WODFTH00010002) on Town Highway 1, crossing Hell Hollow Brook, Woodford, Vermont: U.S. Geological Survey Open-File Report 98-584, 48 p.
- 1998b, Level II scour analysis for Bridge 13 (JERITH00030013) on Town Highway 3, crossing Mill Brook, Jericho, Vermont: U.S. Geological Survey Open-File Report 98-259, 50 p.

- 1998c, Level II scour analysis for Bridge 55, (WILMTH00230055) on Town Highway 23, crossing Beaver Brook, Wilmington, Vermont: U.S. Geological Survey Open-File Report 98-007, 47 p.
- 1998d, Level II scour analysis for Bridge 59 (STRATH00030059) on Town Highway 3, crossing Abbott Brook, Strafford, Vermont: U.S. Geological Survey Open-File Report 98-261, 50 p.
- 1998e, Level II scour analysis for Bridge 75 (CHESTH00170075) on Town Highway 17, crossing the Williams River, Chester, Vermont: U.S. Geological Survey Open-File Report 98-416, 53 p.
- Burns, R.L., and Flynn, R.H., 1998a, Level II scour analysis for Bridge 2, (WHITTH00020002) on Town Highway 2, crossing the South Branch Deerfield River, Whitingham, Vermont: U.S. Geological Survey Open-File Report 98-008, 47 p.
- 1998b, Level II scour analysis for Bridge 13 (MNTPTH00CU0013) on Cummings Street, crossing the North Branch Winooski River, Montpelier, Vermont: U.S. Geological Survey Open-File Report 98-550, 48 p.
- Burns, R.L., and Hammond, R.E., 1997a, Level II scour analysis for Bridge 8, (MANCTH00060008) on Town Highway 6, crossing Bourn Brook, Manchester, Vermont: U.S. Geological Survey Open-File Report 97-813, 50 p.
- 1997b, Level II scour analysis for Bridge 34 (CONCTH00110034) on Town Highway 11, crossing Miles Stream, Concord, Vermont: U.S. Geological Survey Open-File Report 97-776, 50 p.
- Burns, R.L., and Ivanoff, M.A., 1997a, Level II scour analysis for Bridge 34 (HUNTTH00210034) on Town Highway 21, crossing Brush Brook, Huntington, Vermont: U.S. Geological Survey Open-File Report 97-663, 52 p.
- 1997b, Level II scour analysis for Bridge 45 (NFIETH00250045) on Town Highway 25, crossing Union Brook, Northfield, Vermont: U.S. Geological Survey Open-File Report 97-407, 49 p.
- Burns, R.L., and Medalie, Laura, 1997a, Level II scour analysis for Bridge 17 (RIPTTH00180017) on Town Highway 18, crossing the South Branch Middlebury River, Ripton, Vermont: U.S. Geological Survey Open-File Report 97-658, 47 p.
- 1997b, Level II scour analysis for Bridge 81 (NFIETH00PL0081) on Pleasant Street, crossing Union Brook, Northfield, Vermont: U.S. Geological Survey Open-File Report 97-404, 50 p.
- 1998a, Level II scour analysis for Bridge 37 (TOWNTH00290037) on Town Highway 29, crossing Mill Brook, Townshend, Vermont: U.S. Geological Survey Open-File Report 98-152, 50 p.
- 1998b, Level II scour analysis for Bridge 53 (NEWBTH00750053) on Town Highway 75, crossing Harriman Brook, Newbury, Vermont: U.S. Geological Survey Open-File Report 98-262, 48 p.
- 1998c, Level II scour analysis for Bridge 58 (SPRITH00060058) on Town Highway 6, crossing Baltimore Brook, Springfield, Vermont: U.S. Geological Survey Open-File Report 98-056, 47 p.

- Burns, R.L., and Olson, S.A., 1998a, Level II scour analysis for Bridge 20 (SHELTH00220020) on Town Highway 22, crossing Black Creek, Sheldon, Vermont: U.S. Geological Survey Open-File Report 98-422, 50 p.
- 1998b, Level II scour analysis for Bridge 20 (WALDTH00050020) on Town Highway 5, crossing Stanard Brook, Walden, Vermont: U.S. Geological Survey Open-File Report 98-541, 54 p.
- Burns, R.L., and Severance, Timothy, 1997a, Level II scour analysis for Bridge 16 (BURKTH00070016) on Town Highway 7, crossing Dish Mill Brook, Burke, Vermont: U.S. Geological Survey Open-File Report 97-758, 50 p.
- 1997b, Level II analysis for Bridge 37, (BRNETH00740037) on Town Highway 74, crossing South Peacham Brook, Barnet, Vermont: U.S. Geological Survey Open-File Report 97-815, 50 p.
- 1997c, Level II scour analysis for Bridge 65 (NEWBTH00500065) on Town Highway 50, crossing Peach Brook, Newbury, Vermont: U.S. Geological Survey Open-File Report 97-804, 50 p.
- 1998a, Level II scour analysis for Bridge 15, (SHRETH00300015) on Town Highway 30, crossing Freeman Brook, Shrewsbury, Vermont: U.S. Geological Survey Open-File Report 98-192, 48 p.
- 1998b, Level II scour analysis for Bridge 28 (SHERTH00380028) on Town Highway 38, crossing the Ottauquechee River, Sherburne, Vermont: U.S. Geological Survey Open-File Report 98-260, 50 p.
- Burns, R.L., and Weber, M.A., 1997a, Level II scour analysis for Bridge 25 (ROYATH00550025) on Town Highway 55, crossing Broad Brook, Royalton, Vermont: U.S. Geological Survey Open-File Report 97-422, 50 p.
- 1997b, Level II scour analysis for Bridge 26 (ROYATH00540026) on Town Highway 54, crossing Broad Brook, Royalton, Vermont: U.S. Geological Survey Open-File Report 97-579, 50 p.
- Burns, R.L., and Weber, M.A., 1998a, Level II scour analysis for Bridge 13 (BRAITH00150013) on Town Highway 15, crossing the Third Branch White River, Braintree, Vermont: U.S. Geological Survey Open-File Report 98-390, 50 p.
- 1998b, Level II scour analysis for Bridge 14 (SHARTH00040014) on Town Highway 4, crossing Broad Brook, Sharon, Vermont: U.S. Geological Survey Open-File Report 98-162, 50 p.
- 1998c, Level II scour analysis for Bridge 29 (READTH00510029) on Town Highway 51, crossing Mill Brook, Reading, Vermont: U.S. Geological Survey Open-File Report 98-402, 51 p.

- Burns, R.L., and Wild, E.C., 1997, Level II scour analysis for Bridge 44 (LINCTH00330044) on Town Highway 33, crossing the New Haven River, Lincoln, Vermont: U.S. Geological Survey Open-File Report 97-659, 50 p.
- \_\_\_\_\_ 1998a, Level II scour analysis for Bridge 15 (BOLTTH00150015) on Town Highway 15, crossing Joiner Brook, Bolton, Vermont: U.S. Geological Survey Open-File Report 98-425, 55 p.
- \_\_\_\_\_ 1998b, Level II scour analysis for Bridge 30 (NEWHTH00050030) on Town Highway 5, crossing the New Haven River, New Haven, Vermont: U.S. Geological Survey Open-File Report 98-058, 49 p.
- \_\_\_\_\_ 1998c, Level II scour analysis for Bridge 35, (ANDOVT00110035) on State Route 11, crossing the Middle Branch Williams River, Andover, Vermont: U.S. Geological Survey Open-File Report 98-87, 50 p.
- \_\_\_\_\_ 1998d, Level II scour analysis for Bridge 40 (ROCKTH00140040) on Town Highway 14, crossing the Williams River, Rockingham, Vermont: U.S. Geological Survey Open-File Report 98-543, 55 p.
- Degnan, J.R., 1997, Level II scour analysis for Bridge 31 (BRISTH00030031) on Town Highway 3, crossing the New Haven River, Bristol, Vermont: U.S. Geological Survey Open-File Report 97-628, 47 p.
- \_\_\_\_\_ 1998a, Level II scour analysis for Bridge 24 (BERLTH00600024) on Town Highway 60, crossing Cox Brook, Berlin, Vermont: U.S. Geological Survey Open-File Report 98-057, 50 p.
- \_\_\_\_\_ 1998b, Level II scour analysis for Bridge 29 (JAMATH00300029) on Town Highway 30, crossing Ball Mountain, Jamaica, Vermont: U.S. Geological Survey Open-File Report 98-88, 47 p.
- Flynn, R.H., 1997a, Level II scour analysis for Bridge 6 (STAMVT01000006) on State Route 100, crossing the North Branch of the Hoosic River, Stamford, Vermont: U.S. Geological Survey Open-File Report 97-216, 49 p.
- \_\_\_\_\_ 1997b, Level II scour analysis for Bridge 7 (ANDOTH00010007) on Town Highway 1, crossing Andover Brook, Andover, Vermont: U.S. Geological Survey Open-File Report 97-186, 50 p.
- \_\_\_\_\_ 1997c, Level II scour analysis for Bridge 29 (HUNTTH00290029) on Town Highway 29, crossing Cobb Brook, Huntington, Vermont: U.S. Geological Survey Open-File Report 97-652, 49 p.
- \_\_\_\_\_ 1997d, Level II scour analysis for Bridge 63 (CHESTH00090063) on Town Highway 9, crossing the Williams River, Chester, Vermont: U.S. Geological Survey, Open-File Report 97-423, 49 p.
- Flynn, R.H., and Boehmler, E.M., 1997a, Level II scour analysis for Bridge 4 (DANVTH00010004) on Town Highway 1, crossing Joes Brook, Danville, Vermont: U.S. Geological Survey Open-File Report 97-675, 47 p.
- \_\_\_\_\_ 1997b, Level II scour analysis for Bridge 23 (WEELTH00210023) on Town Highway 21, crossing Miller Run, Wheelock, Vermont: U.S. Geological Survey Open-File Report 97-795, 49 p.

- 1997c, Level II scour analysis for Bridge 48 (FFIETH00300048) on Town Highway 30, crossing Wanzer Brook, Fairfield, Vermont: U.S. Geological Survey Open-File Report 97-592, 48 p.
- Flynn, R.H., and Burns, R.L., 1997a, Level II scour analysis for Bridge 7 (WARRTH00010007) on Town Highway 1, crossing Freemans Brook, Warren, Vermont: U.S. Geological Survey Open-File Report 97-8, 50 p.
- 1997b, Level II scour analysis for Bridge 12 (CHESVT01030012) on State Highway 103, crossing the Williams River, Chester, Vermont: U.S. Geological Survey Open-File Report 97-364, 55 p.
- 1997c, Level II scour analysis for Bridge 25 (ANDOTH00230025) on Town Highway 23, crossing Andover Branch, Andover, Vermont: U.S. Geological Survey Open-File Report 97-372, 47 p.
- 1997d, Level II scour analysis for Bridge 25 (REDSTH00360025) on Town Highway 36, crossing the West Branch Deerfield River, Readsboro, Vermont: U.S. Geological Survey Open-File Report 97-653, 53 p.
- 1997e, Level II scour analysis for Bridge 92 (WSTOVT01000092) on State Highway 100, crossing the West River, Weston, Vermont: U.S. Geological Survey Open-File Report 97-1, 50 p.
- Flynn, R.H., and Burns, R.L., 1998, Level II scour analysis for Bridge 20 (ADISTH00240020) on Town Highway 24, crossing East Branch Dead Creek, Addison, Vermont: U.S. Geological Survey Open-File Report 98-006, 47 p.
- Flynn, R.H., and Degnan, J.R., 1997, Level II scour analysis for Bridge 31 (HUNTTH00220031) on Town Highway 22, crossing Brush Brook, Huntington, Vermont: U.S. Geological Survey Open-File Report 97-673, 49 p.
- 1998, Level II scour analysis for Bridge 33 (BURKTH00130033) on Town Highway 13, crossing Roundy Brook, Burke, Vermont: U.S. Geological Survey Open-File Report 98-005, 49 p.
- Flynn, R.H., and Ivanoff, M.A., 1996, Level II scour analysis for Bridge 9 (JAYVT02420009) on Vermont Highway 242, crossing the Jay Branch of the Missisquoi River, Jay, Vermont: U.S. Geological Survey Open-File Report 96-750, 48 p.
- 1998, Level II scour analysis for Bridge 41 (BRNETH00990041) on Town Highway 99, crossing Stevens River, Barnet, Vermont: U.S. Geological Survey Open-File Report 98-540, 51 p.
- Flynn, R.H., and Medalie, Laura, 1997a, Level II scour analysis for Bridge 12 (SUNDFLR0030012) on Forest Land Road 3, crossing Roaring Branch Brook, Sunderland, Vermont: U.S. Geological Survey Open-File Report 97-185, 47 p.

- 1997b, Level II scour analysis for Bridge 13 (PFRDTH00030013) on Town Highway 3, crossing Furnace Brook, Pittsford, Vermont: U.S. Geological Survey Open-File Report 97-110, 49 p.
- 1997c, Level II scour analysis for Bridge 37 (CABOTH00410037) on Town Highway 41, crossing the Winooski River, Cabot, Vermont: U.S. Geological Survey Open-File Report 97-781, 51 p.
- Flynn, R.H., and Severance, Timothy, 1997a, Level II scour analysis for Bridge 25 (DANVTH00610025) on Town Highway 61, crossing Water Andric Brook, Danville, Vermont: U.S. Geological Survey Open-File Report 97-796, 49 p.
- 1997b, Level II scour analysis for Bridge 34 (SHERUS00040034) on U.S. Highway 4, crossing the Ottauquechee River, Sherburne, Vermont: U.S. Geological survey Open-File Report 97-9, 48 p.
- 1997c, Level II scour analysis for Bridge 49 (WALLVT01030049) on State Highway 103, crossing Freeman Brook, Wallingford, Vermont: U.S. Geological Survey Open-File Report 97-184, 50 p.
- Flynn, R.H., and Song, D.L., 1996, Level II scour analysis for Bridge 6 (RICHTH00030006) on Town Highway 3, crossing an unnamed tributary to the Missisquoi River, Richford, Vermont: U.S. Geological Survey Open-File Report 96-635, 50 p.
- 1997, Level II scour analysis for Bridge 12 (PFRDTH00020012) on Town Highway 2, crossing Otter Creek, Pittsford, Vermont: U.S. Geological Survey Open-File Report 97-10, 52 p.
- Flynn, R.H., and Wild, E.C., 1997, Level II scour analysis for Bridge 8 (ANDOTH00010008) on Town Highway 1, crossing Andover Branch, Andover, Vermont: U.S. Geological Survey Open-File Report 97-374, 48 p.
- Ivanoff, M.A., 1996a, Level II scour analysis for Bridge 5 (CHELTH00030005) on Town Highway 3, crossing Jenkins Brook, Chelsea, Vermont: U.S. Geological Survey Open-File Report 96-743, 50 p.
- 1996b, Level II scour analysis for Bridge 13 (POMFTH00020013) on Town Highway 2, crossing Barnard Brook, Pomfret, Vermont: U.S. Geological Survey Open-File Report 96-583, 50 p.
- 1996c, Level II scour analysis for Bridge 15 (GRNVTH00230015) on Town Highway 23, crossing the Third Branch of the White River, Granville, Vermont: U.S. Geological Survey Open-File Report 96-564, 50 p.
- 1996d, Level II scour analysis for Bridge 32 (BETHTH00380032) on Town Highway 038, crossing Camp Brook, Bethel, Vermont: U.S. Geological Survey Open-File Report 96-192, 47 p.
- 1996e, Level II scour analysis for Bridge 49 (BRIDTH00530049) on Town Highway 53, crossing North Branch Ottauquechee River, Bridgewater, Vermont: U.S. Geological Survey Open-File Report 96-407, 50 p.
- 1997a, Level II scour analysis for Bridge 2 (RYEGTH00020002) on Town Highway 2, crossing the Wells River, Ryegate, Vermont: U.S. Geological Survey Open-File Report 97-646, 48 p.

- 1997b, Level II scour analysis for Bridge 5 (DUMMVT00300005) on State Route 30, crossing Stickney Brook, Dummerston, Vermont: U.S. Geological Survey Open-File Report 97-627, 47 p.
- 1997c, Level II scour analysis for Bridge 5C (CORITH0003005C) on Town Highway 3, crossing Cooksville Brook, Corinth, Vermont: U.S. Geological Survey Open-File Report 97-111, 49 p.
- 1997d, Level II scour analysis for Bridge 8 (DANVTH00020008) on Town Highway 2, crossing the Morrill Brook, Danville, Vermont: U.S. Geological Survey Open-File Report 97-104, 47 p.
- 1997e, Level II scour analysis for Bridge 8 (STAMVT01000008) on State Highway 100, crossing the North Branch of the Hoosic River, Stamford, Vermont: U.S. Geological Survey Open-File Report 97-215, 49 p.
- 1997f, Level II scour analysis for Bridge 13 (EDENTH00170013) on Town Highway 17, crossing the Gihon River, Eden, Vermont: U.S. Geological Survey Open-File Report 97-392, 50 p.
- 1997g, Level II scour analysis for Bridge 16 (TROYTH00290016) on Town Highway 29, crossing Beetle Brook, Troy, Vermont: U.S. Geological Survey Open-File Report 97-413, 50 p.
- 1997h, Level II scour analysis for Bridge 26 (PUTNTH00010026) on Town Highway 1, crossing Sacketts Brook, Putney, Vermont: U.S. Geological Survey Open-File Report 97-183, 49 p.
- 1997i, Level II scour analysis for Bridge 27 (STJOTH00080027) on Town Highway 8, crossing the Sleepers River, St. Johnsbury, Vermont: U.S. Geological Open-File Report 97-779, 50 p.
- 1997j, Level II scour analysis for Bridge 28 (CAMBTH00460028) on Town Highway 46, crossing the Seymour River, Cambridge, Vermont: U.S. Geological Survey Open-File Report 97-648,49 p.
- 1997k, Level II scour analysis for Bridge 34 (CORITH0050034) on Town Highway 50, crossing the South Branch Waits River, Corinth, Vermont: U.S. Geological Survey Open-File Report 97-671, 52 p.
- 1997l, Level II scour analysis for Bridge 46 (BRNETH00610046) on Town Highway 61, crossing East Peacham Brook, Barnet, Vermont: U.S. Geological Survey Open-File Report 97-766, 50 p.
- 1997m, Level II scour analysis for Bridge 80 (JAMAVT01000080) on State Highway 100, crossing the West River, Jamaica, Vermont: U.S. Geological Survey Open-File Report 97-214, 50 p.

- 1997n, Level II scour analysis for Bridge 81 (MARSUS00020081) on U.S. Highway 2, crossing the Winooski River, Marshfield, Vermont: U.S. Geological Survey Open-File Report 97-809, 50 p.
- 1997o, Level II scour analysis for Bridge 86 (VERNVT01420086) on State Route 142, crossing Broad Brook, Vernon, Vermont: U.S. Geological Survey Open-File Report 97-363, 53 p.
- 1997p, Level II scour analysis for Bridge 106 (NEWBUS00050106) on U.S. Highway 5, crossing the Wells River, Newbury, Vermont: U.S. Geological Survey Open-File Report 97-5, 50 p.
- 1997q, Level II scour analysis for Bridge 108 (STJOUS00020108) on U.S. Highway 2, crossing the Moose River, St. Johnsbury, Vermont: U.S. Geological Survey Open-File Report 97-107, 49 p.
- 1998a, Level II scour analysis for Bridge 26 (WRUTTH00050026) on Town Highway 5, crossing the Clarendon River, West Rutland, Vermont: U.S. Geological Survey Open-File Report 98-071, 50 p.
- 1998b, Level II scour analysis for Bridge 50 (WALLTH00600050) on Town Highway 60, crossing Otter Creek, Wallingford, Vermont: U.S. Geological Survey Open-File Report 98-255, 50 p.
- 1998c, Level II scour analysis for Bridge 61 (MTHOTH00100061) on Town Highway 10, crossing Perry Brook, Mount Holly, Vermont: U.S. Geological Survey Open-File Report 98-054, 47 p.
- Ivanoff, M.A., and Boehmler, E.M., 1998a, Level II scour analysis for Bridge 5 (POULTH00040005) on Town Highway 4, crossing the Poultney River, Poultney, Vermont: U.S. Geological Survey Open-File Report 98-381, 50 p.
- 1998b, Level II scour analysis for Bridge 7 (WFAITH000300007) on Town Highway 3, crossing Algerine Brook, West Fairlee, Vermont: U.S. Geological Survey Open-File Report 98-405,
- 1998c, Level II scour analysis for Bridge 11 (VERSTH00380011) on Town Highway 38, crossing Algerine Brook, Vershire, Vermont: U.S. Geological Survey Open-File Report 98-254, 48 p.
- 1998d, Level II scour analysis for Bridge 31 (LUDLTH00460031) on Town Highway 46, crossing Jewell Brook, Ludlow, Vermont: U.S. Geological Survey Open-File Report 98-376, 50 p.
- 1998e, Level II scour analysis for Bridge 64 (MTHOTH00170064) on Town Highway 17, crossing an unnamed tributary of Mill River, Mount Holly, Vermont: U.S. Geological Survey Open-File Report 98-010, 50 p.
- Ivanoff, M.A., and Burns, R.L., 1997a, Level II scour analysis for Bridge 11 (HINETH00040011) on Town Highway 4, crossing Lewis Creek, Hinesburg, Vermont: U.S. Geological Survey Open-File Report 97-106, 47 p.



- 1997b, Level II scour analysis for Bridge 40 (ANDOVT00110040) on State Route 11, crossing Lyman Brook, Andover, Vermont: U.S. Geological Survey Open-File Report 97-594, 50 p.
- Ivanoff, M.A., and Degnan, J.R., 1997, Level II scour analysis for Bridge 11 (STAMVT01000011) on State Route 11, crossing Crazy John Stream, Stamford, Vermont: U.S. Geological Survey Open-File Report 97-824, 50 p.
- Ivanoff, M.A., and Hammond, R.E., 1996a, Level II scour analysis for Bridge 33 (BETHTH00310033) on Town Highway 031, crossing Lilliesville Brook, Bethel, Vermont: U.S. Geological Survey Open-File Report 96-191, 48 p.
- 1996b, Level II scour analysis for Bridge 145 (HANCVT01000145) on Vermont Highway 100, crossing the Hancock Branch of the White River, Hancock, Vermont: U.S. Geological Survey Open-File Report 96-747, 50 p.
- 1997a, Level II scour analysis for Bridge 4 (RYEGTH00050004) on Town Highway 5, crossing the Wells River, Ryegate, Vermont: U.S. Geological Survey Open-File Report 97-765, 48 p.
- 1997b, Level II scour analysis for Bridge 16 (CHESVT01030016) on State Route 103, crossing the Williams River, Chester, Vermont: U.S. Geological Survey Open-File Report 97-581, 52 p.
- 1997c, Level II scour analysis for Bridge 23 (WALDTH00060023) on Town Highway 6, crossing Stannard Brook, Walden, Vermont: U.S. Geological Survey Open-File Report 97-674, 50 p.
- 1997d, Level II scour analysis for Bridge 39 (STOWTH00160039) on Town Highway 16, crossing Moss Glen Brook, Stowe, Vermont: U.S. Geological Survey Open-File Report 97-794, 45 p.
- 1997e, Level II scour analysis for Bridge 44 (CHESVT00110044) on State Route 11, crossing Andover Brook, Chester, Vermont: U.S. Geological Survey Open-File Report 97-378, 50 p.
- 1997f, Level II scour analysis for Bridge 45 (BRNETH00070045) on Town Highway 7, crossing the Stevens River, Barnet, Vermont: U.S. Geological Survey Open-File Report 97-753, 50 p.
- 1997g, Level II scour analysis for Bridge 53 (CAMBTH00750053) on Town Highway 75, crossing the Brewster River, Cambridge, Vermont: U.S. Geological Survey Open-File Report 97-647, 50 p.
- 1997h, Level II scour analysis for Bridge 81 (JAMAVT01000081) on State Route 100, crossing the Winhall River, Jamaica, Vermont: U.S. Geological Survey Open-File Report 97-409, 50 p.

- \_\_\_\_\_ 1998a, Level II scour analysis for Bridge 25 (RYEGTH00500025) on Town Highway 50, crossing the Wells River, Ryegate, Vermont: U.S. Geological Survey Open-File Report 98-91, 48 p.
- \_\_\_\_\_1998b, Level II scour analysis for Bridge 30 (ROYATH00060030) on Town Highway 6, crossing thr White River, Royalton, Vermont: U.S. Geological Survey Open-File Report 98-264, 51 p.
- Ivanoff, M.A., and Medalie, Laura, 1997a, Level II scour analysis for Bridge 12 (NEWFVT00300012) on State Route 30, crossing Smith Brook, Newfane, Vermont: U.S. Geological Survey Open-File Report 97-424, 47 p.
- \_\_\_\_\_1997b, Level II scour analysis for Bridge 15 (TROYTH00290015) on Town Highway 29, crossing Beetle Brook, Troy, Vermont: U.S. Geological Survey Open-File Report 97-408, 50 p.
- \_\_\_\_\_1997c, Level II scour analysis for Bridge 21 (WALDTH00450021) on Town Highway 45, crossing Joes Brook, Walden, Vermont: U.S. Geological Survey Open-File Report 97-799, 51 p.
- \_\_\_\_\_1997d, Level II scour analysis for Bridge 30 (MNTGTH00410030) on Town Highway 41, crossing the Trout River, Montgomery, Vermont: U.S. Geological Survey Open-File Report 97-396, 50 p.
- \_\_\_\_\_1997e, Level II scour analysis for Bridge 30 (NEWFVT00300013) on Vermont Highway 30, crossing Smith Brook, Newfane, Vermont: U.S. Geological Survey Open-File Report 97-218, 47 p.
- \_\_\_\_\_1997f, Level II scour analysis for Bridge 43 (SPRICYBRIG0043) on Bridge Street, crossing the Black River, Springfield, Vermont: U.S. Geological Survey Open-File Report 97-227, 46 p.
- \_\_\_\_\_ 1998a, Level II scour analysis for Bridge 4 (PROCTH00060004) on Town Highway 6, crossing Otter Creek, Proctor, Vermont: U.S. Geological Survey Open-File Report 98-055, 49 p.
- \_\_\_\_\_1998b, Level II scour analysis for Bridge 5 (BRNETH00020005) on Town Highway 2, crossing East Peacham Brook, Barnet, Vermont: U.S. Geological Survey Open-File Report 98-263, 50 p.
- \_\_\_\_\_1998c, Level II scour analysis for Bridge 13 (CHESTH00060013) on Town Highway 6, crossing the Williams River, Chester, Vermont: U.S. Geological Survey Open-File Report 98-403, 50 p.
- \_\_\_\_\_1998d, Level II scour analysis for Bridge 34 (JAMATH00080034) on Town Highway 8, crossing the Winhall River, Jamaica, Vermont: U.S. Geological Survey Open-File Report 98-539, 51 p.
- Ivanoff, M.A., and Olson, S.A., 1996a, Level II scour analysis for Bridge 43 (BETHTH00070043) on Town Highway 07, crossing Gilead Brook, Bethel, Vermont: U.S. Geological Survey Open-File Report 96-307, 51 p.
- \_\_\_\_\_1996b, Level II scour analysis for Bridge 49 (BETHTH00790049) on Town Highway 79, crossing Locust Creek, Bethel, Vermont: U.S. Geological Survey Open-File Report 96-303, 51 p.
- Ivanoff, M.A., and Severance, Timothy, 1998a, Level II scour analysis for Bridge 23 (BRADTH00090023) on Town Highway 9, crossing Mill Pond Brook, Bradford, Vermont: U.S. Geological Survey Open-File Report 98-195, 50 p.

- 1998b, Level II scour analysis for Bridge 32 (SHERTH00470032) on Town Highway 47, crossing Roaring Brook, Sherburne, Vermont: U.S. Geological Survey Open-File Report 98-258, 48 p.
- Ivanoff, M.A., and Song, D.L., 1996a, Level II scour analysis for Bridge 38 (BETHTH00070038) on Town Highway 007, crossing Gilead Brook, Bethel, Vermont: U.S. Geological Survey Open-File Report 96-189, 51 p.
- 1996b, Level II scour analysis for Bridge 46 (CHELTH00680046) on Town Highway 68, crossing the First Branch of the White River, Chelsea, Vermont: U.S. Geological Survey Open-File Report 96-406, 50 p.
- 1997, Level II scour analysis for Bridge 22 (JAY-TH00400022) on Town Highway 40, crossing Jay Branch, Jay, Vermont: U.S. Geological Survey Open-File Report 97-591, 47 p.
- 1998a, Level II scour analysis for Bridge 22 (MENDTH00180022) on Town Highway 18, crossing the Cold River, Mendon, Vermont: U.S. Geological Survey Open-File Report 98-073, 50 p.
- 1998b, Level II scour analysis for Bridge 24 (CLARTH00160024) on Town Highway 16, crossing the Clarendon River, Clarendon, Vermont: U.S. Geological Survey Open-File Report 98-153, 50 p.
- Ivanoff, M.A., and Striker, L.K., 1998, Level II scour analysis for Bridge 25 (STOCTH00360025) on Town Highway 36, crossing Stony Brook, Stockbridge, Vermont: U.S. Geological Survey Open-File Report 98-197, 50 p.
- Ivanoff, M.A., and Weber, M.A., 1996a, Level II scour analysis for Bridge 16 (BRNATH00800016) on Town Highway 80, crossing Locust Creek, Barnard, Vermont: U.S. Geological Survey Open-File Report 96-383, 49 p.
- 1996b, Level II scour analysis for Bridge 25 (BRNATH00290034) on Town Highway 29, crossing Locust Creek, Barnard, Vermont: U.S. Geological Survey Open-File Report 96-642, 50 p.
- 1996c, Level II scour analysis for Bridge 25 (BRNAV00120025) on State Highway 12, crossing Locust Creek, Barnard, Vermont: U.S. Geological Survey Open-File Report 96-388, 48 p.
- 1996d, Level II scour analysis for Bridge 35 (BRNATH00680035) on Town Highway 68, crossing Locust Creek, Barnard, Vermont: U.S. Geological Survey Open-File Report 96-306, 50 p.
- 1996e, Level II scour analysis for Bridge 37 (BETHTH00070037) on Town Highway 007, crossing Gilead Brook, Bethel, Vermont: U.S. Geological Survey Open-File Report 92-233, 50 p.

- \_\_\_\_\_ 1997, Level II scour analysis for Bridge 13 (NORWTH00020013) on Town Highway 2, crossing Charles Brown Brook, Norwich, Vermont: U.S. Geological Survey Open-File Report 97-800, 50 p.
- Ivanoff, M.A., and Weber, M.A., 1998a, Level II analysis for Bridge 27 (READTH00380027) on Town Highway 38, crossing the North Branch Black River, Reading, Vermont: U.S. Geological Survey Open-File Report 98-379, 50 p.
- \_\_\_\_\_1998b, Level II scour analysis for Bridge 28 (READTH00540028) on Town Highway 54, crossing the North Branch Black River, Reading, Vermont: U.S. Geological Survey Open-File Report 98-292, 50 p.
- Ivanoff, M.A., and Wild, E.C., 1998, Level II scour analysis for Bridge 32 (FERRTH00190032) on Town Highway 19, crossing the South Slang Little Otter Creek, Ferrisburgh, Vermont: U.S. Geological Survey Open-File Report 98-025, 45 p.
- Olson, S.A., 1996a, Level II scour analysis for Bridge 6 (IRASTH00050006) on Town Highway 5, crossing the Black River, Irasburg, Vermont: U.S. Geological Survey Open-File Report 96-193, 48 p.
- \_\_\_\_\_1996b, Level II scour analysis for Bridge 12 (BRAITH00230012) on Town Highway 23, crossing Ayers Brook, Braintree, Vermont: U.S. Geological Survey Open-File Report 96-390, 50 p.
- \_\_\_\_\_1996c, Level II scour analysis for Bridge 14 (CLARTH00010014) on Town Highway 1, crossing Cold River, Clarendon, Vermont: U.S. Geological Survey Open-File Report 96-389, 56 p.
- \_\_\_\_\_1996d, Level II scour analysis for Bridge 14 (FFIETH00010014) on Town Highway 1, crossing the Fairfield River, Fairfield, Vermont: U.S. Geological Survey Open-File Report 96-742, 50 p.
- \_\_\_\_\_1996e, Level II scour analysis for Bridge 15 (BRIDTH00220015) on Town Highway 22, crossing Dailey Hollow Branch, Bridgewater, Vermont: U.S. Geological Survey Open-File Report 96-403, 48 p.
- \_\_\_\_\_1996f, Level II scour analysis for Bridge 20 (IRASTH00080020) on Town Highway 8, crossing the Black River, Irasburg, Vermont: U.S. Geological Survey Open-File Report 96-154, 51 p.
- \_\_\_\_\_1996g, Level II scour analysis for Bridge 22 (WODSTH00180022) on Town Highway 18, crossing north Bridgewater Brook, Woodstock, Vermont: U.S. Geological Survey Open-File Report 96-159, 48 p.
- \_\_\_\_\_1996h, Level II scour analysis for Bridge 23 (HARDTH00530023) on Town Highway 53, crossing Haynesville Brook, Hardwick, Vermont: U.S. Geological Survey Open-File Report 96-638, 50 p.
- \_\_\_\_\_1996i, Level II scour analysis for Bridge 24 (HARDTH00490024) on Town Highway 49, crossing Nichols Brook at Mackville Pond Outlet, Hardwick, Vermont: U.S. Geological Survey Open-File Report 96-637, 51 p.
- \_\_\_\_\_1996j, Level II scour analysis for Bridge 27 (BRIDTH00490027) on Town Highway 049, crossing Broad Brook, Bridgewater, Vermont: U.S. Geological Survey Open-File Report 96-195, 52 p.

- 1996k, Level II scour analysis for Bridge 28 (BRIDTH00440028) on Town Highway 044 crossing Plymouth Brook, Bridgewater, Vermont: U.S. Geological Survey Open-File Report 96-188, 52 p.
- 1996l, Level II scour analysis for Bridge 28 (HARDTH00300028) on Town Highway 30, crossing the Lamoille River, Hardwick, Vermont: U.S. Geological Survey Open-File Report 96-569, 63 p.
- 1996m, Level II scour analysis for Bridge 31 (HARDTH00050031) on Town Highway 5, crossing the Lamoille River, Hardwick, Vermont: U.S. Geological Survey Open-File Report 96-644, 50 p.
- 1996n, Level II scour analysis for Bridge 32 (CONCTH00030032) on Town Highway 3, crossing the Moose River, Concord, Vermont: U.S. Geological Survey Open-File Report 96-582, 50 p.
- 1996o, Level II scour analysis for Bridge 34 (RANDTH00660034) on Town Highway 66, crossing Second Branch White River, Randolph, Vermont: U.S. Geological Survey Open-File Report 96-236, 50 p.
- 1996p, Level II scour analysis for Bridge 35 (RANDTH00650035) on Town Highway 65, crossing the Second Branch White River, Randolph, Vermont: U.S. Geological Survey Open-File Report 96-563, 51 p.
- 1996q, Level II scour analysis for Bridge 36 (RANDTH00480036) on Town Highway 48, crossing Snows Brook, Randolph, Vermont: U.S. Geological Survey Open-File Report 96-641, 50 p.
- 1996r, Level II scour analysis for Bridge 37 (CONCTH00010037) on Town Highway 1, crossing the Moose River, Concord, Vermont: U.S. Geological Survey Open-File Report 96-741, 50 p.
- 1996s, Level II scour analysis for Bridge 38 (CONCTH00060038) on Town Highway 6, crossing the Moose River, Concord, Vermont: U.S. Geological Survey Open-File Report 96-744, 50 p.
- 1996t, Level II scour analysis for Bridge 38 (RANDTH00640038) on Town Highway 64, crossing the Second Branch of the White River, Randolph, Vermont: U.S. Geological Survey Open-File Report 96-587, 50 p.
- 1996u, Level II scour analysis for Bridge 41 (WODSTH00750041) on Town Highway 75, crossing Happy Valley Brook, Woodstock, Vermont: U.S. Geological Survey Open-File Report 96-567, 48 p.
- 1996v, Level II scour analysis for Bridge 42 (HARDELMSTR0042) on Elm Street, crossing Cooper Brook, Hardwick, Vermont: U.S. Geological Survey Open-File Report 96-565, 55 p.

- 1996w, Level II scour analysis for Bridge 42 (RANDVT00120042) on State Highway 12, crossing Third Branch White River, Randolph, Vermont: U.S. Geological Survey Open-File Report 96-187, 51 p.
- 1996x, Level II scour analysis for Bridge 43 (BRIDTH00040043) on Town Highway 004, crossing Dailey Hollow Branch, Bridgewater, Vermont: U.S. Geological Survey Open-File Report 96-153, 49 p.
- 1996y, Level II scour analysis for Bridge 43 (HARDTH00CU0043) on Church Street, crossing the Lamoille River, Hardwick, Vermont: U.S. Geological Survey Open-File Report 96-745, 51 p.
- 1996z, Level II scour analysis for Bridge 45a (BRIDUS00040045a) on U.S. Route 4, crossing Ottauquechee River, Bridgewater, Vermont: U.S. Geological Survey Open-File Report 96-244, 50 p.
- 1996aa, Level II scour analysis for Bridge 51 (BRIDTH00460051) on Town Highway 46, crossing Ottauquechee River, Bridgewater, Vermont: U.S. Geological Survey Open-File Report 96-242, 51 p.
- 1996bb, Level II scour analysis for Bridge 51 (RANDTH00SC0051) on School Street, crossing Thayer Brook, Randolph, Vermont: U.S. Geological Survey Open-File Report 96-240, 51 p.
- 1996cc, Level II scour analysis for Bridge 54 (RANDTH00BR0054) on Brook Street, crossing Thayer Brook, Randolph, Vermont: U.S. Geological Survey Open-File Report 96-308, 47 p.
- 1996dd, Level II scour analysis for Bridge 99 (LUDLVT01000099) on State Highway 99, crossing Branch Brook, Ludlow, Vermont: U.S. Geological Survey Open-File Report 96-572, 48 p.
- 1997a, Level II scour analysis for Bridge 1 (JAY-TH00040001) on Town Highway 4, crossing Crook Brook, Jay, Vermont: U.S. Geological Survey Open-File Report 97-366, 47 p.
- 1997b, Level II scour analysis for Bridge 2 (BENNCYPARK0002) on Park Street, crossing Furnace Brook, Bennington, Vermont: U.S. Geological Survey Open-File Report 97-341, 50 p.
- 1997c, Level II scour analysis for Bridge 6 (ALBUTH00150006) on Town Highway 15, crossing Mud Creek, Alburg, Vermont: U.S. Geological Survey Open-File Report 97-397, 49 p.
- 1997d, Level II scour analysis for Bridge 6 (VICTTH000110006) on Town Highway 1, crossing the Moose River, Victory, Vermont: U.S. Geological Survey Open-File Report 97-6, 48 p.
- 1997e, Level II scour analysis for Bridge 10 (WFIETH00170010) on Town Highway 17, crossing Taft Brook, Westfield, Vermont: U.S. Geological Survey Open-File Report 97-344, 47 p.
- 1997f, Level II scour analysis for Bridge 24 (MANCUS00070024) on U.S. Route 7, crossing Lye Brook, Manchester, Vermont: U.S. Geological Survey Open-File Report 97-390, 51 p.
- 1997g, Level II scour analysis for Bridge 29 (HARDTH00310029) on Town Highway 31, crossing the Lamoille River, Hardwick, Vermont: U.S. Geological Survey Open-File Report 97-340, 49 p.

- 1997h, Level II scour analysis for Bridge 43 (BENNCYDEPO0043) on Depot Street, crossing the Walloomsac River, Bennington, Vermont: U.S. Geological Survey Open-File Report 97-346, 49 p.
- 1997i, Level II scour analysis for Bridge 43 (CHELTH00460043) on Town Highway 46, crossing Jail Brook, Chelsea, Vermont: U.S. Geological Survey Open-File Report 97-386, 47 p.
- 1997j, Level II scour analysis for Bridge 49 (FFIETH00290049) on Town Highway 29, crossing Black Creek, Fairfield, Vermont: U.S. Geological Survey Open-File Report 97-391, 51 p.
- 1998a, Level II scour analysis for Bridge 6 (GLOVTH00030006) on Town Highway 3, crossing the Barton River, Glover, Vermont: U.S. Geological Survey Open-File Report 98-552, 54 p.
- 1998b, Level II scour analysis for Bridge 41 (NORWTH00160041) on Town Highway 16, crossing Bloody Brook, Norwich, Vermont: U.S. Geological Survey Open-File Report 98-399, 51 p.
- Olson, S.A., and Ayotte, J.D., 1996, Level II scour analysis for Bridge 35 (BRIDTH00050035) on Town Highway 05, crossing the North Branch Ottauquechee River, Bridgewater, Vermont: U.S. Geological Survey Open-File Report 96-305, 50 p.
- 1997, Level II scour analysis for Bridge 71 (WODSTH00050071) on Town Highway 5, crossing Kedron Brook, Woodstock, Vermont: U.S. Geological Survey Open-File Report 97-807, 50 p.
- Olson, S.A., and Boehmler, E.M., 1996, Level II scour analysis for Bridge 36 (BRIDTH00050036) on Town Highway 5, crossing Bridgewater Hollow Brook, Bridgewater, Vermont: U.S. Geological Survey Open-File Report 96-387, 50 p.
- 1997, Level II scour analysis for Bridge 23 (GLOVTH00410023) on Town Highway 41, crossing Sherburne Brook, Glover, Vermont: U.S. Geological Survey Open-File Report 97-388, 47 p.
- Olson, S.A., and Burns, R.L., 1997, Level II scour analysis for Bridge 10 (BENNUS00070010) on U.S. Route 7, crossing the Walloomsac River, Bennington, Vermont: U.S. Geological Survey Open-File Report 97-580, 49 p.
- Olson, S.A., and Degnan, J.R., 1997, Level II scour analysis for Bridge 42 (BENNCYSCHL0042) on School Street, crossing Walloomsac River, Bennington, Vermont: U.S. Geological Survey Open-File Report 97-208, 50 p.
- Olson, S.A., and Ivanoff, M.A., 1996a, Level II scour analysis for Bridge 10 (HANCTH00010010) on Town Highway 1, crossing the White River, Hancock, Vermont: U.S. Geological Survey Open-File Report 96-570, 50 p.

- 1996b, Level II scour analysis for Bridge 29 (BRIDTH00360029) on Town Highway 36, crossing North Branch Ottauquechee River, Bridgewater, Vermont: U.S. Geological Survey Open-File Report 96-245, 52 p.
- 1997a, Level II scour analysis for Bridge 4 (ARLITH00010004) on Town Highway 1, crossing Warm Brook, Arlington, Vermont: U.S. Geological Survey Open-File Report 97-182, 50 p.
- 1997b, Level II scour analysis for Bridge 9 (BARRUSO3020009) on U.S. Route 302, crossing Jail Branch, Barre, Vermont: U.S. Geological Survey Open-File Report 97-109, 47 p.
- 1997c, Level II scour analysis for Bridge 87 (CABOUS00020087) on U.S. Route 2, crossing Mollys Brook, Cabot, Vermont: U.S. Geological Survey Open-File Report 97-187, 49 p.
- Olson, S.A., and Hammond, R.E., 1996, Level II scour analysis for Bridge 49 (WODSTH00990049) on Town Highway 99, crossing Gulf Brook, Woodstock, Vermont: U.S. Geological Survey Open-File Report 96-639, 50 p.
- 1996c, Level II scour analysis for Bridge 37 (BRIDTH00050037) on Town Highway 5, crossing North Branch Ottauquechee River, Bridgewater, Vermont: U.S. Geological Survey Open-File Report 96-309, 51 p.
- Olson, S.A., and Medalie, Laura, 1997, Level II scour analysis for Bridge 49 (BENNCYHUNT0049) on Hunt Street, crossing the Walloomsac River, Bennington, Vermont: U.S. Geological Survey Open-File Report 97-367, 49 p.
- Olson, S.A., and Medalie, Laura, 1998, Level II scour analysis for Bridge 50 (FFIETH00490050) on Town Highway 49, crossing Black Creek, Fairfield, Vermont: U.S. Geological Survey Open-File Report 98-418, 49 p.
- Olson, S.A., and Song, D.L., 1996a, Level II scour analysis for Bridge 3 (BRIDTH000100003) on Town Highway 1, crossing Dailey Hollow Branch, Bridgewater, Vermont: U.S. Geological Survey Open-File Report 96-237, 47 p.
- 1996b, Level II scour analysis for Bridge 24 (WODSTH00190024) on Town Highway 19, crossing North Bridgewater Brook, Woodstock, Vermont: U.S. Geological Survey Open-File Report 96-238, 53 p.
- 1996c, Level II scour analysis for Bridge 30 (BRIDTH00330030) on Town Highway 33, crossing Dailey Hollow Branch, Bridgewater, Vermont: U.S. Geological Survey Open-File Report 96-304, 50 p.
- 1996d, Level II scour analysis for Bridge 33 (BRIDTH00050033) on Town Highway 5, crossing the North Branch Ottauquechee River, Bridgewater, Vermont: U.S. Geological Survey Open-File Report 96-385, 50 p.
- 1996e, Level II scour analysis for Bridge 35 (BETHTH00190035) on Town Highway 19, crossing Gilead Brook, Bethel, Vermont: U.S. Geological Survey Open-File Report 96-239, 50 p.



- 1996f, Level II scour analysis for Bridge 46 (BRIDTH00050046) on Town Highway 05, crossing North Branch Ottauquechee River, Bridgewater, Vermont: U.S. Geological Survey Open-File Report 96-311, 50 p.
- 1996g, Level II scour analysis for Bridge 46 (NORWTH00030046) Town Highway 3 (VT132) crossing the Ompompanoosuc River, Norwich, Vermont: U.S. Geological Survey Open-File Report 96-160, 49 p.
- Olson, S.A., and Weber, M.A., 1996a, Level II scour analysis for Bridge 23 (WODSTH00180023) on Town Highway 18, crossing North Bridgewater Brook, Woodstock, Vermont: U.S. Geological Survey Open-File Report 96-197, 52 p.
- 1996b, Level II scour analysis for Bridge 42 (BRIDTH00040042) on Town Highway 04, crossing Dailey Hollow Brook, Bridgewater, Vermont: U.S. Geological Survey Open-File Report 96-243, 50 p.
- Serra, M.M., 1998a, Level II scour analysis for Bridge 4 (VICTTH00020004) on Town Highway 2, crossing Moose River, Victory, Vermont: U.S. Geological Survey Open-File Report 98-082, 50 p.
- 1998b, Level II scour analysis for Bridge 42 (BRNETH00810042) on Town Highway 81, crossing Stevens River, Barnet, Vermont: U.S. Geological Survey, Open-File Report 98-289, 51 p.
- Serra, M.M., and Boehmler, E.M., 1998a, Level II scour analysis for Bridge 7 (CORITH00020007) on Town Highway 2, crossing Cookville Brook, Corinth, Vermont: U.S. Geological Survey Open-File Report 98-553, 51 p.
- 1998b, Level II scour analysis for Bridge 32 (BURKTH00440032) on Town Highway 44, crossing Roundy Brook, Burke, Vermont: U.S. Geological Survey Open-File Report 98-554, 49 p.
- Serra, M.M., and Ivanoff, M.A., 1998, Level II scour analysis for Bridge 64 (STOWTH00340064) on Town Highway 34, crossing Ranch Brook, Stowe, Vermont: U.S. Geological Survey Open-File Report 98-081, 48 p.
- Serra, M.M., and Medalie, Laura, 1998, Level II scour analysis for Bridge 4 (SUTTTH00450004) on Town Highway 45, crossing Calender Brook, Sutton, Vermont: U.S. Geological Survey Open-File Report 98-528, 48 p.
- Serra, M.M., and Severance, Timothy, 1998, Level II scour analysis for Bridge 20 (BURKTH00560020) on Town Highway 56, crossing the East Branch Passumpsic River, Burke, Vermont: U.S. Geological Survey Open-File Report 98-555, 50 p.
- Severance, Timothy, 1997, Level II scour analysis for Bridge 28 (BRNATH00660028) on Town Highway 66, crossing Locust Creek, Barnard, Vermont: U.S. Geological Survey Open-File Report 97-209, 49 p.
- Song, D.L., and Toppin, K.W., 1996, Level II scour analysis for Bridge 39 (RANDTH00730039) on Town Highway 73, crossing the Second Branch White River, Randolph, Vermont: U.S. Geological Survey Open-File Report 96-234, 50 p.

- Striker, L.K., 1997a, Level II scour analysis for Bridge 7 (WALDTH00020007) on Town Highway 2, crossing Coles Brook, Walden, Vermont: U.S. Geological Survey Open-File Report 97-632, 50 p.
- 1997b, Level II scour analysis for Bridge 10 (WNDH00020010) on Town Highway 2, crossing the Middle Branch of the Williams River, Windham, Vermont: U.S. Geological Survey Open-File Report 97-387, 48 p.
- 1997c, Level II scour analysis for Bridge 18 (GROTTH00480018) on Town Highway 48, crossing the Wells River Groton, Vermont: U.S. Geological Survey Open-File Report 97-626, 50 p.
- 1997d, Level II scour analysis for Bridge 26 (WSTOTH00070026) on Town Highway 7, crossing Greendale Brook, Weston, Vermont: U.S. Geological Survey Open File Report 97-576, 47 p.
- 1997e, Level II scour analysis for Bridge 29 (LONDTH00410029) on Town Highway 41, crossing Cook Brook, Londonderry, Vermont: U.S. Geological Survey Open-File Report 97-403, 50 p.
- 1997f, Level II scour analysis for Bridge 36 (ANDOV00110036) on VT 11, crossing Middle Branch Williams River, Andover, Vermont: U.S. Geological Survey Open-File Report 97-393, 50 p.
- 1997g, Level II scour analysis for Bridge 38 (ANDOV00110038) on State Route 11, crossing the Middle Branch Williams River, Andover, Vermont: U.S. Geological Survey Open-File Report 97-368, 49 p.
- 1997h, Level II scour analysis for Bridge 38 (TOPSTH00570038) on Town Highway 57, crossing Waits River, Topsham, Vermont: U.S. Geological Survey Open File Report 97-649, 50 p.
- 1997i, Level II scour analysis for Bridge 43 (CHESVT00110043) on State Highway 11, crossing the Middle Branch Williams River, Chester, Vermont: U.S. Geological Survey Open-File Report 97-342, 48 p.
- 1998, Level II scour analysis for Bridge 6 (MAIDTH00050006) on Town Highway 5, crossing Cutler Mill Brook, Maidstone, Vermont: U.S. Geological Survey Open-File Report 98-419, 51 p.
- Striker, L.K., and Degnan, J.R., 1997a, Level II scour analysis for Bridge 17 (SHEFTH00380017) on Town Highway 38, crossing Miller Run, Sheffield, Vermont: U.S. Geological Survey Open-File Report 97-782, 50 p.
- 1997b, Level II scour analysis for Bridge 22 (TOPSTH00490022) on Town Highway 49, crossing Waits River, Topsham, Vermont: U.S. Geological Survey Open-File Report 97-822, 50 p.
- 1998a, Level II scour analysis for Bridge 5 (MAIDTH00040005) on Town Highway 4, crossing Cutler Mill Brook, Maidstone, Vermont: U.S. Geological Survey Open-File Report 98-194, 50 p.
- 1998b, Level II scour analysis for Bridge 15 (SHEFTH00320015) on Town Highway 32, crossing the Branch of Millers Run, Sheffield, Vermont: U.S. Geological Survey Open-File Report 98-080, 50 p.

- 1998c, Level II scour analysis for Bridge 39 (BETHTH00060039) on Town Highway 6, crossing the Second Branch of the White River, Bethel, Vermont: U.S. Geological Survey Open-File Report 98-060, 50 p.
- Striker, L.K., and Flynn, R.H., 1997, Level II scour analysis for Bridge 6 (FAYSTH00010006) on Town Highway 1, crossing Shepard Brook, Fayston, Vermont: U.S. Geological Survey Open-File Report 97-755, 50 p.
- Striker, L.K., and Hammond, R.E., 1998a, Level II scour analysis for Bridge 10 (GROTTH00240010) on Town Highway 32, crossing Heath Brook, Groton, Vermont: U.S. Geological Survey Open-File Report 98-288, 51 p.
- 1998b, Level II scour analysis for Bridge 19 (FAYSTH00100019) on Town Highway 10, crossing Shepard Brook, Fayston, Vermont: U.S. Geological Survey Open-File Report 98-272, 50 p.
- Striker, L.K., and Ivanoff, M.A., 1997a, Level II scour analysis for Bridge 8 (WELLTH00020008) on Town Highway 2, crossing Wells Brook, Wells, Vermont: U.S. Geological Survey Open-File Report 97-770, 50 p.
- 1997b, Level II scour analysis for Bridge 16 (GROTTH00170016) on Town Highway 17, crossing the Wells River, Groton, Vermont: U.S. Geological Survey Open-File Report 97-805, 50 p.
- 1997c, Level II scour analysis for Bridge 22 (WALDTH00180022) on Town Highway 18, crossing Coles Brook, Walden, Vermont: U.S. Geological Survey Open-File Report 97-768, 47 p.
- 1998, Level II scour analysis for Bridge 16 (STRATH00180016) on Town Highway 18, crossing the West Branch of the Ompompanoosuc River, Strafford, Vermont: U.S. Geological Survey Open-File Report 98-024, 52 p.
- Striker, L.K., and Medalie, Laura, 1997a, Level II scour analysis for Bridge 4 (MAIDTH00070004) on Town Highway 7, crossing Cutler Mill Brook, Maidstone, Vermont: U.S. Geological Survey Open-File Report 97-760, 50 p.
- 1997b, Level II scour analysis for Bridge 21 (MORETH00010021) on Town Highway 1, crossing Cox Brook, Moretown, Vermont: U.S. Geological Survey Open-File Report 97-662, 50 p.
- 1997c, Level II scour analysis for Bridge 53 (CHESTH01180053) on Town Highway 118, crossing the Williams River, Chester, Vermont: U.S. Geological Survey Open-File Report 97-769, 50 p.
- 1998, Level II scour analysis for Bridge 52 (STOWTH00230052) on Town Highway 23, crossing West Branch Little River, Stowe, Vermont: U.S. Geological Survey Open-File Report 98-061, 49 p.
- Striker, L.K., and Severance, Timothy, 1997, Level II scour analysis for Bridge 39 (TOPSTH00510039) on Town Highway 51, crossing Tabor Branch Waits River, Topsham, Vermont: U.S. Geological Survey, Open-File Report 97-797, 50 p.
- 1998, Level II scour analysis for Bridge 47 (LYNDTH00360047) on Town Highway 36, crossing the East Branch Passumpsic River, Lyndon, Vermont: U.S. Geological Survey Open-File Report 98-406, 51 p.

- Striker, L.K., and Wild, E.C., 1997, Level II scour analysis for Bridge 36 (STOWTH00430036) on Town Highway 43, crossing Miller Brook, Stowe, Vermont: U.S. Geological Survey Open-File Report 97-780, 50 p.
- Striker, L.K., and Weber, M.A., 1998, Level II scour analysis for Bridge 5 (STOCTH00360005) on Town Highway 36, crossing Stony Brook, Stockbridge, Vermont: U.S. Geological Survey Open-File Report 98-409, 48 p.
- Wild, E.C., 1997a, Level II scour analysis for Bridge 5 (WOLCTH00150005) on Town Highway 15, crossing the Wild Branch Lamoille River, Wolcott, Vermont: U.S. Geological Survey Open-File Report 97-808, 49 p.
- 1997b, Level II scour analysis for Bridge 7H (HUNTTTH0001007H) on Town Highway 1, crossing Cobb Brook, Huntington, Vermont: U.S. Geological Survey Open-File Report 97-339, 50 p.
- 1997c, Level II scour analysis for Bridge 29 (DORSTH00100029) on Town Highway 10, crossing the Mettawee River, Dorset, Vermont: U.S. Geological Survey Open-File Report 97-774, 50 p.
- 1997d, Level II scour analysis for Bridge 31 (JERITH00350031) on Town Highway 35, crossing Mill Brook, Jericho, Vermont: U.S. Geological Survey Open-File Report 97-767, 50 p.
- 1997e, Level II scour analysis for Bridge 37 (DUXBTH00120037) on Town Highway 12, crossing Ridley Brook, Duxbury, Vermont: U.S. Geological Survey Open-File Report 97-405, 50 p.
- 1997f, Level II scour analysis for Bridge 46 (CHESVT00110046) on Vermont State Route 11, crossing the Middle Branch Williams River, Chester, Vermont: U.S. Geological Survey Open-File Report 97-365, 47 p.
- 1997g, Level II scour analysis for Bridge 72 (STRATH00510072) on Town Highway 51, crossing the West Branch Ompompanoosuc River, Strafford, Vermont: U.S. Geological Survey Open-File Report 97-379, 50 p.
- 1998a, Level II scour analysis for Bridge 13 (LINCTH00010013) on Town Highway 1, crossing Cota Brook, Lincoln, Vermont: U.S. Geological Survey Open-File Report 98-157, 48 p.
- 1998b, Level II scour analysis for Bridge 27 (WSTOTH00070027) on Town Highway 7, crossing Jenny Coolidge Brook, Weston, Vermont: U.S. Geological Survey Open-File Report 98-156, 47 p.
- 1998c, Level II scour analysis for Bridge 28 (STRATH00020028) on Town Highway 2, crossing the West Branch Ompompanoosuc River, Strafford, Vermont: U.S. Geological Survey Open-File Report 98-293, 50 p.
- 1998d, Level II scour analysis for Bridge 32 (TUNBTH00600032) on Town Highway 60, crossing First Branch White River, Tunbridge, Vermont: U.S. Geological Survey Open-File Report 98-013, 52 p.
- 1998e, Level II scour analysis for Bridge 46 (LINCTH00060046) on Town Highway 6, crossing the New Haven River, Lincoln, Vermont: U.S. Geological Survey Open-File Report 98-023, 50 p.

- 1998f, Level II scour analysis for Bridge 51 (JERITH00590051) on Town Highway 59, crossing The Creek, Jericho, Vermont: U.S. Geological Survey Open-File Report 98-89, 50 p.
- Wild, E.C., and Boehmler, E.M., 1997, Level II scour analysis for Bridge 18 (SHEFTH00410018) on Town Highway 41, crossing Millers Run, Sheffield, Vermont: U.S. Geological Survey Open-File Report 97-772, 50 p.
- 1998, Level II scour analysis for Bridge 65 (MTHOTH00120065) on Town Highway 12, crossing Freeman Brook, Mount Holly, Vermont: U.S. Geological Survey Open-File Report 98-161, 47 p.
- Wild, E.C., and Burns, R.L., 1998, Level II scour analysis for Bridge 17 (NEWHTH00200017) on Town Highway 20, crossing Little Otter Creek, New Haven, Vermont: U.S. Geological Survey Open-File Report 98-015, 50 p.
- Wild, E.C., and Degnan, J.R., 1997a, Level II scour analysis for Bridge 23 (WOLCTH00130023) on Town Highway 13, crossing the Wild Branch of the Lamoille River, Wolcott, Vermont: U.S. Geological Survey Open-File Report 97-394, 50 p.
- 1997b, Level II scour analysis for Bridge 34 (ROCHTH00210034) on Town Highway 21, crossing the White River, Rochester, Vermont: U.S. Geological Survey Open-File Report 97-670, 50 p.
- 1997c, Level II scour analysis for Bridge 36 (DUXBTH00040036) on Town Highway 4, crossing Crossett Brook, Duxbury, Vermont: U.S. Geological Survey Open-File Report 97-661, 48 p.
- 1997d, Level II scour analysis for Bridge 38 (JERITH0020038) on Town Highway 20, crossing the Lee River, Jericho, Vermont: U.S. Geological Survey Open-File Report 97-773, 47 p.
- 1998, Level II scour analysis for Bridge 8 (NEWFTH00010008) on Town Highway 1, crossing Wardsboro Brook, Newfane, Vermont: U.S. Geological Survey Open-File Report 98-90, 50 p.
- Wild, E.C., and Flynn, R.H., 1998a, Level II scour analysis for Bridge 20 (CONCTH00110020) on Town Highway 11, crossing Miles Stream, Concord, Vermont: U.S. Geological Survey Open-File Report 98-421, 51 p.
- 1998b, Level II scour analysis for Bridge 33 (WWINTH00300033) on Town Highway 30, crossing Mill Brook, West Windsor, Vermont: U.S. Geological Survey Open-File Report 98-256, 50 p.
- 1998c, Level II scour analysis for Bridge 46 (FFIETH00470046) on Town Highway 47, crossing Black Creek, Fairfield, Vermont: U.S. Geological Survey Open-File Report 98-424, 51 p.
- Wild, E.C., and Hammond, R.E., 1997a, Level II scour analysis for Bridge 10 (CHESTH00030010) on Town Highway 3 (VT 35), crossing the South Branch of Williams River, Chester, Vermont: U.S. Geological Survey Open-File Report 97-369, 50 p.
- 1997b, Level II scour analysis for Bridge 29 (ROYATH00920029) on Town Highway 92, crossing the First Branch White River, Royalton, Vermont: U.S. Geological Survey Open-File Report 97-819, 50 p.

- 1997c, Scour analysis for Bridge 41 (ANDOVT00110041) on State Route 11, crossing the Middle Branch Williams River, Andover, Vermont: U.S. Geological Survey Open-File Report 97-771, 50 p.
- Wild, E.C., and Ivanoff, M.A., 1998a, Level II scour analysis for Bridge 22 (BRADTH00270022) on Town Highway 27, crossing the Waits River, Bradford, Vermont: U.S. Geological Survey Open-File Report 98-537, 48 p.
- 1998b, Level II scour analysis for Bridge 42 (NEWFTH00350042) on Town Highway 35, crossing Stratton Hill Brook, Newfane, Vermont: U.S. Geological Survey Open-File Report 98-404, 48 p.
- 1998c, Level II scour analysis for Bridge 52 (CHESTH00100052) on Town Highway 10, crossing the South branch Williams River, Chester, Vermont: U.S. Geological Survey Open-File Report 98-012, 50 p.
- Wild, E.C., and Medalie, Laura, 1997a, Level II scour analysis for Bridge 17 (LYNDTH00020017) on Town Highway 2, crossing Hawkins Brook, Lyndon, Vermont: U.S. Geological Survey Open-File Report 97-752, 47 p.
- 1997b, Level II scour analysis for Bridge 19 (SHEFTH00440019) on Town Highway 44, crossing Trout Brook, Sheffield, Vermont: U.S. Geological Survey Open-File Report 97-817, 50 p.
- 1998, Level II scour analysis for Bridge 37 (PLYMTH00080037) on Town Highway 8, crossing Broad Brook, Plymouth, Vermont: U.S. Geological Survey Open-File Report 98-556, 52 p.
- Wild, E.C., and Severance, Timothy, 1997, Level II scour analysis for Bridge 33 (TUNBTH00450033) on Town Highway 45, crossing the First Branch White River, Tunbridge, Vermont: U.S. Geological Survey Open-File Report 97-803, 50 p.
- 1998a, Level II scour analysis for Bridge 63 (MTHOTH00120063) on Town Highway 12, crossing Russell Brook, Mount Holly, Vermont: U.S. Geological Survey Open-File Report 98-159, 47 p.
- 1998b, Level II scour analysis for Bridge 67 (MTHOTH00120067) on Town Highway 12, crossing Freeman Brook, Mount Holly, Vermont: U.S. Geological Survey Open-File Report 98-401, 48 p.
- Wild, E.C., and Weber, M.A., 1997, Level II scour analysis for Bridge 13 (SHARTH00040013) on Town Highway 4, crossing Broad Brook, Sharon, Vermont: U.S. Geological Survey Open-File Report 97-593, 50 p.
- 1998a, Level II scour analysis for Bridge 25 (ROCHTH00400025) on Town Highway 40, crossing Corporation Brook, Rochester, Vermont: U.S. Geological Survey Open-File Report 98-160, 50 p.
- 1998b, Level II scour analysis for Bridge 28 (ROCHTH00370028) on Town Highway 37, crossing Brandon Brook, Rochester, Vermont: U.S. Geological Survey Open-File Report 98-273, 50 p.
- 1998c, Level II scour analysis for Bridge 29 (STOCTH00050029) on Town Highway 5, crossing Lilliesville Brook, Stockbridge, Vermont: U.S. Geological Survey Open-File Report 98-423, 48 p.

- 1998d, Level II scour analysis for Bridge 47 (PLYMTH00540047) on Town Highway 54, crossing Pinney Hollow Brook, Plymouth, Vermont: U.S. Geological Survey Open-File Report 98-196, 50 p.
- Willoughby, S.A., and Burns, R.L., 1997, Level II scour analysis for Bridge 57 (CHESTH00090057) on Town Highway 9, crossing Chase Brook, Chester, Vermont: U.S. Geological Survey Open-File Report 97-823, 49 p.
- Willoughby, S.A., and Ivanoff, M.A., 1998a, Level II scour analysis for Bridge 25 (MENDTH00130025) on Town Highway 13, crossing Mendon Brook, Mendon, Vermont, U.S. Geological Survey Open-File Report 98-155, 48 p.f
- 1998b, Level II scour analysis for Bridge 54 (LUDLTH03560054) on Town Highway 356, crossing Jewell Brook, Ludlow, Vermont: U.S. Geological Survey Open-File Report 98-92, 50 p.
- Willoughby, S.A., and Severance, Timothy, 1998, Level II scour analysis for Bridge 20 (MENDTH00070020) on Town Highway 7, crossing Mendon Brook, Mendon, Vermont: U.S. Geological Survey Open-File Report 98-527, 50 p.