



REQUIRES
PROPER ATTIRE



NSLS
BUILDING 725
2nd FLOOR

175
173A CLOSET A
173B
171B CLOSET B
171C CLOSET C
171D
171
MEN
173
LADIES

188
186
182C
182A
182B
184
188
162
160
158
156D
156C
178
176
155D
184A
184B
190A
190B
190C
190E
190D

152
154
156A
152A
FILE ROOM

124D
124E
124C
124B
124A
120
118
116
114
112
110
108
106
104C
104B
104A
102
103
101
100
100C
100A

117
115
113
111
109
107
105
107A
107B

192A
194
196
198
200
202
204
206
208
210
211
212
213
215
217
217A
217-B

122
R.F. PENTHOUSE

125A
125
SEMINAR ROOM

129
128
127B
127A
CHAIRMAN'S OFFICE

119
117
115
113
111
109
107
105
103
101
100
100C
100A

191A
191
189
187
185
183
181
179
177
175

MECH. E.Q. RM.
NO. 6

ELEV NO. 1
193

195
197
199
201
203
205
207
209

173B
171B CLOSET B
171C CLOSET C
171D

COVERED WALKWAY

REQUIRES
PROPER ATTIRE