Inventory (NES). With the exception of Kentucky and Pennsylvania, whose most current data is 2005, all data is from the 2007 NEI. Of the 251 structurally deficient NHS bridges in Michigan, 15 could not be geolocated because of insufficient data. Structurally deficient bridges are not recessarily unsafe. all public road bridges receive regular safety inspections. The bridges listed were categorized as structurally deficient at the time the maps were developed

Bridge Label	Structure ID	Bridge Description	Location Description
1	13113081000S010	I-94 BL (MLK)	0.1 MI E OF KALAMAZOO CO
2	13113081000R013	I-94 EB	0.5 MI E OF KALAMAZOO CO
3	13113081000R014	I-94 WB	0.5 MI E OF KALAMAZOO CO
4	13113081000S053	I-94 EB	0.5 MI W OF M-66
5	13113081000S054	I-94 WB	0.5 MI W OF M-66
6	13113082000S033	I-94 EB	3.2 MI E OF M-66
7	23123012000B012	US-127 SB	1.0 MI SW OF POTTERVILLE
8	23123012000B011	US-127 NB	1.0 MI SW OF POTTERVILLE
9	38138101000B010	I-94	3.0 MI W OF M-60
10	38138131000R012	US-127 SB	3.3 MI N OF I 94
11	38138083000B020	I-94BL,US127BR,M50	IN JACKSON (CLINTON ST)
12	38138083000B030	I-94BL,US127BR,M50	IN JACKSON (MILWAUKEE ST)
13	38138111000S052	US-127 SB	@ E JCT I-94
14	38138111000S051	US-127 NB	@ E JCT I-94
15	38138101000S120	I-94	@ I-94 BL WB
16	46146062000B020	US-223	IN PALMYRA