

hvenlory (NB). With the exception of Kentucky and Pennsylvania, whose most current data is 2006, all data is from the 2007 NBI. Of the 207 structurally deficient NNS bridge in Tillinois, 7 could not be geobrated because of insufficient data. Structurally deficient bridges are not necessarily unsate; all public road bridges receives against arbity inspection. The bridges listed ware adegointed as structurally deficient to the sins then says were developed.

Bridge Label	Structure ID	Bridge Description	Location Description
1	16021903994 U	S 20	.8M W NAPERVILLE RD
2	16058104255 IL	L 62 (ALGONQUIN	0.7 M E ILL 53 P5
3	16050404182 IL	L 72 (HIGGINS RD	1 M E I-290,IL53 P5
4	22300705564 TH	HORNDALE AV	1.6 MI E I-290
5	16998005267 19	0 WB (NW TOLL)	0.6 M W US 45 P11