

Structurally Deficient Bridges on the National Highway System
Massachusetts - Congressional District 03



Consult your state DOT for the most up-to-date status of bridges.

Area of Detail



Note: The bridges displayed on this map represent the results of a combined BTS/FHWA effort to geocode bridges from the FHWA's National Bridge Inventory (NBI). With the exception of Kentucky and Pennsylvania, whose most current data is 2006, all data is from the 2007 NBI. Of the 187 structurally deficient NHS bridges in Massachusetts, 11 could not be geolocated because of insufficient data. Structurally deficient bridges are not necessarily unsafe; all public road bridges receive regular safety inspections. The bridges listed were categorized as structurally deficient at the time the maps were developed.

Bridge Label	Structure ID	Bridge Description	Location Description
1	A170474KMMTANBI I 90 WB		.1 MI.W.I290 K5
2	A170474KLMTANBI I 90 EB		.1 MI W. I 290 K5
3	W4402723AMHD634 HWY CAMBRIDGE ST		JUST W. OF SOUTHBRIDGE ST
4	W441081RVMHDNBI I 290 EB		.1 MI. E OF COLLEGE SQ.
5	W441241XGMHDNBI I 190 SB		I 190/12 & RAMP B
6	W441241XFMHDNBI I 190 NB		I 190NB/12 & RAMP B
7	W440941L2MHDNBI ST 9 BELMONT ST		.2 MI. EAST OF LINCOLN SQ
8	S140011L0MHDNBI ST 9 BELMONT ST		100 F.T. E. OF LAKE AVE.
9	W440631LAMHDNBI ST122 GRAFTON ST		.3 MI.NTH.OF MILLBURY TL.
10	W240274NGMTANBI I 90 WB		.3MI.EAST I495 L4
11	W240274NFMTANBI I 90 EB		.3MI. EAST I495 L4
12	W240324NEMTANBI I 90 WB		.7MI.EAST I495 L5
13	W240324NDMTANBI I 90 EB		.7MI.EAST I495 L5
14	H230111URMHDNBI I 495 SB		.3 MI. EAST OF SOUTH ST
15	H230111UQMHDNBI I 495 NB		1.1 MI.STH.OF ST-135
16	R040013N6MHDNBI US 44 WINTHROP ST		1.7 MI NE SEEKONK T.L.
17	F020593TTMHDNBI ST 79 SB		AT E END OF BRAGA BR
18	F020453MEMHDNBI ST 24		1.0 MI N OF I 195