

deficient NHS bridges in California, 54 could not be geolocated because of insufficient data. Structurally deficient bridges are not necessarily una afe; all public road bridges receive regular safety inspections. The bridges listed were categorized as structurally deficient at the time the maps were developed

Bridge Label	Structure ID	Bridge Description	Location Description	
1	53 1095 l	JS HIGHWAY 101	07-LA-101-25.88-LA	
2	53 1063 l	JS HIGHWAY 101	07-LA-101-24.85-LA	