




## Structurally Deficient Bridges on the National Highway System Wisconsin - Congressional District 07



Consult your state DOT for the most up-to-date status of bridges.

Area of Detail



Note: The bridges displayed on this map represent the results of a combined BTS/FHWA effort to geocode bridges from the FHWA's National Bridge Inventory (NBI). With the exception of Kentucky and Pennsylvania, whose most current data is 2006, all data is from the 2007 NBI. Of the 102 structurally deficient NHS bridges in Wisconsin, 8 could not be geolocated because of insufficient data. Structurally deficient bridges are not necessarily unsafe; all public road bridges receive regular safety inspections. The bridges listed were categorized as structurally deficient at the time the maps were developed.

Bridge Label	Structure ID	Bridge Description	Location Description
1	B03005600000000	USH 53 SB	2.5M S JCT CTH V
2	B09037200000000	CTH X	1.9M E JCT CTH H TO N
3	B03001500000000	USH 53 NB	1.5M N JCT CTH M TO E
4	B09005100000000	USH 53 NB	2.7M N JCT STH 124 TO N
5	B57001900000000	USH 63	5.5M N JCT STH 77 TO E
6	B09001100000000	CTH X	1.1M E JCT STH 124 TO N
7	B71074200000000	USH 10	0.1M E JCT CTH B TO S
8	B26000500000000	USH 51	2.1M N JCT CTH FF
9	B37014200000000	IH USH 51-IH 39 NB	1.6M N JCT CTH DB TO E