

TABLE OF CONTENTS

TABLE OF CONTENTS	1
INTRODUCTION	1
OVERVIEW OF LOWER DUWAMISH WATERWAY-WIDE SOURCE CONTROL ACTIVITIES.....	3
BUSINESS INSPECTIONS	4
<i>Summary for the June 2004-December 2004 Reporting Period</i>	<i>5</i>
SOURCE TRACING.....	7
<i>Key Manhole Samples.....</i>	<i>7</i>
<i>Sediment Trap Samples.....</i>	<i>8</i>
<i>Catch Basin Samples.....</i>	<i>8</i>
PHTHALATE SOURCE STUDY	11
DIAGONAL/DUWAMISH EARLY ACTION SITE.....	14
BUSINESS INSPECTIONS	14
<i>Key Findings.....</i>	<i>14</i>
SOURCE SAMPLING AND IDENTIFICATION.....	15
<i>Source Tracing in the Diagonal Ave S CSO/SD.....</i>	<i>15</i>
<i>In-Line Sediment Traps.....</i>	<i>16</i>
<i>Catch Basin Samples.....</i>	<i>17</i>
SOURCE CONTROL ACTIONS.....	18
<i>Diagonal Ave S CSO/SD Cleaning.....</i>	<i>18</i>
SLIP 4 EARLY ACTION SITE	20
BUSINESS INSPECTIONS	20
SOURCE TRACING.....	21
<i>Sediment Trap Samples.....</i>	<i>21</i>
<i>Catch Basin Samples.....</i>	<i>22</i>
FORMER SLIP 5 AND SLIP 6.....	23
BUSINESS INSPECTIONS	23
SOURCE TRACING.....	23
TERMINAL 117 EARLY ACTION SITE	25
BUSINESS INSPECTIONS	25
SOURCE CONTROL ACTIONS.....	26
<i>Dallas Ave S PCBs Cleanup</i>	<i>26</i>
NEXT STEPS.....	28
BUSINESS INSPECTIONS	28
<i>Diagonal/Duwamish</i>	<i>28</i>
<i>Slip 4</i>	<i>28</i>
<i>Terminal 117.....</i>	<i>28</i>
<i>Other Areas in the LDW.....</i>	<i>28</i>
SOURCE SAMPLING.....	29
<i>Source Tracing.....</i>	<i>29</i>
<i>Phthalate Source Study.....</i>	<i>29</i>
<i>Site-Specific Source Control Actions</i>	<i>30</i>
REFERENCES	31

TABLES

- Table 1. Corrective actions requested by program area.
- Table 2. Most frequent corrective actions.
- Table 3. Surface water quality complaints in the Lower Duwamish Waterway.
- Table 4. Construction projects in the Lower Duwamish Waterway.
- Table 5. Phthalates in key manhole samples.
- Table 6. Onsite catch basin sediment sample results.
- Table 7. Right-of-way catch basin sediment sample results.
- Table 8. Summary of exceedances of sediment management standards for metals in storm drain sediment samples.
- Table 9. Land use in the Diagonal Ave S CSO/SD service area.
- Table 10. Petroleum hydrocarbon results from Diagonal Ave S source tracing samples.
- Table 11. Diagonal Ave S CSO/SD sediment trap results.
- Table 12. Diagonal Ave S CSO/SD inline sediment sample results.
- Table 13. Dallas Ave S and vicinity sample results.

FIGURES

- Figure 1. Areas discharging to the Lower Duwamish Waterway.
- Figure 2. Outfalls in the Lower Duwamish Waterway.
- Figure 3. Businesses inspected June – December, 2004.
- Figure 4. Key manhole sampling locations.
- Figure 5. Catch basin sampling locations.
- Figure 6. Diagonal Ave S CSO/SD basin.
- Figure 7. Land use in Diagonal Ave S CSO/SD basin.
- Figure 8. Businesses inspected in Diagonal Ave S CSO/SD basin.
- Figure 9. Sediment trap locations in Diagonal Ave S CSO/SD basin.
- Figure 10. Catch basin samples collected in the Diagonal Ave S CSO/SD basin.
- Figure 11. Sediment sampling locations in Diagonal Ave S CSO/SD.
- Figure 12. Diagonal Ave S CSO/SD cleaning.
- Figure 13. Businesses inspected in Slip 4 drainage basin.
- Figure 14. Proposed sediment trap locations in Slip 4 storm drains.
- Figure 15. Businesses inspected in areas draining to Slip 5 and Slip 6.
- Figure 16. Sampling locations in vicinity of T117.
- Figure 17. Dallas Ave S sampling locations.

APPENDICES

Appendix A. Business inspection process and field form.

Appendix B. Data base output.

Table B-1. Summary of inspections completed June - December 2004.

Table B-2. Summary reports for all areas inspected.

Table B-3. Corrective actions requested (grouped by regulatory area).

Table B-4. Site history by basin.

Table B-5. Corrective actions requested (grouped by basin and subbasin).

Appendix C. Phthalate air monitoring information.

Appendix D. East Waterway inspection information.