

Hurricane Katrina Damage to OCS Facilities In the Gulf of Mexico

Forty-six mostly low-producing structures were destroyed. Some of these were single-well caissons.

Twenty producing structures had extensive damage.

Four drilling rigs were destroyed. One was a jack-up rig. The other three were platform rigs.

Nine drilling rigs have extensive damage. Four of these are from broken anchor patterns.

Six rigs are adrift, but they have been located and remanned, and they are currently being repowered.

