





ESDA



2:44 pm Brian Bill Roanoke Tornado Statistics: Rated F4 on the Fujita Scale

Path Length: 9.6 miles; Maximum Width: ½ mile



2:41 pm

Wreckage from cars in the parking lot was blown into the building by the tornado.



Houses % mile down the road from the Parsons plant were demolished by the tornado. Steel beams from the plant were found nearby.




Zero fatalities, and only 3 minor injurie



The storm shelters were the only part of the plant to remain intact during the tornado.





Radar images of the tornado as it struck the Roanoke plant; reflectivity (above) and storm relative motion (below).



The Parsons Manufacturing plant west of Roanoke was destroyed by the tornado. There were 150 people in the plant at the time. However, there were NO fatalities and NO injuries at the plant!

The foresight of the plant owner to build storm shelters in the plant, and a working plan to monitor the weather and evacuate if necessary, saved lives.

Today, the plant has been rebuilt, with additional storm shelters in place.



CWG