


# White Chuck River Flood Damage Sites Road 23



**Legend**

- ▲ 2003 Flood Damage Sites
- 2006 Flood Damage Sites
- Road 23
- ⋯ Trails
- Wilderness Boundary
- ▲ Snohomish County Flood Damage
- Paved Road
- Gravel Road, Suitable for Passenger Cars
- Road Not Maintained for Passenger Cars
- Closed Roads
- National Forest Boundary
- Rivers

The product reproduced from information prepared by the USGS, and is not a warranty, guarantee, or endorsement of any kind by the USGS. The USGS does not warrant the accuracy or reliability of the information, and the user assumes all liability for any use of the information. The USGS is not responsible for any errors or omissions in this product. The information is provided for informational purposes only. For more information, contact the USGS at 1225 National Center, Reston, VA 20192-1225. The USGS is an equal opportunity provider.