

Shoreline Erosion



Shoreline Erosion



**Main Pass, Louisiana: Photo A**  
**Examples of Shearing After Hurricanes Katrina and Rita**  
**Fresh and Intermediate Marsh Community Types**

*Delta Pass*

Wrack

Wrack



Photo Date: November 19, 2005

Data Series 281

U.S. Department of the Interior  
U.S. Geological Survey