


Delacroix, Louisiana: Photo I
Examples of Shearing After Hurricanes Katrina and Rita



Belle Chasse

Braithwaite

Surge-removed Floating Aquatic Vegetation

Wrack

Shear Zone

Cane Ridge Slough

Wrack

Shears

Existing Pond with Debris

Wrack

Mud and Wrack

Delacroix Canal

Mud and Wrack

Wrack



Photo Date: November 18, 2005

Data Series 281

U.S. Department of the Interior
U.S. Geological Survey