

Delacroix, Louisiana: Photo L  
Examples of Shearing After Hurricanes Katrina and Rita




Photo Date: November 18, 2005

Data Series 281

U.S. Department of the Interior  
U.S. Geological Survey