


**Delacroix, Louisiana: Photo 0**  
**Examples of Shearing After Hurricanes Katrina and Rita**



*Lake Borgne*

Kenilworth

St. Bernard

Wrack

Compression Features

*Magnolia Canal*

Shear

Mud

*Pipeline Canal*

Shear

NE



Photo Date: December 9, 2005

Data Series 281

U.S. Department of the Interior  
U.S. Geological Survey