


Delacroix, Louisiana: Photo R

Examples of Shearing After Hurricanes Katrina and Rita



Bayou la Croix

River aux Chenes

Shear-expanded Pond

Scoured Marsh

Shear

Remnant Marsh Surface

WNW
↑

Photo Date: December 9, 2005

Data Series 281

U.S. Department of the Interior
U.S. Geological Survey