



## Structurally Deficient Bridges on the National Highway System New York - Congressional District 12



Consult your state DOT for the most up-to-date status of bridges.

Area of Detail



Note: The bridges displayed on this map represent the results of a combined BTS/FHWA effort to geocode bridges from the FHWA's National Bridge Inventory (NBI). With the exception of Kentucky and Pennsylvania, whose most current data is 2006, all data is from the 2007 NBI. Of the 227 structurally deficient NHS bridges in New York, 5 could not be geolocated because of insufficient data. Structurally deficient bridges are not necessarily unsafe; all public road bridges receive regular safety inspections. The bridges listed were categorized as structurally deficient at the time the maps were developed.

<b>Bridge Label</b>	<b>Structure ID</b>	<b>Bridge Description</b>	<b>Location Description</b>
1	2230858	RTE I278	.7 MI SW I278 & BRKLYN BR
2	2230887	RTE I278	0.1 MI E JCT I278 & BK BR
3	2268507	RTE I278	ADJACENT TO YORK STREET
4	1065439	RTE I278	3.3 MI SW JCT I278 + I495