



Structurally Deficient Bridges on the National Highway System New York - Congressional District 15



Consult your state DOT for the most up-to-date status of bridges.



Note: The bridges displayed on this map represent the results of a combined BTS/FHWA effort to geocode bridges from the FHWA's National Bridge Inventory (NBI). With the exception of Kentucky and Pennsylvania, whose most current data is 2006, all data is from the 2007 NBI. Of the 227 structurally deficient NHS bridges in New York, 5 could not be geolocated because of insufficient data. Structurally deficient bridges are not necessarily unsafe; all public road bridges receive regular safety inspections. The bridges listed were categorized as structurally deficient at the time the maps were developed.

Bridge Label	Structure ID	Bridge Description	Location Description
1	2229410	RTE 9A	6.4 MI NE ROUTE 9A+79 ST
2	2233059	RTE 907P	3.6 MI NE JCT FDR & SH 25
3	5521209	TRIBORO-NY TO RI	ON RANDALLS ISLAND