




Structurally Deficient Bridges on the National Highway System Missouri - Congressional District 03



Consult your state DOT for the most up-to-date status of bridges.

Area of Detail



Note: The bridges displayed on this map represent the results of a combined BTS/FHWA effort to geocode bridges from the FHWA's National Bridge Inventory (NBI). With the exception of Kentucky and Pennsylvania, whose most current data is 2006, all data is from the 2007 NBI. Of the 125 structurally deficient NHS bridges in Missouri, 2 could not be geolocated because of insufficient data. Structurally deficient bridges are not necessarily unsafe; all public road bridges receive regular safety inspections. The bridges listed were categorized as structurally deficient at the time the maps were developed.

Bridge Label	Structure ID	Bridge Description	Location Description
1	342	IS 55 N	S 416 T 40 N R 6 E
2	6511	IS 64 E	S 22 T 45 N R 6 E
3	6513	IS 64 E	S 22 T 45 N R 6 E
4	6541	IS 64 E	S 23 T 45 N R 6 E
5	2063	IS 44 W	S 19 T 45 N R 6 E
6	11901	IS 55 N	S 23 T 45 N R 7 E
7	1246	IS 64 W	S 23 T 45 N R 7 E
8	1245	IS 64 E	S 23 T 45 N R 7 E