

**EXPLANATION**



— watershed boundary

Photos taken October 30, 1991  
Photos derived from Digital Orthophoto  
Quadrangles, U.S. Geological Survey,  
Reston, VA.

Universal Transverse Mercator projection,  
Zone 10

This map is a plot derived from data  
contained in the digital database  
Open-File Report 00-127, "Possible Costs  
Associated with Investigating and Mitigating  
Some Geologic Hazards in Rural Parts of San  
Mateo County, California." A PostScript  
image of this map is included in the  
Open-File Report, but the Open-File  
Report does not contain a paper copy of  
this map. The Open-File Report consists of  
the digital data and a pamphlet explaining  
the database and indicating how to obtain  
the data from which this map was prepared  
as well as the PostScript image of the map.

This report is preliminary and has not  
been reviewed for conformity with U.S.  
Geological Survey editorial standards  
or with the North American Geographic  
Code. Any use of trade product, or  
firm name is for descriptive purposes  
only and does not imply endorsement by  
the U.S. Government.  
This database, identified as "Possible Costs  
Associated with Investigating and Mitigating  
Some Geologic Hazards in Rural Parts of San  
Mateo County, California" has been approved  
for release and publication by the Director  
of the USGS. Although the database has  
been subjected to rigorous review and is  
substantially complete, the USGS reserves  
the right to revise the data pursuant to  
further analysis and review. Furthermore,  
it is released on condition that neither  
the USGS nor the United States Government  
may be held liable for any damages  
resulting from its authorized or  
unauthorized use.



**POSSIBLE COSTS ASSOCIATED WITH INVESTIGATING AND MITIGATING SOME GEOLOGIC  
HAZARDS IN RURAL PARTS OF SAN MATEO COUNTY, CALIFORNIA**

**By Earl E. Brabb, Sebastian Roberts, William R. Cotton,  
Alan L. Kropp, Robert H. Wright, and Erik N. Zinn  
2000**