


USG HUMANITARIAN ASSISTANCE TO HAITI



2008 HURRICANES IN THE CARIBBEAN





The boundaries and names used on this map do not imply official endorsement or acceptance by the U.S. Government.

ROUTE STATUS

- Full ▲ Partial
- Heavy Duty Vehicle Only
- Truck + Trailer > 20 MT
- Heavy Truck < 20 MT
- Light Truck < 10 MT
- 4WD < 3.5 MT
- Non-motorized: Motorbike
- Primary Road
- Secondary Road
- Tertiary Road
- Trail


SOURCE: WFP Logistics Cluster, UNJLC
10/31/08



The boundaries and names used on this map do not imply official endorsement or acceptance by the U.S. Government.

Gonaives, Haiti
September 9, 2008

Post Hurricane Hanna/Ike Damage Overview



The effects of extreme rainfall related to Hurricanes Hanna and Ike cause flooding, destruction and loss of life in Gonaives and other regions of Haiti. This image clearly shows the sediment loaded runoff still coloring the water bodies, including the Gulf of Gonaives (1) and the Savane Jonc (2). The La Quinte River has deposited significant quantities of sediment outside of its channel (3) and changed its route to the sea, cutting directly through the city of Gonaives (4). The Savane Jonc has swollen and submerged the causeway linking to points south (5). Engineers are working to increase the capacity of a detour to handle the increased traffic loads (6).