1/2-MILE RIVER REMOVALACTION MONTHLY PROGRESS REPORT AUGUST 2002 FIGURE 1: PHOTO DOCUMENTATION

PHOTO NO. 1

LOCATION: Downstream Cell J-3

DESCRIPTION: Waterloo wall/riverbed

restoration.

DATE: August 9, 2002.



LOCATION: Middle Cell J-3

DESCRIPTION: River restoration

(geotextile, peat, isolation layer,

geogrid, armor cap).

DATE: August 13, 2002.







PHOTO NO. 3

LOCATION: Upstream Cell J-3.

DESCRIPTION: Restored riverbed and

Waterloo wall.

DATE: August 20, 2002