

Saugatuck, Michigan

DANGER
**SEVERE
EROSION**
**ENTER AT
OWN RISK**



Shoreline erosion Ogden Dunes Indiana





Shoreline erosion
Lake Michigan Indiana



Storm erosion
White Gravel Bay Ontario



Erosion along developed shoreline
Lake Michigan Indiana



Lake Michigan Indiana



Erosion along sand banks



Willoughby, Ohio



Erosion and damage to marsh
Toledo, Ohio



Slump erosion
Nemadji River Wisconsin



Cut bank erosion
Nemadji River



Lake St. Clair Michigan



Lakefront Drive, 1973



Red clay erosion - Lake Superior