

Legend

Site Limits Staging Area Emergent Marsh

In-stream Woody Material

Riparian Forest Overhang Restoration Planting Bare

🔀 Rip Rap Ruderal Image Source AirPhotoUSA May 2006. Current site conditions may vary from those shown on aerial photo.

Sacramento River RM 16.8L

