

# U.S. Senate

## Desk Description and Condition Report

Desk No : **66.00096.000**

Paper Label No.(on shelf bottom): 60 (partially torn)      Painted No. (on bottom): N/A

Other identifying labels or marks (specify location): Stretcher: 59, 60, XCVI / Top: 59, 97 /  
 Drawer Bottom: outside - "No. 24," remnant paper label with script / Drawer Back: 59 (pencil), 7 $\frac{1}{2}$  (ink) /  
 Inside Case Back: V (carved)

### Description of Desk

Dimensions (in inches)

	Overall	Orig. Desk*	Case	Shelf
Height	35 3/8	32 1/4		
Width (front)	27 7/8	26 1/4	25 9/16	
Width (rear)	24 5/8	22 3/4	22 1/8	
Depth	20	20 3/8	19 1/16	9 3/8

\* Note: Dimensions do not include "booster" blocks added to feet or writing top.

### Woods

Primary:

Mahogany

Mahogany veneer

Rosewood veneer

Other Wood (specify): \_\_\_\_\_

\_\_\_\_\_

Character of case mahogany:

Plain

Ribbon

Mottled

Crotch

Other

Secondary:

Element	Pine	Ash	Poplar	Mahog	Other
Drawer Sides				✓	
Drawer Bottom			✓		
Drawer Back			✓		
Case Interior	✓	✓			
Drawer Front	✓				



### Condition of Desk

Structure

Previous breaks in structural elements: Yes   
 (shown on schematic)  
 No

Current split or broken elements: Yes   
 (shown on schematic)  
 No

Other loose or damaged joinery: Yes   
 (describe in narrative)  
 No

Damage to drawer front: Extreme   
 Moderate   
 Minor

Drawer lock: relocated on face Yes

Drawer lock: resized on inside Yes

Cockbead on drawer front: Damaged   
 (show on schematic)  
 Missing   
 Loose   
 Replacements

Replaced drawer-side runners: Yes   
 No

Replaced case-side runners: Yes   
 No

Drawer bottom pieced-out at back edge: Yes   
 No

Wear on Feet	Extreme	Moderate	Minor
Front	✓		
Rear			✓

Number of loose spindles: No: 1

Number of replaced spindles: (show on schematic) No: 8

Replaced veneers and cross-banding: Yes   
 (show on schematic)  
 No

Missing veneers and cross-banding: Yes   
 (show on schematic)  
 No

Delaminated/loose veneers & cross-banding: Yes   
 (show on schematic)  
 No

Shelf supports: Original/old   
 New/recent   
 Missing

Spindle support board in case: Yes   
 No

**Finish**

Age	Excellent	Good	Fair	Poor
New			✓	
Old				
Unk.				

Note: Describe finish problems in narrative.

**Hardware/Attachments**

Item	Mismatch	Missing	Damaged
Knob (L)	✓		
Knob (R)			

Toe cap size:	Right toe: 5
	Left toe: 5