U.S. Senate Desk Description and Condition Report

Desk No: 66.00000.056

Paper Label No.(on shelf bottom): 41 Painted No. (on bottom): N/A

Other identifying labels or marks (specify location): Stretcher: 41, 41, LVI / Top: 41 (stamp), 51 (blue crayon) / Drawer Bottom: outside - 41 (pencil), 2 (pencil), paper label remnant / Drawer Back: 2 (pencil) / Drawer Blade: 41 (pencil) / Inkwell: 56 (pencil), pencilled name

Description of Desk

Dimensions (in inches)

	Overall	Orig. Desk*	Case	Shelf
Height	34 13/16	32 1/2		
Width (front)	28 1/8	26 1/2	25 3/4	
Width (rear)	26 3/8	24 3/4	24	1
Depth	20 1/4	20 1/16	19 1/4	9

^{*} Note: Dimensions do not include "booster" blocks added to feet or writing top.

Woods

Primary:	Mahogany ■	Character of case mahogany:	Plain
	Mahogany veneer ■ Rosewood veneer □		Ribbon 🗆
Other Wood (specify):		Mottled ■	
			Crotch
	4		Other 🗆

Secondary:

Element	Pine	Ash	Poplar	Mahog	Other
Drawer Sides				1	
Drawer Bottom			1		
Drawer Back			1		
Case Interior	1	1			
Drawer Front	1				

	tion and Condition	n Report	t: Desk No: 0	56				Page 2
Construction	n Details							
	Wood Type				rosewood crossband	other crossband	d cross	
mahog, veneer						/	,	
	solid mahogar	ny						
other:								
oot construc	tion:		1-part ■ 2-part □ 5-part □	Cock	sbead width on I	pottom of	Na	it: irrow 🏻 width I
	(Other:		Oper	ning in original t	op for inkv	well:	Yes
Double bead	on edge of leg:	194100	1					No C
Shape of cros	ss-stretcher edge	es:	ounded □	1000	t distance of sin	gle bead o	Applied on desk ba	
			angular _	pane	31.		Sid	e: 1 1/4
	Think	Thin	Other	Top: 7/8				
Spindle type:	Thick	5.17,000	Otner	- 1			3)	op: 7/8"
Spindle type:	Thick	10	Other					op: 7/8" om: 7/8"
Number	ver drawer blade	10						om: 7/8"
Number		10 e to case		1	. of Glue Blocks	Case		shelf
Number		10 e to case single o	sides:	Or	riginal/Old	Case	Botto Stretch'r	om: 7/8"
Number		10 to case single of 2 do	sides:	Or	iginal/Old ew/Recent	Case	Botto	sm: 7/8"
Number		10 e to case single o 2 de 3 de	sides: dovetail □ ovetails ■	Or	riginal/Old	Case	Botto Stretch'r	shelf
Number Joinery of lov		10 e to case single o 2 de 3 de	sides: dovetail □ ovetails ■ ovetails □	Or N	iginal/Old ew/Recent		Stretch'r	Shelf 2

Left: 9/16"

0-		2	
Pa	ae	31	
100	0-	_	

Condition of Desk

Structure

Previous breaks in structural ele (shown on schematic)	ements: Yes	Drawer bottom p	ieced-out a	it back edge	: Yes ■
	No □				No 🗆
Current split or broken elements	Yes ■	Wear on Feet	Extreme	Moderate	Minor
(shown on schematic)	No 🗆	Front		/	
		Rear			1
Other loose or damaged joinery (describe in narrative)	Yes □	Number of loose	enindlee:		
(describe in narrative)	No ■	Number of loose	spiridies.		No: 0
Damage to drawer front:	Extreme □ Moderate □	Number of repla (show on scher	and the same of the same of	es:	No: 0
	Minor I	Replaced venee	rs and cros	ss-banding:	Yes
Drawer lock: relocated on face	Yes ■	(show on scher	matic)	W 10 10 10 10 10 10 10 10 10 10 10 10 10	No 🗆
Drawer lock: resized on inside	Yes ■	Missing veneers	and cross-	-banding:	Yes
Cockbead on drawer front:	Damaged ■	(show on sche	matic)		No □
(show on schematic)	Missing □	Delaminated/loose veneers &			Yes I
	Loose 🗆	cross-banding: (show on sche	matic)	Viv.	No 🗆
	Replacements	Shelf supports:		Origi	nal/old
Replaced drawer-side runners:	Yes □			New	/recent [
	No ■			٨	Aissing [
Replaced case-side runners:	Yes ■	Spindle support	board in ca	ase:	Yes 🗆
	No □				No ■

Finish

Age	Excellent	Good	Fair	Poor
New			1	
Old				
Unk.				

Note: Describe finish problems in narrative.

Hardware/Attachments

Item	Mismatch	Missing	Damaged
Knob (L)			
Knob (R)			

Toe cap size:	Right toe:	15	
	Left toe:	15	