### U.S. Senate Desk Description and Condition Report

Desk No: 66.00068.000

Paper Label No.(on shelf bottom): 76 Painted No. (on bottom): N/A

Other identifying labels or marks (specify location): Stretcher: 76, 78, LXVIII / Top: (stamped) 76, (pencil) 69 / Drawer Back: (pencil) 76 / Drawer bottom inside: (pencil) 76, 78 / Inside Case Back: (pencil) 59, VIII, "clay", "alla" / Inkwell: (pencil) 68, (tape) "Edmonson"

# **Description of Desk**

Dimensions (in inches)

	Overall	Orig. Desk*	Case	Shelf
Height	35 3/8	32 1/2		
Width (front)	29	26 3/8	25 1/2	
Width (rear)	27 1/2	25	24 1/8	
Depth	20 1/4	20 1/16	19 1/8	9 5/8

<sup>\*</sup> Note: Dimensions do not include "booster" blocks added to feet or writing top.

### Woods

Primary:	Mahogany ■	Character of case mahogany:	Plain
	Mahogany veneer ■		Ribbon
	Rosewood veneer ■		Mottled []
Other Wo	ood (specify):		Crotch [
-			Other [

#### Secondary:

Element	Pine	Ash	Poplar	Mahog	Other
Drawer Sides				1	
Drawer Bottom			1		
Drawer Back			1		
Case Interior		1			
Drawer Front	1				

Construction	n Details							
- A - A - A - A - A - A - A - A - A - A	Wood Type				rosewood crossband	other crossbane	d cross	
	mahog. venee	r			1			
	solid mahogar	ny						
	other:							
Double bead o	on edge of leg:		d: Thick □ Thin ■ s: 1 3/16 "		ening in origina undels:		vell: ce ("yo-yo" Applied	
Shape of cros	s-stretcher edge	F	Rounded □ stangular ■	Inse	et distance of s nel;	ingle bead o		ck le: 1 1/4"
Spindle type:	Thick	Thin	Other				Т	op: 7/8"
Number	2	8			-		Botto	om: 7/8"
Joinery of low	er drawer blade	single	dovetail 🗆	1,500	o. of Glue locks	Case	Stretch'r	Shelf
			dovetails  dovetails	C	Original/Old			
		3	lap joint	1	New/Recent	4		2

Joinery of lower drawer blad	le to case sides:
	single dovetail $\square$
	2 dovetails
	3 dovetails
	lap joint □
other:	
Shelf molding applied:	Yes 🗆

- 10 10	
Yes 🗆	
No 🔳	

No. of Glue Blocks	Case	Stretch'r	Shelf
Original/Old			
New/Recent	4		2
Missing			

nterior	case-side	flush	with	corner	block?	Yes	
						No	

Width of drawer-opening offset	Right : 5/8"
ANALY SERVICE	Left : 5/8"

# **Condition of Desk**

### Structure

Previous breaks in structural elem (shown on schematic)	nents: Yes ■	Drawer bottom p	ieced-out a	t back edge	Yes
	No 🗆				No 🗆
Current split or broken elements:	Yes □	Wear on Feet	Extreme	Moderate	Minor
(shown on schematic)	No ■	Front	1		
		Rear			1
Other loose or damaged joinery: (describe in narrative)	Yes □	Number of loose	spindles:		No: 0
	No ■	ii.			No: 0
Damage to drawer front:	Extreme □ Moderate ■	Number of replace (show on schero		s:	No: 2
	Minor [	Replaced venee		s-banding:	Yes ■
Drawer lock: relocated on face	Yes ■	(Show on Solice	ridicy		No □
Drawer lock: resized on inside	Yes ■	Missing veneers (show on scher		banding:	Yes ■
Cockbead on drawer front: (show on schematic)	Damaged				No □
	Missing	Delaminated/loo cross-banding:	se veneers	&	Yes ■
	Loose 🗆	(show on scher	matic)		No □
R	eplacements	Shelf supports:		Origi	nal/old
Replaced drawer-side runners:	Yes ■			New	/recent ■
	No □			A	Aissing 🗆
Replaced case-side runners:	Yes ■	Spindle support	board in ca	ise:	Yes 🗆
4551	No □				No ■

# Finish

Age	Excellent	Good	Fair	Poor
New				
Old				
Unk.			1	

Note: Describe finish problems in narrative.

## Hardware/Attachments

Item	Mismatch	Missing	Damaged
Knob (L)	1		1
Knob (R)			1

Toe cap size:	Right toe:	2	
	Left toe:	2	